

MONTANA
BRIDGE
CONDITION REPORT

COMPILED BY THE
MONTANA HIGHWAY COMMISSION
PLANNING SURVEY

IN COOPERATION WITH
U. S. DEPARTMENT OF COMMERCE
BUREAU OF PUBLIC ROADS

MARCH 1, 1962

Montana State Library



3 0864 1006 4672 1

F O R E W O R D

This report covers major structures on the Federal Aid Interstate, Primary and Secondary Systems and includes those county built structures now in use on the approved routes. Interstate structures are presently listed under equivalent Primary Routes.

This is a biennial report; the bridges were inspected during the period of November 16, 1961 through February 16, 1962.

The bridges are listed in order of sequence on the Federal Aid Route on which located and the Federal Aid Routes are in numerical order.

The Primary bridge numbers consist of three (3) groups of figures as follows:

000-0000-0000

The first digit on the left indicates whether the structure is on U.S. or State numbered highway (1 for U.S., 2 for State). Second and third digits indicate the county number. See list of county names and numbers on the following sheet.

The first three digits of the second group indicate U.S. or State highway number. The fourth digit of the second group indicates whether the section is on the main route or whether it is on a parallel loop, or alternate. The code is 0-Main Route; 1-North; 2-East; 3-South; 4-West; 5-Alternate. Example: 0101 indicates U.S. 10 North; 0105 indicates U.S. 10 Alternate.

The last four digits are the distance of the structure in miles and tenths from the county boundary. If a route starts within a county, these figures indicate the distance of the structure from the beginning of the route. On Interstate projects, letters following the mileage figures indicate the following: A-structure is an access or approach road. F-structure is on frontage road. P-structure is parallel to preceding structure.

Secondary bridge numbers consist of three (3) groups of figures as follows:

000-00-000

First group is secondary route number. Second group indicates county number. Third group indicates miles and tenths from beginning of route. See list of county names and numbers on the following sheet.



Digitized by the Internet Archive
in 2014

<https://archive.org/details/bridgecondition1962mont>

C O U N T Y N A M E S A N D N U M B E R S

<u>COUNTY NAME</u>	<u>COUNTY NUMBER</u>	<u>COUNTY NAME</u>	<u>COUNTY NUMBER</u>
Beaverhead	1	Madison	29
Big Horn	2	Meagher	30
Blaine	3	Mineral	31
Broadwater	4	Missoula	32
Carbon	5	Musselshell	33
Carter	6	Park	34
Cascade	7	Petroleum	35
Chouteau	8	Phillips	36
Custer	9	Pondera	37
Daniels	10	Powder River	38
Dawson	11	Powell	39
Deer Lodge	12	Prairie	40
Fallon	13	Ravalli	41
Fergus	14	Richland	42
Flathead	15	Roosevelt	43
Gallatin	16	Rosebud	44
Garfield	17	Sanders	45
Glacier	18	Sheridan	46
Golden Valley	19	Silver Bow	47
Granite	20	Stillwater	48
Hill	21	Sweet Grass	49
Jefferson	22	Teton	50
Judith Basin	23	Toole	51
Lake	24	Treasure	52
Lewis & Clark	25	Valley	53
Liberty	26	Wheatland	54
Lincoln	27	Wibaux	55
McCone	28	Yellowstone	56

FEDERAL AID PRIMARY ROUTE 1

Field Maintenance Division No. 102

Lincoln County

Br. No. 127-0020-0063 Yaak River

210' Steel Girder

Paint Condition: Good

General Condition: Good

Remarks: Paint on girders needs a spot coat. Copper water stops at both end bents have pulled apart. Rockers covered with dirt. The bearing seat is loaded. Concrete beam seat end guards at both end bents are cracked or broken.

Br. No. 127-0020-0116 Kootenai River & G. N. Ry. 938.5' Steel Truss

Paint Condition: Good

General Condition: Good

Remarks: Under side looks good. Walkways are snow covered, so could not check the extent of deterioration previously reported.

Br. No. 127-0020-0146 Callahan Creek

186.5' Steel Pony Truss

Paint Condition: Good

General Condition: Good

Remarks: Bronze plaque is gone from southwest end post. Paint generally good. There are a number of rust spots and flaked areas. North end of pier caps 2 and 3 are deteriorating, especially pier 3. Dent in left truss batter column.

Br. No. 127-0020-0153 Lake Creek

175' Continuous Steel Beam

Paint Condition: Fair

General Condition: Good

Remarks: Top of some rail posts spalling. Excessive deterioration of many rail units. Some disintegration of south deck edge surface. Drift collected at Pier 2.

Br. No. 127-0020-0278 Cedar Creek

39' Concrete T Beam

General Condition: Good

Remarks: Rail and curb deteriorating and re-steel exposed in some rail units.

Br. No. 127-0020-0312 Parmenter Creek

21.5' Concrete Slab

General Condition: Good

Remarks: Rails deteriorating and re-steel exposed in some units.

Br. No. 127-0020-0321 Flower Creek

21.5' Concrete Slab

General Condition: Good

Remarks: Concrete in rail and posts is deteriorating. There is one rail unit with only the re-steel remaining.

Br. No. 127-0020-0353 Granite Creek

178.8' Steel Beam

Paint Condition: Good on Rail - Fair on Steel

General Condition: Good

Remarks: Concrete surface of end of pier copings and tops of end bent retaining walls are deteriorating. A few rail posts are split and rails scuffed.

Br. No. 127-0020-0412 Getner Creek

38' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Remarks: Paint good except on two posts and two rail panels. Oiled surface on deck in good condition.

Br. No. 127-0020-0448 Libby Creek

140' Steel Truss

Paint Condition: Good

General Condition: Good

Remarks: Paint good except for scattered rust spots and some scaling. Portals and cross frames have been traffic scraped. Concrete deck surface good.

Br. No. 127-0020-0461 Swamp Creek 30' Treated Timber and Concrete
 General Condition: Good
 Remarks: Some light spalling of curb and rail. Underside deck and stringers look good. Oiled surface on deck.

Br. No. 127-0020-0467 Swamp Creek 30' Treated Timber and Concrete
 General Condition: Good
 Remarks: Underside of deck and stringers look good. Deck oil surfaced.

Br. No. 127-0020-0483 Swamp Creek 45' Treated Timber and Concrete
 General Condition: Good
 Remarks: Underside of deck and stringers look good. End posts and curb is deteriorating. Deck oil surfaced.

Br. No. 127-0020-0567 Miller Creek 23' Treated Timber and Concrete
 General Condition: Good
 Remarks: North side exterior stringer has a center split - bottom 4" split and shattered from bearing out to center - loosely bound with three 1/8" pieces of strap iron. Need improved repair. Ice within 2" of stringer base. Curbs snow covered. Deck oil surfaced.

Br. No. 127-0020-0572 Fisher River 180' Thru Steel Truss
 Paint Condition: Good to Fair General Condition: Good
 Remarks: Steel needs spot painting. Cross frames lightly damaged by high truck loads. Where exposed, deck surface shows some wear, but is in good condition. Underside of deck is good. No vertical clearance signs.

Br. No. 127-0020-0699 Private Road - J. Neils Lumber Co. 75' Treated Timber Trestle
 Paint Condition: Good General Condition: Good
 Remarks: Deck snow covered.

Br. No. 127-0020-0712 Fisher River 38' Treated Timber Trestle
 Paint Condition: Good
 Remarks: Paint generally good. Poor on a few panels. Deck oil surfaced. Underside looks good.

Field Maintenance Division No. 102 Flathead County
 Br. No. 115-0020-0001 Lang Creek 38' Treated Timber Trestle
 Paint Condition: Good General Condition: Good
 Remarks: Left rail post Bent 3 split. Underside of deck and stringers look good. Deck oil surfaced.

Br. No. 115-0020-0250 Ashley Creek 75' Treated Timber Trestle
 Paint Condition: Poor General Condition: Good
 Remarks: South side of Bent 2 shifting out of line. Underside deck and stringers look good. Deck oil surfaced.

Br. No. 115-0020-0335 Ashley Creek 41' Concrete T Beam
 General Condition: Good
 Remarks: Underside looks good. Deck oil surfaced.

Br. No. 115-0020-0343 Ashley Creek 41' Concrete T Beam
 General Condition: Good
 Remarks: Some deterioration of right rail and end posts. Underside of structure looks good. Deck oil surfaced.

Br. No. 115-0020-0413	G. N. Railroad	Underpass
Paint Condition: Good		
Remarks: Drain pipes from track deck battered out of use on west side, and disconnected from down spout on east side. Not of much use during winter. Vertical clearance painted on girders - 14' 6" - correct 14' 3". Paint on bottom and edges of flange scraped by high loads.		
Br. No. 115-0020-0420	Stillwater River	230' Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: Considerable wear and spalling of deck surface. Seal coat worn off tire tracks in both lanes.		
Br. No. 115-0020-0432	Spring Creek	150' Treated Timber Trestle
Paint Condition: Fair to Poor		General Condition: Good
Br. No. 115-0020-0434	Drainage	175' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 115-0020-0438	Drainage	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 115-0020-0441	Drainage	125' Treated Timber Trestle
Paint Condition: Fair to Good		General Condition: Good
Remarks: Oil mat on deck is in good condition. One split sway brace.		
Br. No. 115-0020-0442	Drainage	125' Treated Timber Trestle
Paint Condition: Fair to Good		General Condition: Good
Remarks: Cracked stringer, span 1, previously reported, has been repaired with steel base plates and bolts up through the deck.		
Br. No. 115-0020-0444	Flathead River	898' Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: On sections of top of lower chord of truss, aluminum coat of paint has worn off exposing the prime coat. Portions of rail face scuffed by traffic. Touching up of these surfaces needed. Bent 1 fixed shoe pin nuts are missing.		
Br. No. 115-0020-0618	South Fork Flathead River	590' Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 115-0020-0641	Martin Creek	21.5' Concrete Slab
General Condition: Good		
Br. No. 115-0020-0807	Deer Lick Creek	115' Treated Timber Trestle
General Condition: Good		
Br. No. 115-0020-0843	G. N. Railway	362.7' Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 115-0020-0872	G. N. Railway	209' Concrete T Beam
Paint Condition: Good		General Condition: Good
Br. No. 115-0020-0929	Tunnel Creek	32' Concrete T Beam
General Condition: Good		

Br. No. 115-0020-0940	G. N. Railway	Underpass
General Condition: Good		
Remarks: No clearance signs on structure.		
Br. No. 115-0020-0959	Paola Creek	24' Steel I Beam
Paint Condition: Good		General Condition: Good
Br. No. 115-0020-0988	Dickey Creek	34' Concrete T Beam
General Condition: Good		
Br. No. 115-0020-1007	Middle Fork Flathead River	172' Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: Northwest concrete rail section, top deteriorating and re-steel exposed. One pier top and face spalling around bearing plate. Bridge clearance signs 15' 3" - checked clearance 15' 1".		
Br. No. 115-0020-1026	Snowslide Gulch	144' Steel Pony Truss
Paint Condition: Good		General Condition: Good
Remarks: Rail and curb end and end of caps, south and east side deteriorating due to weathering.		
Br. No. 115-0020-1043	G. N. Railway	Underpass
Paint Condition: Good		General Condition: Good
Br. No. 115-0020-1049	Bear Creek #3	110' Concrete T Beam
General Condition: Good		
Br. No. 115-0020-1061	Bear Creek #2	110' Concrete T Beam
General Condition: Good		
Br. No. 115-0020-1065	Bear Creek #1	110' Concrete T Beam
General Condition: Good		
Br. No. 115-0020-1097	Devil Creek	32' Concrete T Beam
General Condition: Good		
Remarks: Some disintegration of rail ends on top, at center joint between sections.		
Br. No. 115-0020-1116	Bear Creek	70' Concrete T Beam
General Condition: Good		
Field Maintenance Division No. 302		Glacier County
Br. No. 118-0020-0112	Midvale Creek	142' Concrete T Beam
General Condition: Good		
Remarks: One end of a north side rail section and also the end post have been damaged and two rebars are exposed in the rail and one in the post.		
Br. No. 118-0020-0122	Two Medicine Creek	760' Continuous Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: Some disintegration of concrete near shoes of three piers due to weather action.		

Br. No. 118-0020-0225	G. N. Railway	127.3' Concrete T Beam
General Condition: Good		
Remarks: Due to G. N. Railway snow shed and snow coverage, substructure could not be inspected. Deck and rails in good condition.		
Br. No. 118-0020-0252	G. N. Railway	144' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: Structural Steel reinforcement of Pier 3.		
Br. No. 118-0020-0310	Willow Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 118-0020-0316	Willow Creek Overflow	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 118-0020-0543	Cut Bank Creek	314' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 302		Toole County
Br. No. 151-0020-0150	I-15, U.S. 91 (FAP Rte. 21)	Underpass
Paint Condition: Good		General Condition: Good
Br. No. 151-0020-0151	I-15, U.S. 91 (FAP Rte 21)	Underpass
Paint Condition: Good		General Condition: Good
Br. No. 151-0020-0370	West Fork Willow Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 151-0020-0397	North Fork Willow Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 302		Liberty County
Br. No. 126-0020-0154	Cottonwood Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 302		Hill County
Br. No. 121-0020-0212	Sage Creek	120' Concrete T Beam
Paint Condition: Good		General Condition: Good
Br. No. 121-0020-0435	Big Sandy Creek	146' Continuous Concrete T Beam
Paint Condition: Good		General Condition: Good
Br. No. 121-0020-0453	G. N. Railway	312' Steel Beam
Paint Condition: Good		General Condition: Good
Remarks: Rockers of Bent 2 from the east are considerably to the expansion side. End bents look good.		
Br. No. 121-0020-0563	Box Elder Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Signs and drain screens have been removed.		
Br. No. 121-0020-0577	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: A few loose bolts that hold rail posts. Curb timbers are battered up.		

Field Maintenance Division No. 302		Blaine County
Br. No. 103-0020-0018	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Normal age shows on rail posts.		
Br. No. 103-0020-0050	Clear Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Left rail shows a little settlement at Pier 2. Normal age shows on rail and curb.		
Br. No. 103-0020-0061	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: One rail wing section gone.		
Br. No. 103-0020-0067	Milk River	241.5' Steel Pony Truss
Paint Condition: Good		General Condition: Good
Remarks: Good size chip off of right corner post Bent 1. Some spalling showing on down stream side of pier.		
Br. No. 103-0020-0108	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 103-0020-0113	Red Rock Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Curb timbers are battered up. Backing plank shows fill pressure on them.		
Br. No. 103-0020-0117	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Third stringer in from right at Bent 1 has small crack that looks like it might get worse.		
Br. No. 103-0020-0131	Red Rock Creek Overflow	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Some riprap gone from east berm.		
Br. No. 103-0020-0134	Drainage	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 103-0020-0136	Lodge Creek	94' Concrete T Beam
Paint Condition: No paint required		General Condition: Good
Remarks: A few spalls near bearing haunches.		
Br. No. 103-0020-0143	Drainage	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Stringers, piles, caps - Okay.		
Br. No. 103-0020-0146	Drainage	152' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Some riprap gone from both berms. Curb timber shows normal age and wear from traffic.		
Br. No. 103-0020-0158	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 103-0020-0160	Drainage	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 103-0020-0169	Drainage	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 103-0020-0174	Drainage	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 103-0020-0189	Battle Creek	196' Through Steel Truss
Paint Condition: Fair		General Condition: Good
Remarks: Some spalling at beam seat Bent 1. Rockers tipped to expansion position. A few members bent from being hit.		
Br. No. 103-0020-0210	Drainage	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 103-0020-0219	Drainage	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 103-0020-0228	Fifteen-Mile Creek	108' Continuous Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: Slight erosion at water line of pier.		
Br. No. 103-0020-0334	Drainage	25' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Could not get underneath-ice within 6" of stringers.		
Br. No. 103-0020-0356	Drainage(Irrigation Canal)	25' Untreated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Backing plank and piling are quite rotten.		
Br. No. 103-0020-0378	Milk River	243.3' Through Steel Truss
Paint Condition: Poor		General Condition: Good
Remarks: East end berm washed out on right side. Rockers, Pier 3, tipped to expansion position. Surface wear showing on deck slab.		
Br. No. 103-0020-0380	Main Canal Fort Belknap	95' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: One stringer in last span has fairly bad break.		
Br. No. 103-0020-0517	White Bear Creek	119' Concrete Slab
Paint Condition: None required		General Condition: Good
Remarks: Two rail posts broken at bottom and pushed a little out of line.		
Field Maintenance Division No. 402		Phillips County
Br. No. 136-0020-0007	Peoples Creek Overflow	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Fourth stringer in from right at span is cracked but not too badly yet.		
Br. No. 136-0020-0008	Peoples Creek Overflow	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Br. No. 136-0020-0011	Peoples Creek	125' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Rail shows sag at Bent 3. Okay underneath.		
Br. No. 136-0020-0050	Dodson Creek Canal	63' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 136-0020-0054	Milk River	240' Steel Truss
Paint Condition: Fair		General Condition: Good
Remarks: Moderate spalling at tops of piers. Rockers in expansion position.		
Br. No. 136-0020-0071	Dodson Creek	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 136-0020-0077	U.S. R.S. Canal	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Quite a few nuts off of curb timber.		
Br. No. 136-0020-0078	Dodson Creek Overflow	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 136-0020-0097	Dodson Creek Overflow	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 136-0020-0113	Spring Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 136-0020-0120	G. N. Railway	186' Concrete T Beam
Paint Condition: None needed		General Condition: Good
Remarks: Fill settling under B-5.		
Br. No. 136-0020-0128	Drainage	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Rail has been pushed out of line on east end for about three posts.		
Br. No. 136-0020-0134	Johnson Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: One corner reflectorized sign damaged.		
Br. No. 136-0020-0165	Nine-Mile Creek	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 136-0020-0174	Bailey Creek	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: One corner post is broken off at the bottom.		
Br. No. 136-0020-0191	O'Neil Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: One corner post has been hit and broken, also the reflector sign.		
Br. No. 136-0020-0213	Exeter Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: A few loose nuts in rail posts.		

Br. No. 136-0020-0256	Milk River	240' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Fill sagging away around northwest corner post. Rockers west end bent too much in expansion position.		
Br. No. 136-0020-0302	Nelson Ditch	95' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 136-0020-0333	Spillway U.S. Canal	29' Concrete T Beam
Paint Condition: None required		General Condition: Good
Remarks: Structurally all right. Looks like a retaining wall for the south bent is missing. Rail is chipped in places.		
Br. No. 136-0020-0432	Beaver Creek Overflow	247' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Third and fourth span from west hard to get to. Didn't see them too well.		
Br. No. 136-0020-0440	Dry Wash	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 136-0020-0444	Beaver Creek	216.7' Steel Pony Truss
Paint Condition: Good on steel, fair on wood		General Condition: Good
Br. No. 136-0020-0532	Beaver Creek	149.5 Continuous Steel Beam
Paint Condition: Good		General Condition: Good
Br. No. 136-0020-0547	Beaver Creek Overflow	114' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 136-0020-0552	Beaver Creek Overflow	190' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 136-0020-0556	Beaver Creek Overflow	133' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 402		Valley County
Br. No. 153-0020-0005	U.S.R.S. Canal	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0053	U.S.R.S. Canal	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0073	Beaver Creek	236.7' Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: Vertical clearances 11' and 15.3'. Posted clearance sign reads 15'2". Broken stringer fifth from west-south end.		
Br. No. 153-0020-0100	Beaver Coulee	95' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 153-0020-0122	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 153-0020-0136	Milk River	333.8' Steel Truss
Paint Condition: Fair		General Condition: Good
Remarks: End Bent south has two rotten piling and cap is rotting. End Bent has been sinking. Rockers on steel span are rocked to extreme expansion at +30° F. End Bent north has sunk. Portals and rail have been hit with traffic.		
Br. No. 153-0020-0138	Milk River Overflow	133' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Second stringer in from north side of first span from west has a crack developing.		
Br. No. 153-0020-0145	Milk River Overflow	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 153-0020-0146	Canal	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0166	Canal	95' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 153-0020-0212	Bear Creek Overflow	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0213	Bear Creek	114' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0259	Unger Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0270	Lime Creek(Signed Buggy Creek)	152' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0323	Chapman Coulee	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0332	Mooney Coulee	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0365	Richardson Coulee	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0370	O'Neil Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 153-0020-0388	Cherry Creek Overflow	114' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Badly broken stringer - first span.		
Br. No. 153-0020-0392	Cherry Creek	114' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Badly broken stringer - fourth span - fourth stringer from right.		
Br. No. 153-0020-0451	Goudge Coulee	38' Treated Timber Trestle
Remarks: Under contract. Let 5-24-61.		

Br. No. 153-0020-0474 Paint Condition: Good	Whatley Coulee	50' Treated Timber Trestle General Condition: Good
Br. No. 153-0020-0503 Paint Condition: Fair	Espeil Coulee	57' Treated Timber Trestle General Condition: Good
Br. No. 153-0020-0508 Paint Condition: Fair Remarks: Second stringers cracked in span 1 and 2.	Spring Creek	95' Treated Timber Trestle General Condition: Good
Br. No. 153-0020-0555 Paint Condition: Good Remarks: Girder cracks over every pier.	Porcupine Creek	152' Continuous Concrete T Beam General Condition: Good
Br. No. 153-0020-0563 Paint Condition: Good	Porcupine Creek Overflow	120' Concrete T Beam General Condition: Good
Br. No. 153-0020-0706 Paint Condition: Good	Little Porcupine Creek	204' Pre-stress Concrete Beams General Condition: Good
Br. No. 153-0020-0716 Paint Condition: Good	Indian Service Canal	25' Treated Timber Trestle General Condition: Good
Br. No. 153-0020-0784 Paint Condition: Good	Oswego Creek	63' Treated Timber Trestle General Condition: Good
Field Maintenance Division No. 402 Br. No. 143-0020-0009 Paint Condition: Good	Flynn Creek	Roosevelt County 57' Treated Timber Trestle General Condition: Good
Br. No. 143-0020-0078 Paint Condition: Good	Wolf Creek	152' Continuous Concrete T Beam General Condition: Good
Br. No. 143-0020-0106 Paint Condition: Fair	Mosquito Creek	63' Treated Timber Trestle General Condition: Good
Br. No. 143-0020-0116 Paint Condition: Fair	Little Wolf Creek	100' Treated Timber Trestle General Condition: Good
Br. No. 143-0020-0202 Paint Condition: Good Remarks: Slight crack in left girder on Bent 4.	Tule Creek	120' Concrete T Beam General Condition: Good
Br. No. 143-0020-0301 Paint Condition: Good Remarks: All rockers in extreme expansion position at +20°. Normal age shows on concrete with a few minor chips and spalls.	Poplar River	294' Concrete T Beam General Condition: Good
Br. No. 143-0020-0339 Paint Condition: Fair Remarks: Piles show some rotting at ground line.	Drainage	57' Untreated Timber Trestle General Condition: Good
Br. No. 143-0020-0451 Paint Condition: Good Remarks: The riprap on east berm is about 25 percent washed out.	Drainage	38' Treated Timber Trestle General Condition: Good

Br. No. 143-0020-0477	Box Elder Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 143-0020-0578	Big Muddy River	162.5 Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: The lapped steel expansion joint in the slab is closed up at +20°F.		
The right rail has been hit and bent.		
Br. No. 143-0020-0645	Clover Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 143-0020-0779	Shotgun Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Field Maintenance Division No. 302		West Glacier Spur
		Flathead County
Br. No. 115-0020-0001	G. N. Railway	Underpass
Paint Condition: Fair		General Condition: Good
Remarks: Underpass vertical clearance signs read - 14' 10". The checked vertical clearance is 14' 0".		
Br. No. 115-0020-0002	Middle Fork Flathead River	380' Continuous Steel Truss
Paint Condition: Fair to Good		General Condition: Good
Field Maintenance Division No. 302		East Glacier Spur
		Glacier County
Br. No. 118-0020-0001	G. N. Railway	Underpass
General Condition: Good		
Br. No. 118-0020-0251	Two Medicine Creek	66' Concrete Arch
Remarks: Did not inspect. Road closed due to snow.		

FEDERAL AID PRIMARY ROUTE 2

Field Maintenance Division No. 101	Mineral County
Br. No. 131-0100-0024 St. Regis River	42.3' Steel Girder
Paint Condition: Fair	General Condition: Good
Remarks: Due to embankment slopes and amount of snow, could not get under bridge to check steel previously reported as tight against back wall. From southeast down stream side steel and abutments could be seen and appeared good.	
Br. No. 131-0100-0068 Randolph Creek	23.3 Steel I Beam
Paint Condition: Good	General Condition: Good
Remarks: One right lower rail unit broken and pushed out. Deck surface snow covered.	
Br. No. 131-0100-0082 St. Regis River	100' Cantilever Steel Girder
Paint Condition: Good to Poor	General Condition: Good
Remarks: Exterior steel girder paint poor - interior girders good. Heavy disintegration of concrete rail posts and portions of deck edge. Oiled deck surface good.	
Br. No. 131-0100-0109 St. Regis River	100' Cantilever Steel Girder
Paint Condition: Fair to Poor	General Condition: Good
Remarks: Exterior girder and steel haunches poor - interior girders good - rail fair. Concrete post tops deteriorating. Portion of oiled surface not snow covered is good.	
Br. No. 131-0100-0224 Twelve-Mile Creek	41.5' Concrete T Beam
Paint Condition: Fair to Poor	General Condition: Good
Remarks: Three rail units not painted aluminum coat. Slight creek side movement of the two jointed wing walls. Deck surface good.	
Br. No. 131-0100-0343 St. Regis River	190' Continuous Steel Girder
Paint Condition: Fair	General Condition: Good
Remarks: Several rail units heavily deteriorated. Paint on central structural steel fair to good - west end span has many small abrasions and flaked spots caused by rocks. Oiled surface good.	
Br. No. 131-0100-0346 Clark Fork & N.P. R.R.	787' Steel Truss
Paint Condition: Good	General Condition: Good
Remarks: Deck sealed and chipped and in good condition.	
Br. No. 131-0100-0391 C.M.ST. P.& P. R.R.	482' Steel Plate Girder
Paint Condition: Good	General Condition: Good
Remarks: Deck sealed and chipped and in good condition.	
Br. No. 131-0100-0456 Clark Fork	621' Riveted Plate Girder
Remarks: No seal coat surface on deck. Concrete surface in good condition.	
Br. No. 131-0100-0479 FAS Route 257-Superior Interchange	153' Prestressed Concrete Beam
Paint Condition: Good	General Condition: Good
Remarks: No seal coat surface on deck. Concrete surface in good condition.	

Br. No. 131-0100-0479P FAS Rte. 257 - Superior Interchange 153' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: No seal coat surface on deck. Concrete surface in good condition.

Br. No. 131-0100-0495 Cedar Creek 168' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: No seal coat surface on deck. Concrete surface in good condition.

Br. No. 131-0100-0498 Clark Fork 800.9' Riveted Plate Girder
Paint Condition: Good General Condition: Good
Remarks: No seal coat surface on deck. Concrete surface in good condition.

Br. No. 131-0100-0594 C.M.ST.P.&P. R.R. Underpass
Paint Condition: Good General Condition: Good

Br. No. 131-0100-0604F Nemote Creek(used in place) 73.1' Concrete T Beam
General Condition: Good
Remarks: The fill is sloughing out from behind the end bent caps, especially on the west end, which will require attention in the near future. The opening is up approximately 2'-6' from the base of the cap.

Br. No. 131-0100-0620 Tarkio Interchange 128' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good

Br. No. 131-0100-0620P Tarkio Interchange 128' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good

Br. No. 131-0100-0666 C.M.ST.P.&P. R.R. Underpass
Paint Condition: Fair General Condition: Good
Remarks: There is a rust strip approximately 8" wide along the base of the web plate on both exterior girders.

Br. No. 131-0100-0667 Clark Fork 421.5' Steel Truss
Paint Condition: Good to Fair
Remarks: Tie plates along top of bottom chords are rusty. Right side beam seat and the lower portion of Bent 2 steel column are covered with dirt. Right ends of pier coping surfaces are deteriorating.

Br. No. 131-0100-0706 Clark Fork 516.3' Continuous Steel Truss
Paint Condition: Good General Condition: Good
Remarks: Deck surface rough textured due to wearing off of surface mortar. Sub-structure looks good.

Br. No. 131-0100-0758 C.M.ST.P.&P. R.R. Underpass
Paint Condition: Fair
Remarks: Strip of rust on bottom of riveted plate at base of web.

Field Maintenance Division No. 101 Missoula County
Br. No. 132-0100-0014 C.M.ST.P.&P. R.R. 123' Concrete T Beam
Paint Condition: Poor General Condition: Good
Remarks: A few rail units and the south side, intermediate bent cap end surfaces are deteriorating. Paint on trolley guard fence pipe supports is poor. Underside of structure is good and the deck is good. Deck has been oil surfaced since the previous report and is in good condition.

Br. No. 132-0100-0021	Drainage	23' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Treated pole spreaders set longitudinally between the end bent caps.		

Br. No. 132-0100-0043	Nine Mile Creek	121.7' Concrete T Beam
General Condition: Good		
Remarks: The southwest end post and rail section has been broken off. The next section east has been cracked through the posts. These units have been repaired with two piles set in the fill and against the deck edge and corrugated metal rail extends the length of the two sections. The first section is cable tied to the pile posts and the next section is bolted to the outside of the cracked concrete posts. One broken rail section on the north side is bridged with a corrugated metal rail section and bolted to 4x4's on the outside. Oil mat on deck is good. Substructure looks good.		

Br. No. 132-0100-0044	C.M.ST.P.&P. R.R.	Underpass
Paint Condition: Good		General Condition: Good
Remarks: Paint generally good except for rust on the lower riveted plate along the base of the web plate and the beam flange edges. Concrete surfaces outside exterior beam faces, west half of structure, is deteriorating and in some sections the re-steel is exposed.		

Br. No. 132-0100-0051	Nine Mile Slide	378.5' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Fifth stringer from right, span two, previously reported as split, has been repaired with two spaced steel bars across the base and bolts up through the deck. Substructure stringers and deck base look good. Some of the piling is deeply checked. Surface oil mat is in good condition.		

Br. No. 132-0100-0203	N. P. Railway	Underpass
Paint Condition: Fair		General Condition: Good
Remarks: Paint poor along bottom of web above the flange. Rust showing.		

Br. No. 132-0100-0287	Rattlesnake Creek	120' Concrete Arch
General Condition: Good		
Remarks: Cracks near ends of concrete side arches. Northeast end post broken horizontally at center.		

Br. No. 132-0100-0305	N. P. Railway	Underpass
Paint Condition: Fair to Poor		General Condition: Good
Remarks: Wing faces scaling, heavy central vertical crack in west abutment and northeast wing wall. Spaces between central and south side girders have been closed with wood forms set on top of bottom flanges. A new deck of 12 x 12 treated timbers has been set on the top south side of structure and main line rails set on the timber base. No track on north side of structure at present time. It appears that the new deck was installed recently.		

Br. No. 132-0100-0348	Big Blackfoot River	354' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Checked Bent 2 expansion device which clicks under heavy traffic. Concrete surfaces adjacent to joint in good condition. No cracking. Click due to slight space between plates.		

Br. No. 132-0100-0354	C.M.ST.P.&P. R.R. Overpass	88' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: Some flaking and abrasion of rails due to surfacing chips being flipped off by traffic.		
Br. No. 132-0100-0423	Truck Road Overpass	27' Untreated Timber Trestle
Paint Condition: Good		General Condition: Fair
Remarks: End bent piles damaged by trucks have been reinforced with 12 x 12 and 8 x 8 timber piles set in where required. Original piling and caps have been tightened with wedges. Oil mat shows some cracks but the surface is good.		
Field Maintenance Division 101		Powell County
Br. No. 139-0100-0015	Jens Interchange	113' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 139-0100-0015P	Jens Interchange	113' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 139-0100-0055	FAS Rte. 460-Gold Creek Interchange	153' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 139-0100-0055P	FAS Rte. 460-Gold Creek Interchange	153' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 139-0100-0142	N.P. R.R. Overpass	204' Continuous Rolled Beam
Paint Condition: Good		General Condition: Good
Remarks: Anchor bolt nut, east side, second bent from north, is nearly off.		
Br. No. 139-0100-0146	Little Blackfoot River	140.5' Concrete I Beam
Paint Condition: Good		General Condition: Good
Remarks: Southeast end post cracked through at top of curb height. South end bent has a vertical hairline crack at center of cross beam.		
Br. No. 139-0100-0195	County Road-Jr. Grade Separation	20' Concrete Slab
Paint Condition: Good		General Condition: Good
Br. No. 139-0100-0224	County Road-Jr. Grade Separation	20' Concrete Slab
Paint Condition: Good		General Condition: Good
Br. No. 139-0100-0244	County Road- North Interchange	123' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 139-0100-0255	Milwaukee Avenue Separation	118' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 139-0100-0265	County Road Separation	168' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 139-0100-0272	Clark Fork	153' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good

Br. No. 139-0100-0272P Clark Fork 153' Prestressed Concrete T
Beam
Paint Condition: Good General Condition: Good

Br. No. 139-0100-0275 FAP Rte. 2-South Interchange Underpass
Paint Condition: Good General Condition: Good
Remarks: Eastbound

Br. No. 139-0100-0275P FAP Rte 2-South Interchange Underpass
Paint Condition: Good General Condition: Good
Remarks: 0275 and 0275P are one - also 139-0100-0031.

Br. No. 139-0100-0280 Powell Creek 35' Concrete T Beam
General Condition: Good
Remarks: Some spalling of west deck edge. Northwest curb end damaged and
post is cracked from curb and deck. Northwest reflector is gone.
Hair cracks in girders. Oiled surface on deck in good condition.

Br. No. 139-0100-0312 Dempsey Creek 62' Concrete T Beam
General Condition: Good
Remarks: West column of Bent 3 spalling at water line and exposing re-steel.
Light cracks in west curb over drains. North bent has settled 3" to
4" on east side and 1" to 2" on west side. No damage other than change
in line along tops of rail posts. Oiled surface on deck in good
condition.

Br. No. 139-0100-0331 Race Track Creek 35' Concrete T. Beam
General Condition:
Remarks: Hair line cracks in girders and curbs over drains. Spalled east edge
of deck has been repaired. Oiled surface on deck in good condition.

Br. No. 139-C100-0342 C.M.ST.P.&P. R.R. Overpass 182.2' Concrete T Beam
General Condition: Good
Remarks: Top and outside faces of the copings of intermediate Bents 2 and 5
are crazed and disintegrating. Deck joints open due to loss of filler.
Overhang haunch at Bent 5 disintegrating and re-steel is exposed.
Oiled surface on deck in good condition.

Field Maintenance Division 201 Deer Lodge County
Br. No. 112-0100-0034 Lost Creek 35' Concrete T Beam
General Condition: Good
Remarks: Short light cracks in wings at junction with curbs. Oiled surface
on deck in good condition.

Br. No. 112-0100-0061 Warm Springs Creek 27' Concrete T Beam
General Condition: Good
Remarks: Oiled surface on deck in good condition.

Br. No. 112-0100-0088 Drainage 31' Concrete T Beam
General Condition: Good
Remarks: Light wing cracks at junction with curbs. Hair line cracks in girders.
Oiled surface on deck in good condition.

Br. No. 112-0100-0093	Drainage	35' Concrete T Beam
General Condition: Good		
Remarks: Short light cracks in the wing wall at junction with curbs. Some hair cracks in girders and in curbs over drains. Oiled surface on deck in good condition.		
Br. No. 112-0100-0099	Willow Creek	35' Concrete T Beam
General Condition: Good		
Remarks: Light cracks in all wings at curb junction. Hair cracks in girders. Oiled surface on deck in good condition.		
Br. No. 112-0100-0102	Clark Fork(Signed Silver Bow Creek)	75' Concrete T Beam
General Condition: Good		
Remarks: Hair line cracks in girders and a few in the curbs over drains. Slight spalling of top edge of deck for two rail panel lengths on east side. Oiled surface on deck in good condition.		
Br. No. 112-0100-0116	Drainage	25' Concrete T Beam
Remarks: Lower rail at northwest end post broken. Light cracks in west curb over drains. Oiled surface on deck in good condition.		
Field Maintenance Division 201		Silver Bow County
Br. No. 147-0100-0002	C.M.ST.P.&P. R.R.	Underpass
Paint Condition: Good		General Condition: Good
Remarks: East exterior beam hit and flange split and lower part of web bent. West exterior beam flange bent.		
Br. No. 147-0100-0084	U.S. 91	161' Continuous Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: See FAP Rte. 3, 147-0910-0295. Northwest rail panel hit and three pickets bent. Oiled surface good. Some light cracks across curbs.		
Br. No. 147-0100-0113	B.A.&P. Railway	133' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: Eastbound lane. Some light cracks across curbs. Oiled surface on deck in good condition.		
Br. No. 147-0100-0113P	B.A.&P. Railway	133' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: Westbound lane. One picket on north rail broken from bottom rail. Some light cracks across curbs. Oiled surface on deck in good condition.		
Br. No. 147-0100-0121	U.S. 10A	Underpass
Paint Condition: Good		General Condition: Good
Br. No. 147-0100-0127	Excelsior Street	156' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: Some light cracks across curbs and at rail posts. Oiled surface on decks in good condition.		

Br. No. 147-0100-0136	Clark Fork	35.5' Concrete Slab
General Condition: Fair		
Remarks: Rail cracked and one re-bar exposed. East sidewalk surface gone and curb deteriorating. East half (northbound lane) of deck is oil surfaced. West half of deck has a number of cracks and surface worn exposing coarse aggregate. Underside of slab has one spalled spot exposing re-bar. There are also some honeycomb areas, otherwise, deck base good. North abutment and west wing eroded 6" deep exposing vertical and horizontal re-bars. Heel of center pier eroded in 1'6" exposing re-bars, and about 4" at nose. Top and end of northwest wing deteriorating and re-steel is exposed.		
Br. No. 147-0100-0137	N. P. Railway	Underpass
Paint Condition: Good		General Condition: Good
Remarks: Tops of retaining walls and trainmans walk deteriorating, also top of wings.		
Br. No. 147-0100-0138	Interstate Routes 15 & 90	Underpass
Paint Condition: Good		General Condition: Good
Remarks: Vertical clearance may change following construction. Roadway contract let August 30, 1961.		
Br. No. 147-0100-0139	Interstate Routes 15 & 90	Underpass
Paint Condition: Good		General Condition: Good
Br. No.	U.S. 10-Montana St. Interchange	
		168' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: Also #147-0100-0139		
Br. No. P	U.S. 10-Montana St. Interchange	
		168' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: Also #147-0100-0138		
Br. No.	Lexington St. Separation	Underpass
Paint Condition: Good		General Condition: Good
Br. No. P	Lexington St. Separation	
Remarks: Preceding same structure. Roadway contract let August 30, 1961		
Br. No.	Oregon Street Separation	Underpass
Paint Condition: Good		General Condition: Good
Bridge No. P	Oregon Street Separation	Underpass
Remarks: Preceding same structure.		
Br. No.	U.S. 10 Bypass Harrison Ave. Interchange	
		209.5' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. P	U.S. 10 Bypass Harrison Ave. Interchange	209.5' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good

Br. No. Sheridan Street Separation Underpass
Paint Condition: Good General Condition: Good

Br. No. P Sheridan Street Separation Underpass
Paint Condition: Good General Condition: Good
Remarks: Preceding same structure.

Br. No. 147-0100-0158 Drainage 33' Concrete Slab
General Condition: Good
Remarks: Light vertical crack in west abutment. Oiled surface on deck in good condition.

Field Maintenance Division 201 Jefferson County
Br. No. 122-0100-0075 Rader Creek 95' Treated Timber Trestle
Paint Condition: Good southside - Fair north side General Condition: Good
Remarks: Northwest end post, rail and curb end traffic damaged. Two additional stringers set in Span 2 to reinforce broken stringers. Oiled surface on deck in good condition.

Br. No. 122-0100-0098 Colbert Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Some loose x-bridging and one-half of one piece of solid bridging gone. Oiled surface on deck is in good condition.

Br. No. 122-0100-0132 Big Pipestone Creek 76' Treated Timber Trestle
Paint Condition: Good, south side - Poor, north side General Condition: Good
Remarks: One broken stringer, east span, repaired with steel side and base plates bolted to stringer. Oiled surface on deck is in good condition.

Br. No. 122-0100-0136 N. P. Railway 113' Concrete T Beam
General Condition: Good
Remarks: Four west rail post tops traffic chipped and the north end post cracked around the base. West end of Bent 2 coping cracked vertically. Oiled surface on deck is in good condition.

Br. No. 122-0100-0186 Whitetail Creek 63.8' Concrete T Beam
Paint Condition: Good General Condition: Good
Remarks: Oiled surface wearing off in westbound traffic lane, otherwise good. Exposed concrete in deck in good condition.

Br. No. 122-0100-0256 North Boulder River 90' Steel Pony Truss
Paint Condition: Good General Condition: Good
Remarks: Paint good except on a few truss members, north side, which have been traffic scarred. Oiled surface good.

Br. No. 122-0100-0391 Drainage 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Rails and posts scarred and several posts split at bottom. Oiled surface on deck in good condition.

Field Maintenance Division No. 201 Broadwater County
Br. No. 104-0100-0003 Dry Wash 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Paint good on south rail and fair on north rail. Oiled surface on deck in good condition.

Br. No. 104-0100-0045	Dry Wash	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: One broken stringer repaired with steel base plate with bolts up through deck. West end bent cribbed and braced to hold roadway fill. Several rail posts split and one rail end broken. South side rail battered out of alignment. Oiled surface on deck is in good condition.		
Br. No. 104-0100-0047	Jefferson River	247' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Some transverse checking in the deck and light cracks across curbs at some drains. This deck has not been sealed but is in good condition.		
Field Maintenance Division No. 201		Gallatin County
Br. No. 116-0100-0016	C.M.ST.P.&P. R.R.	208.3' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Some surface crazing and cracking on caps and bents.		
Br. No. 116-0100-0042	Madison River	220' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 116-0100-0048	Middle Fork Madison River	100' Concrete Slab.
Paint Condition: Poor (Pipe Rail)		General Condition: Good
Remarks: Rail is traffic scarred and one post is split. Up stream face of two columns show advanced erosion.		
Br. No. 116-0100-0055	East Fork Madison River	80' Concrete Slab
Paint Condition: Good (Pipe Rail)		General Condition: Good
Remarks: Some crazing of deck slab edges. Rail posts and curb faces are traffic scarred. One south side pipe rail section damaged.		
Br. No. 116-0100-0062	Ray Creek	80' Concrete Slab
Paint Condition: Fair (Pipe Rail)		General Condition: Good
Remarks: Tops of posts and curb faces have been scarred by traffic, also sections of curb top and face on both sides are deteriorating		
Br. No. 116-0100-0086	County Road	77' Concrete T Beam
General Condition: Good		
Remarks: Tops of rail posts nicked by traffic.		
Br. No. 116-0100-0087	N. P. Railway	343.2' Concrete T Beam
General Condition: Good		
Remarks: Movement of third span has opened east joint to 2 3/4" and shift shows in the curb alignment. Four posts on the north side damaged and re-steel exposed.		
Br. No. 116-0100-0119	Drainage	21.5' Concrete Slab
General Condition: Good		
Br. No. 116-0100-0156	N. P. Railway	280' Concrete Girder
General Condition: Good		
Remarks: Deck expansion joints are open. Some crazing and light deterioration of concrete surfaces of intermediate bent caps.		

Br. No. 116-0100-0165	Camp Creek	41' Concrete T Beam
General Condition: Good		
Br. No. 116-0100-0167	Baker Creek	51.6' Concrete T Beam
General Condition: Good		
Br. No. 116-0100-0181	West Gallatin River	247' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Some rocker pins are moving slightly. Tightened several nuts by hand at both end bents. Nuts should be set.		
Br. No. 116-0100-0318	N. P. Railway	208.5' Concrete T Beam
General Condition: Good		
Remarks: Some scattered spalling of concrete surfaces, deck edge, curb ends, etc., rail chipped by traffic. Could not check deck condition due to snow and ice cover.		
Br. No. 116-0100-0324	N. P. Railway	154' Continuous Steel Beam
Paint Condition: Fair		General Condition: Good
Remarks: Two rail units on the east side are broken. Bent 4 rockers are in the expansion position.		
Br. No. 116-0100-0391	Bear Canyon Interchange	113' Prestressed Concrete Beam
Remarks: Under Construction Let 5-24-61		
Br. No. 116-0100-0391P	Bear Canyon Interchange	113' Prestressed Concrete Beam
Remarks: Under Construction Let 5-24-61		
Br. No. 116-0100-0397	N. P. Railway	337.5' Steel Girder
Remarks: Under Construction Let 5-24-61		
Br. No. 116-0100-0397P	N. P. Railway	332.5' Steel Girder
Remarks: Under Construction Let 5-24-61		
Br. No. 116-0100-0424	Trail Creek Interchange	128' Prestressed Concrete Beam
Remarks: Under Construction Let 5-24-61		
Br. No. 116-0100-0424P	Trail Creek Interchange	128' Prestressed Concrete Beam
Remarks: Under Construction Let 5-24-61		
Field Maintenance Division No. 202		Park County
Br. No. 134-0100-0083	U.S. 10 West Interchange	113' Prestressed Concrete Beam
Remarks: Under Construction Completion date 9-15-62 Roadway		
Br. No. 134-0100-0083P	U.S. 10 West Interchange	113' Prestressed Concrete Beam
Remarks: Under Construction Completion date 9-15-62 Roadway		
Br. No. 134-0100-0084	U.S. 89 South Interchange	251' Prestressed Concrete Beam
Remarks: Under Construction Completion date 9-15-62 Roadway		FAP Rte. 11 #134-0890-0548
Br. No. 134-0100-0084P	U.S. 89 South Interchange	251' Prestressed Concrete Beam
Remarks: Under Construction Completion date 9-15-62 Roadway		FAP Rte. 11 #134-0890-0549

Br. No. 134-0100-0090	Yellowstone River	730' Riveted Plate Girder
Paint Condition: Good		General Condition: Good
Br. No. 134-0100-0090P	Yellowstone River	730' Riveted Plate Girder
Paint Condition: Good		General Condition: Good
Br. No. 134-0100-0123	FAS Rte. 295- Separation	128' Prestressed Concrete Beam
General Condition: Good (Concrete)		
Remarks: Under Construction Completion date 9-15-62 Roadway		
Br. No. 134-0100-0123P	FAS Rte. 295-Separation	128' Prestressed Concrete Beam
General Condition: Good (Concrete)		
Remarks: Under Construction Completion date 9-15-62 Roadway		
Br. No. 134-0100-0133	U.S. 89 East Interchange	Underpass
Remarks: Under Construction Completion date 9-15-62 FAP Rte. 11 #134-0890-0597		
0133 and 0133P - one structure		
Br. No. 134-0100-0133P	U.S. 89 East Interchange	Underpass
Remarks: Under Construction Completion date 9-15-62 0133 and 0133P -One structure		
Br. No. 134-0100-0159	U.S. 89 - Mission Interchange	Underpass
Remarks: Under Construction Completion date 9-15-62 Roadway - 0159 and 0159P one structure.		
Br. No. 134-0100-0159P	U.S. 89 - Mission Interchange	Underpass
Remarks: Under Construction Completion date 9-15-62 Roadway - 0159 and 0159P one structure.		
Br. No. 134-0100-0198	Mission Creek	118' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 202		Sweet Grass County
Br. No. 149-0100-0157	Boulder River	286' Steel Plate Girder
Paint Condition: Good		General Condition: Good
Remarks: Pitted spots in paint surface, otherwise good.		
Br. No. 149-0100-0158	Boulder River Overflow	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 149-0100-0199	Dry Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 149-0100-0220	Upper Deer Creek	39' Concrete T Beam
General Condition: Good		
Remarks: Surface mortar worn from rail posts and curb faces. Deck edges are disintegrating.		
Br. No. 149-0100-0236	Lower Deer Creek	39' Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: Paint on south girder exterior face is pitted and flaked due to children throwing rocks. North side much better. Interior beams good.		
Br. No. 149-0100-0239	Drainage and Stockpass	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 149-0100-0311	Bridger Creek	95' Concrete T Beam
General Condition: Good		
Remarks: Considerable deterioration of rail surfaces, especially the north side. There are a few cracked beam haunches.		
Br. No. 149-0100-0345	Work Creek	67' Concrete T Beam
General Condition: Good		
Remarks: Heavy disintegration of south exterior face of curb and top edge of deck.		
Br. No. 149-0100-0357	Humph Creek	29' Concrete T Beam
General Condition: Good		
Remarks: A few rail posts battered and south exterior curb face and deck edge is deteriorating.		
Field Maintenance Division No. 501		Stillwater County
Br. No. 148-0100-0054	Section House Creek	89' Concrete T Beam
Paint Condition: None needed		General Condition: Fair
Remarks: Rail has been damaged quite a little. There is spalling on concrete edges of slab. Rail shows structure has sagged out of grade line at some time.		
Br. No. 148-0100-0065	Yellowstone River	568.6' Steel Truss
Paint Condition: Fair		General Condition: Fair
Remarks: One corner post cracked at bottom and leaned over slightly. Tops of piers are spalling at edges. Rail bent in places.		
Br. No. 148-0100-0065	Yellowstone River	558' Riveted Plate Girder
Remarks: New 1961 New job. I did not look it over.		
Br. No. 148-0100-0071	N. P. Railway	207.6' Steel Girder
Paint Condition: Fair		General Condition: Fair
Remarks: Left rail shows a sag in it. At Bent 5, the expansion joint is opened up to 2". Right girder Bent 5 has a section broken out of bent cap. One rail post has been hit and damaged.		
Br. No. 148-0100-0085	Coulee Creek	65' Concrete T Beam
Paint Condition: None needed		General Condition: Good
Remarks: One rail post on left side hit and smashed.		
Br. No. 148-0100-0091	Berry Creek	75.5' Concrete T Beam
Paint Condition: None needed		General Condition: Good
Br. No. 148-0100-0094	Merrill Ditch	21.7' Concrete Slab
Paint Condition: None needed		General Condition: Good
Br. No. 148-0100-0171	Keyser Creek	75.5' Concrete T Beam
Paint Condition: None needed		General Condition: Good
Remarks: One corner post has chip knocked out.		
Br. No. 148-0100-0229	Brown Creek	96' Concrete T Beam
Paint Condition: None needed		General Condition: Good

Br. No. 148-0100-0235	Hensley Creek	83.5' Steel I Beam
Paint Condition: Fair		General Condition: Good
Remarks: Dirt eroding out from end bent caps. Two terminal rail ends on wrong.		
Br. No. 148-0100-0257	Cove Irrigation Ditch	23' Steel I Beam
Paint Condition: Fair		General Condition: Good
Remarks: Some noticeable spalls in the older concrete.		
Br. No. 148-0100-0285	Allen Creek	21' Steel I Beam
Paint Condition: Fair		General Condition: Good
Remarks: Drift collected underneath. Several checked posts.		
Br. No. 148-0100-0299	Big Ditch	100' Continuous Concrete T Beam
Paint Condition: Good		General Condition: Good
Br. No. 148-0100-0342	Valley Creek	107.6' Steel I Beam
Paint Condition: Fair		General Condition: Good
Remarks: About 15 percent of the posts have good size cracks.		
Br. No. 148-0100-0364	Big Ditch	34' Steel I Beam
Paint Condition: Poor		General Condition: Good
Br. No. 148-0100-0367	Cove Irrigation Ditch	27' Steel I Beam
Paint Condition: Poor		General Condition: Good
Br. No. 148-0100-0384	Cove Irrigation Ditch	25' Steel I Beam
Paint Condition: Fair		General Condition: Good
Remarks: General checking of concrete.		
Field Maintenance Division No. 501		Yellowstone County
Br. No. 156-0100-0015	Big Ditch	63.4' Concrete T Beam
Paint Condition: None needed		General Condition: Good
Remarks: End bent concrete is checked somewhat.		
Br. No. 156-0100-0086	N. P. Railway	269' Steel Girder
Paint Condition: Fair		General Condition: Fair
Remarks: Beam seats on Bent 1 spalled badly at face of concrete. A few scattered spalls on deck. Rockers on Bent 4 in expansion position at +40°.		
Br. No. 156-0100-0091	Canyon Creek Irrigation	25' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Some loose bridging.		
Br. No. 156-0100-0096	B. L. & I. Ditch	36' Steel I Beam
Paint Condition: Fair		General Condition: Fair
Remarks: Fairly old looking. Left corner post Bent 2 broken off at base and pushed out of line 6". Some spalling on concrete edges.		
Br. No. 156-0100-0117	County Road, Beet Dump Separation	153' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 156-0100-0117P	County Road, Beet Dump Separation	153' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good

Br. No. 156-0100-0141 Paint Condition: Good	Underpass	General Condition: Good
Br. No. 156-0100-0141P Paint Condition: Good	Underpass	General Condition: Good
Br. No. 156-0100-0141F General Condition: Good	Canyon Creek	Underpass
Br. No. 156-0100-0142 Paint Condition: Good	Canyon Creek	153' Prestressed Concrete Beam General Condition: Good
Br. No. 156-0100-0142P Paint Condition: Good	Canyon Creek	153' Prestressed Concrete Beam General Condition: Good
Br. No. 156-0100-0142F Paint Condition: Good	Canyon Creek	153' Prestressed Concrete Beam General Condition: Good
Br. No. 156-0100-0169 Paint Condition: Good Remarks: No nameplate.	Hogan Slough	81.5' Prestressed Concrete Beams General Condition: Good
Br. No. 156-0100-0169P Paint Condition: Good Remarks: No nameplate.	Hogan Slough	81.5' Prestressed Concrete Beams General Condition: Good
Br. No. 156-0100-0169F Paint Condition: Good	Hogan Slough	81.5' Prestressed Concrete Beams General Condition: Good
Br. No. 156-0100-0192 Paint Condition: Good Remarks: Retaining walls spreading out at junction with structure 2".	N.P. R.R. & U.S. 10 Bypass	1711' Prestressed Concrete Beams General Condition: Good
Br. No. 156-0100-0192P Paint Condition: Good Remarks: Retaining walls spreading away from where it joins the structure.	N.P. R.R. & U.S. 10 Bypass	1711' Prestressed Concrete Beams General Condition: Good
Br. No. 156-0100-0232 Paint Condition: Fair Remarks: Rockers in expansion position at 40°.	Alkali Creek	130' Continuous Steel Girders General Condition: Good
Br. No. 156-0100-0265 Paint Condition: Good	Bitter Creek	63' Treated Timber Trestle General Condition: Good
Br. No. 156-0100-0272 Paint Condition: Fair	B. L. & I. Ditch	67' Treated Timber Trestle General Condition: Good
Br. No. 156-0100-0281 Paint Condition: Good	B. L. & I. Ditch	59' Treated Timber Trestle General Condition: Good
Br. No. 156-0100-0287 Paint Condition: Good Remarks: Riprapped berms show signs of deterioration.	Seven Mile Creek	25' Treated Timber Trestle General Condition: Good

Br. No. 156-0100-0325	Twelve Mile Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0100-0347	Yellowstone River	1022' Steel Girder
Paint Condition: Fair		General Condition: Good
Remarks: One nut gone from rocker pin Bent 2. Drift collected at Pier 4. Rockers at Pier 4 and east end bent are slightly too much to expansion position.		
Br. No. 156-0100-0381	Custer Coulee	25' Steel I Beam
Paint Condition: Fair		General Condition: Good
Remarks: Rail has a few chips and cracks.		
Br. No. 156-0100-0445	Drainage	24.4' Concrete I Beam
Paint Condition: Poor		General Condition: Good
Br. No. 156-0100-0517	N. P. Railway	268.3' Steel Pony Truss
Paint Condition: Fair		General Condition: Good
Remarks: Small spalls showing up in various places, top Pier 3 and curb edges. Weather checks on corner posts tower span 4 and columns of construction joint.		
Br. No. 156-0100-0540	Fly Creek	125' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: A lot of planking missing from the pile bents.		
Br. No. 156-0100-0557	Sand Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0100-0571	Mill Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0100-0596	Kaiser Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0100-0612	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0100-0627	Spring Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0100-0654	Automatic Creek	106' Steel Girder
Paint Condition: Fair		General Condition: Good
Remarks: Two flared ends on wrong.		
Br. No. 156-0100-0801	Big Horn River	629' Steel Thru Truss
Paint Condition: Fair		General Condition: Good
Remarks: A few small spalls on curb edges. Portals bent slightly.		
Field Maintenance Division No. 501		Treasure County
Br. No. 152-0100-0018	Irrigation Ditch	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 152-0100-0046	Unknown Creek	133' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 152-0100-0103 Paint Condition: Good	Forty-Four Creek	76' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0130 Paint Condition: Good	Buckingham Coulee	95' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0177 Paint Condition: Fair Remarks: Right rail and curb shows quite a swale in grade line at Bent 4 and 5. One rail split.	Box Elder Creek	95' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0188 Paint Condition: Good	Irrigation Ditch	25' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0216 Paint Condition: Good	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0221 Paint Condition: Good	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0226 Paint Condition: Good	Sarpy Creek	95' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0231 Paint Condition: Good	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0234 Paint Condition: Good	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0266 Paint Condition: Fair	Irrigation Ditch	76' Treated Timber Trestle General Condition: Good
Br. No. 152-0100-0282 Paint Condition: Fair	Irrigation Ditch	57' Treated Timber Trestle General Condition: Good
Field Maintenance Division No. 501 Br. No. 144-0100-0039 Paint Condition: Fair	Reservation Creek	Rosebud County 100' Treated Timber Trestle General Condition: Good
Br. No. 144-0100-0081 Paint Condition: Fair	Wyant Coulee	65' Steel I Beam General Condition: Good
Br. No. 144-0100-0100 Paint Condition: None required Remarks: Two beam seats on girders cracked and one crumbled over Pier 2.	Armells Creek	129' Concrete T Beam General Condition: Good
Br. No. 144-0100-0130 Paint Condition: Poor	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0100-0142 Paint Condition: Fair	Smith Creek	89' Steel I Beam General Condition: Good
Br. No. 144-0100-0262 Paint Condition: Fair	Rosebud Creek	123' Steel Pony Truss General Condition: Good

Br. No. 144-0100-0280	Butte Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 144-0100-0337	Sweeney Creek	114' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 144-0100-0365	Coal Creek	95' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 114-0100-0402	Graveyard Creek	81.5' Prestressed Concrete Beams
Remarks: Under contract - Let 7-19-61		
Field Maintenance Division No. 502	Custer County	
Br. No. 109-0100-0061	Moon Creek Road Interchange Underpass	
Remarks: Under contract - Let 7-19-61		
Br. No. 109-0100-0086	Radar Base Interchange	Underpass
Paint Condition: Good		General Condition: Good
Remarks: New in 1961		
Br. No. 109-0100-0154	U.S. 10 West Interchange	Underpass
Paint Condition: Good		General Condition: Good
Remarks: New 1961 - Also Br. No. 109-0100-0154P		
Br. No. 109-0100-0154P	U.S. 10 West Interchange	Underpass
Paint Condition: Good		General Condition: Good
Remarks: No. 109-0100-0154 and 109-0100-0154P	one structure.	
Br. No. 109-0100-0169	Tongue River	290' Riveted Plate Girder
Remarks: New 1961		
Br. No. 109-0100-0178	County Road Separation	153' Prestressed Concrete Beams
Remarks: New 1961		
Br. No. 109-0100-0182	U.S. 312 (FAP Rte. 23)	158' Prestressed Concrete Beams
Remarks: New 1961		
Br. No. 109-0100-0187	Jr. Grade Separation, County Road	21.2' Concrete Slab
Remarks: Under contract - Let 4-19-61		
Br. No. 109-0100-0198	Jr. Grade Separation, County Road	21.2' Concrete Slab
Remarks: Under contract - Let 4-19-61		
Br. No. 109-0100-0210	U.S. 12 - Baker Road Interchange	Underpass
Remarks: Under contract - Let 4-19-61 - Also Br. No. 109-0120-0026		
Br. No. 109-0100-0154	I94 - West Interchange	268' Steel Girder
Remarks: Also Br. No. 109-0100-0154 (Underpass)		
Br. No. 109-0100-0162	N. P. Railway	310.5' Steel Plate Girder
Paint Condition: Good		General Condition: Good

Br. No. 109-0100-0176	Tongue River	300' Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 109-0100-0185	N. P. Railway (City)	Underpass
Paint Condition: Poor		General Condition: Fair
Remarks: Sidewalk on right on east end has heaved out of place. Many large cracks in it and also in wall from walkway to roadway. Slab is rough, many cracks and a lot of asphalt patching has been done. One post up by the rail walkway has chunk broken out. Curb along roadway is spalling in places.		
Br. No. 109-0120-0224	I94--(Baker Road Interchange)	168' Prestressed Concrete Beams
Remarks: Also Br. No. 109-0100-0210P		
Br. No. 109-0120-0225	Kircher Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: No signs.		
Br. No. 109-0120-0241	Dry Wash	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: No signs.		
Br. No. 109-0120-0249	Bensley Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 109-0120-0353	Meadow Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0360	Ash Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0383	Little Cottonwood Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0395	Cottonwood Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0428	South Fork Smith Creek	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Rail scarred up a little.		
Br. No. 109-0120-0435	Smith Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0457	Dry Wash	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0472	Smith Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0474	Powder River	553.5' Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: Deck expansion plate in Pier 3 doesn't have the required clearance. There is 3/8" at 10° below 0°. Rockers on Bent 1 covered with dirt and asphalt mix.		

Br. No. 109-0120-0506	Rabbage Creek	114' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0511	Dry Wash	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Bent 1 cap shows movement with fill pressure. The cap timber is tipped up toward the right side of the roadway.		
Br. No. 109-0120-0523	Dry Wash	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0531	Dry Wash	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0535	Johnnie Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0541	Dry Wash	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0552	Hogan Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0566	Archdale Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0607	Locate Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-0120-0675	South Fork Cottonwood Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 502		Fallon County
Br. No. 113-0120-0011	South Fork Cottonwood Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 113-0120-0054	Cottonwood Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 113-0120-0071	O'Fallon Creek	199.8' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Small amount of drift collected at Pier 2.		
Br. No. 113-0120-0099	Hay Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 113-0120-0162	Sandstone Creek	140' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Slight erosion shows on Pier near low water line.		
Br. No. 113-0120-0190	Sandstone Creek	132.9' Steel Girder
Paint Condition: Fair		General Condition: Good
Br. No. 113-0120-0211	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 113-0120-0229	Drainage	50' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 113-0120-0256	Timber Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 113-0120-0280	Red Butte Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 113-0120-0306	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 113-0120-0341	C.M.ST.P.&P. R.R.	159.5' Concrete T Beam
Paint Condition: None Needed		General Condition: Good
Remarks: Girders have a 45° crack back from bearing Bent 1. Center span is shifted about 2" out of line with the second end spans. Expansion material is dropping out at Pier 3. Corner post top Bent 1 is cracked.		
Br. No. 113-0120-0342	Sandstone Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 113-0120-0413	Waterhole Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 113-0120-0433	Sand Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 201		Silver Bow County
Federal Aid Primary Route 2 Loop in Butte		
Br. No. 147-0100-0001	U.S. 10	96' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: Same structure underpass on U.S. 10. Oiled surface on deck is in good condition.		
Br. No. 147-0100-0002	B.A.&P. Ry. & C.M.ST.P.&P. R.R.	162.4 Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Front Street. Some light cracks across curbs. Oiled surface on deck is in good condition.		
Br. No. 147-0100-0008	C.M.ST.P.&P. R.R.	Underpass
Paint Condition: Good to Fair		General Condition: Good
Remarks: Some surface cracks and crazing in abutments and wings. Paint on edge and bottom of girder flanges fair.		
Br. No. 147-0100-0019	N. P. Railway	Underpass
Paint Condition: Good		General Condition: Good
Remarks: Some scaling of abutments and wing surfaces. Vertical crack at south end of west abutment. Paint good except edges and bottom side of flanges which ranges from fair to poor. Oiled street surface under structure is good.		

Br. No. 147-0100-0021	Clark Fork	20' Concrete Slab
General Condition: Good		
Remarks: Harrison Avenue. A few rail posts have a corner re-bar exposed. Cannot see through this structure as the west end which passes between buildings is boarded over. Portion visible from east end appears good. Oiled surface over deck is intact.		
Br. No. 147-0100-0026	Blacktail Creek	20' Concrete Slab
Remarks: This structure will be replaced with a section plate culvert. Grading, surfacing, etc. contract let August 30, 1961.		
Br. No. 147-0100-0027	FAI Routes 15 and 90	Underpass
Paint Condition: Good		General Condition: Good
Br. No. 147-0100-0028	FAI Routes 15 and 90	Underpass
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 501		Yellowstone County
Federal Aid Primary Route 2 Loop in Billings		
Br. No. 156-0100-0027	N. P. Railway	Underpass
Remarks: Not inspected.		
Field Maintenance Division No. 101		Powell County
Federal Aid Primary Route 2 PTW Through Deer Lodge		
Br. No. 131-0100-0011	Cottonwood Creek	23' Concrete Slab
General Condition: Good		
Br. No. 131-0100-0025	Clark Fork	130' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Southwest end post cracked. Four rail posts and brackets broken, next two cracked.		
Br. No. 131-0100-0031 FAI Route 90-South Interchange		
		256' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: Also #131-0100-0275		

FEDERAL AID PRIMARY ROUTE 3

Field Maintenance Division No. 201	Beaverhead County
Br. No. 101-0910-0005 Monida Interchange	118' Prestressed Concrete Beams
Paint Condition: Good	General Condition: Good
Remarks: Oiled surface in good condition. FAS Rte. 509 - #509-01-0001	
Br. No. 101-0910-0015 U. P. R. R.	280.5' Prestressed Concrete Beams
Paint Condition: Good	General Condition: Good
Remarks: Oiled surface on deck is good.	
Br. No. 101-0910-0147 U. P. R. R.	450' Steel Plate Girder
Paint Condition: Good	General Condition: Good
Remarks: Oiled surface on deck is good.	
Br. No. 101-0910-0151 Lima Interchange	118' Prestressed Concrete Beams
Paint Condition: Good	General Condition: Good
Remarks: Oiled surface on deck is good. Vertical clearance above roadway under interchange: 15'	
Br. No. 101-0910-0232 Big Sheep Creek	21.5' Concrete Slab
General Condition: Good	
Remarks: Some light cracks in rails and over curb drains. North abutment eroded at water line. Oiled surface on deck is good.	
Br. No. 101-0930-0310 Drainage	21.5' Concrete Slab
General Condition: Good	
Remarks: North abutment eroding at water line. Top surface of both west wing walls, especially the northwest wing, are deteriorating. Oiled surface on deck is good.	
Br. No. 101-0910-0383 Red Rock River	143' Prestressed Concrete Beams
Remarks: Under construction - Let 3-22-61	
Br. No. 101-0910-0386 County Road Separation	107' Prestressed Concrete Beam
Remarks: Under construction - Let 3-22-61	
Br. No. 101-0910-0443 FAS Rte. 324-Horse Prairie Interchange	
	Underpass
Remarks: FAS Rte. #324-01-0001 Under construction - Let 3-22-61	
Br. No. 101-0910-0448 Beaverhead River	173' Prestressed Concrete Beam
Remarks: Under construction - Let 3-22-61	
Br. No. 101-0910-0536 Grasshopper Creek	31' Concrete T Beam
General Condition: Good	
Remarks: Flex beam rail which replaced damaged west side concrete rail, is in good condition. Oiled surface on deck is in good condition.	
Br. No. 101-0910-0608 Beaverhead River	139.5' Continuous I Beam
Paint Condition: Good	General Condition: Good
Remarks: One end post bridge marker is gone. Oil mat on deck is good. Some light curb cracks over drains.	

Br. No. 101-0910-0613 U.P. R.R. Overpass 143' Concrete T Beam

General Condition: Good

Remarks: West end of north curb cracked. Spans have shifted laterally with respect to each other. Shift at east track bent is approximately 3/4" and at west track bent 2". Girder haunches at west bent are cracked and two at the east bent. Rockers in expansion position. Oiled surface on deck is in good condition.

Br. No. 101-0910-0614 Poindexter Slough 77' Concrete T Beam

General Condition: Good

Remarks: Southwest end post cracked. A few curb cracks over drains. Oiled surface on deck is good.

Br. No. 101-0910-0662 Beaverhead River 149.5' Continuous Steel I Beam

Paint Condition: Good

General Condition: Good

Remarks: No oiled surface on deck. Concrete surface in good condition. Grouted riprap is being undercut and breaking up.

Br. No. 101-0910-0698 Irrigation Canal 29' Concrete T Beam

General Condition: Good

Remarks: Oiled surface in good condition.

Br. No. 101-0910-0707 Fry Pan Creek 66' Concrete T Beam

General Condition: Fair

Remarks: Bent 4 (north) has cracked across the haunches, both sides, at height of beam bottom. Right end post is also cracked. Settlement of Bent 2, approximately 2", has opened up joint at Bent 3 and joint material is gone. Hole in oil mat near center of northeast end post where drainage from bridge runs down behind the backwall.

Br. No. 101-0910-0880 Big Hole River 237.7' Steel Truss

Paint Condition: Fair to Poor

General Condition: Good

Remarks: Curbs deteriorating, especially the north side, exposing re-steel. Truss span rockers are in the extreme expansion position against the anchor bolt nuts. Deck surface is spalling. Rough or pot hole areas have been oil patched. A few truss members are traffic scarred.

Field Maintenance Division No. 201

Silver Bow County

Br. No. 147-0910-0281 FAS Route 423-Victor Interchange Underpass

Paint Condition: Good

General Condition: Good

Remarks: 0281 and 0281P are one structure.

Br. No. 147-0910-0281P FAS Route 423-Victor Interchange Underpass

Paint Condition: Good

General Condition: Good

Remarks: 0281 and 0281P are one structure.

Br. No. 147-0910-0289 B.A.&P. Ry., C.M.ST.P.&P. R.R., N.P. Ry. & Clark Fork

613.5' Steel Girder

Paint Condition: Good

General Condition: Good

Br. No. 147-0910-0289P B.A.&P. Ry., C.M.ST.P.&P. R.R., N.P. Ry. & Clark Fork

598.5' Steel Girder

Paint Condition: Good

General Condition: Good

Br. No. 147-0910-0295 U. S. 10 Underpass
Paint Condition: Good General Condition: Good
Remarks: See FAP Rte 2 #147-0100-0084

Br. No. 147-0910-0368 Truck Road 147.5' Concrete T Beam
Remarks: Bent 5, north column corner, hit by trucks and vertical re-bar is exposed. North column of Bent 4 has some light cracks below the haunches and is bound with 3/4" x 3" steel clamps. One crack in east span. South side rail posts cracked. Repaired with grader blades placed on each side of break and bolted together. Some spalling of deck surface and deterioration of curbs and rail.

Br. No. 147-0910-0372 N. P. Railway 157' Steel Beam
Paint Condition: Good General Condition: Good
Remarks: Tops of southeast and northwest end posts deteriorating, also top and sides of curb and walk. Underside of deck is good. Oiled surface on deck is good. East bent rockers are in the expansion position.

Br. No. 147-0910-0373 Clark Fork 158' Treated Timber Trestle
General Condition: Good
Remarks: Curbs and walks deteriorating, especially the north side. In the center span the sixth stringer from the north has a diagonal crack across the base that extends up the side about 4". This stringer was previously reported. Underside of deck and stringers look good. Oiled surface on deck is in good condition.

Br. No. 147-0910-0374 N. P. Railway 145' Continuous Steel Beam
Paint Condition: Good General Condition: Good
Remarks: At southeast bearing plate surface and end of seat is deteriorating due to weathering. Curb faces, south side curb and deck edge and tops of tower span rail and end posts are also deteriorating. West rockers are in the expansion position. Oiled surface on deck is in good condition. Underside of deck and beams look good.

Br. No. 147-0910-0381 G. N. Railway 125.8' Steel Girder
Paint Condition: Good General Condition: Good
Remarks: Underside of deck and girders look good. Concrete deck shows light surface wear and is in good condition.

Br. No. 147-0910-0382 Drainage 25' Concrete T Beam
General Condition: Good
Remarks: Oiled surface on deck is in good condition. Slight traffic scar on end post and crack in curb.

Field Maintenance Division No. 201 Jefferson County
Br. No. 122-0910-0088 Bison Creek 31' Steel I Beam
Paint Condition: Fair to Poor General Condition: Good
Remarks: East edge of curb and tops of wing walls and deck edge deteriorating. Vertical crack in south abutment and one at junction with wing wall. Oiled surface on deck is in good condition.

Br. No. 122-0910-0123	Bison Creek	81' Concrete T Beam
General Condition: Good		
Remarks: Hairline cracks in girders and diaphragms. Honeycomb area, west column of north stream bent eroded to re-steel. Oiled surface on deck is in good condition.		
Br. No. 122-0910-0135	Bison Creek	98.8' Concrete T Beam
General Condition: Good		
Remarks: End post, rail, and curbs are deteriorating. East side curb is chipping out at joints. Advanced crazing of Pier 2 cap ends. Oiled surface on deck is in good condition.		
Br. No. 122-0910-0144	Bison Creek	31' Concrete T Beam
General Condition: Good		
Remarks: Tops of wing walls are deteriorating, also curbs and the re-steel is exposed on the south curb. Southeast wing cracked at abutment, northwest wing cracked and a large piece is ready to spall off. Oiled surface on deck is in good condition.		
Br. No. 122-0910-0168	G. N. Railway	Underpass
Paint Condition: Good		
Remarks: Paint is generally good. On bottom flanges the paint is fair. Two anchor bolts on inside of girder shoe heaved up.		
Br. No. 122-0910-0179	Boulder River	43' Concrete T Beam
General Condition: Good		
Remarks: South deck edge of east span heavily deteriorated, also top and face of north curb to a lesser degree. Cracks in curbs over drains. Wing wall tops deteriorating. Oiled surface on deck in good condition.		
Br. No. 122-0910-0188	Red Rock Creek	21.5' Concrete Slab
General Condition: Good		
Remarks: Light deterioration of south edge of deck and tops of wing walls. East abutment eroding at water line. Oiled surface on deck in good condition.		
Br. No. 122-0910-0221	Basin Creek	23.3' Concrete Slab
Paint Condition: Good	General Condition: Good	
Remarks: Oiled surface on deck in good condition.		
Br. No. 122-0910-0231	Cataract Creek	79' Concrete T Beam
General Condition: Good		
Remarks: Curbs are deteriorating, especially north face of the north curb, also the south exterior curb face and deck edge. Pier copings crazing and cracking on top and end surfaces. Oiled surface on deck in good condition.		
Br. No. 122-0910-0247	G. N. Railway	Underpass
Paint Condition: Good	General Condition: Good	
Br. No. 122-0910-0248	Boulder River	148.8' Concrete T Beam
General Condition: Good		
Remarks: Curb ends disintegrating. Inside face of west curb and east outside face of curb and deck edge is heavily deteriorated. Top and south end of Bent 3 cap surfaces deteriorating. South exterior girders are chipping at joint over Bent 2. Some cracking of girder haunches		

at Bent 3. Underside of deck and girders look good. Deck surface has been oil patched over spalled areas. Oiled surface wearing off and except for a few pot holes, deck is in good condition. Expansion side of Bent 3 covered with sand falling through deck joint.

Br. No. 122-0910-0266 Boulder River 137.5' Concrete T Beam
Remarks: Face of north curb and south edge of deck are deteriorating. At east end of Span 2, Bent 3, there are some cracks in the girder haunches. At Bent 4, edge of wall deteriorating exposing re-steel. Underside of deck and girders look good. Oiled surface on deck in good condition.

Br. No. 122-0910-0471 Prickley Pear Creek 31' Concrete T Beam
General Condition: Good
Remarks: Some disintegration of concrete of north abutment and one wing wall at water line. Approximately 1" deep. Some light cracks in exterior girders and south abutment at girder haunch line. Oiled surface on deck in good condition.

Br. No. 122-0910-0534 G. N. Railway & Prickley Pear Creek
General Condition: Good 244.5' Concrete T Beam
Remarks: Top of northeast end post broken and top rail hanging over side. One east side lower rail, second span from north, broken out and hanging over side of bridge. At south end bent there are heavy cracks across faces of both haunches that extend up in to cross beam. There are several areas of light cracking in columns and haunches, heavier cracking and some spalling of rails. Some disintegration of outside edge of deck due to weathering. Oil mat on deck in good condition and does not indicate any recent settlement of south end spans of structure.

Field Maintenance Division No. 301 Lewis and Clark County
Br. No. 125-0910-0020 U.S. 12-Colonial Club Interchange Underpass
Paint Condition: Good General Condition: Good
Remarks: New in 1961. FAP Route 8 #125-0120-0178.

Br. No. 125-0910-0020P U.S. 12-Colonial Club Interchange Underpass
Paint Condition: Good General Condition: Good
Remarks: New in 1961. #0020 and 0020P are one structure.

Br. No. 125-0910-0021 U.S. 12-Colonial Club Interchange Underpass
Paint Condition: Good General Condition: Good
Remarks: New in 1961. FAP Rte. 8 #125-0120-0178P.

Br. No. 125-0910-0021P U.S. 12-Colonial Club Interchange Underpass
Paint Condition: Good General Condition: Good
Remarks: New in 1961. #0021 and 0021P are one structure.

Br. No. 125-0910-0028 G.N. Ry., N.P. Ry., & Boulder Avenue
797.5' Riveted Plate Girder
Paint Condition: Good General Condition: Good
Remarks: New in 1961.

Br. No. 125-0910-0028P G.N. Ry., N.P. Ry., & Boulder Avenue
809.7' Riveted Plate Girder
Paint Condition: Good General Condition: Good
Remarks: New in 1961

Br. No. 125-0910-0034 Cedar St. Interchange Underpass
General Condition: Good
Remarks: Under contract - Let 5-24-61

Br. No. 125-0910-0034P Cedar St. Interchange Underpass
Remarks: Under contract - Let 5-24-61 - #125-0910-0034 same bridge

Br. No. 125-0910-0041 York Road Separation Underpass
Remarks: Under contract - Let 5-24-61 - FAS 280 - #280-25-0004

Br. No. 125-0910-0041P York Road Separation Underpass
Remarks: Under contract - Let 5-24-61 - #107-0910-0041 Same bridge

Br. No. 125-0910-0071 County Road Separation 118' Prestressed Concrete Beams
Remarks: Under contract - Let 12-20-61

Br. No. 125-0910-0071P County Road Separation 118' Prestressed Concrete Beams
Remarks: Under contract - Let 12-20-61

Br. No. 125-0910-0101 Lincoln Road Interchange-FAS 274 Underpass
Remarks: Under contract - Let 12-20-61 - FAS Rte. 274 #274-20-0001

Br. No. 125-0910-0101P Lincoln Road Interchange-FAS 274 Underpass
Remarks: #125-0910-0101 and 125-0910-0101P are one structure.

Br. No. 125-0910-0046 G. N. Railway 83' Concrete T Beam
General Condition: Good
Remarks: Shoulder fill at northwest walk end, which has sloughed out for 1.5' in from rail needs to be replaced. Southeast end reflector is gone. Bolsters have been placed under south end diaphragms of Span 2, as girder haunches failed. West diaphragm surface adjacent to exterior girder has flaked off 2 1/2' long, 1 1/2' high and into re-steel above the outer bolster. A few minor cracks in girders and back walls. Concrete deck surface in good condition.

Br. No. 125-0910-0048 N. P. Railway 119' Concrete T Beam
General Condition: Good
Remarks: Fills at both south and northwest sidewalk ends sloughing out and should be refilled. Cracks in both columns to backwall haunches of the north bent. Vertical cracks where exterior girders meet the backwall, both end bents. Both collision struts have vertical cracks at column junction. East side intermediate bent columns lightly cracked at both strut junctures. Minor crack in the haunches of one girder of the center span. Concrete deck surface wearing to coarse aggregate in scattered areas, but in good condition.

Br. No. 125-0910-0068 Helena Valley Canal 23.1' Steel & Concrete
Paint Condition: Good General Condition: Good

Br. No. 125-0910-0074 Ten Mile Creek 67' Concrete T Beam
General Condition: Good
Remarks: At the center pier there are heavy cracks in many of the girder haunches of both spans. Cracks extend from center of bearing plates up and into joint between deck spans. Cracks are all old.

Br. No. 125-0910-0209 Gates of Mountain Interchange 118' Prestressed Concrete Beam
Remarks: Under contract - Let 6-14-61

Br. No. 125-0910-0209P Gates of Mountain Interchange 118' Prestressed Concrete Beam
Remarks: Under contract - Let 6-14-61

Br. No. 125-0910-0283 Sieben Interchange 133' Prestressed Concrete Beam
Remarks: Under contract - Let 10-25-61

Br. No. 125-0910-0283P Sieben Interchange 133' Prestressed Concrete Beam
Remarks: Under contract - Let 10-25-61

Br. No. 125-0910-0294F Little Prickly Pear Creek - On Frontage Road 63.1' Treated Timber Trestle
Remarks: Under contract - Let 10-25-61

Br. No. 125-0910-0365 Sheep Creek 63.2' Concrete T Beam
General Condition: Good
Remarks: Some spalling of concrete on edge of deck overhang haunch north span eastside at joint between spans. Outside edge of deck spalling for one rail panel length on west side. Oiled surface on deck in good condition.

Br. No. 125-0910-0422 Missouri River 472.6' Continuous Steel Truss
Paint Condition: Good General Condition: Good
Remarks: At the north bent there is some disintegration of the concrete around the side and edges of the cap. Deck contraction device over first pier from north is loose and noisy under traffic. Pier scouring at water line. Surface checks in deck slab, but in good condition. Paint is generally good, except on face plates of bent and pier truss batter columns

Br. No. 125-0910-0477 Wagner Creek 39.3' Concrete T Beam
General Condition: Good
Remarks: Hairline cracks in girders. Oiled surface on deck in good condition.

Br. No. 125-0910-0501 Stickney Creek 92' Concrete T Beam
Paint Condition: Good General Condition: Good
Remarks: A few hairline cracks, west girder over bearings. Three small holes in oil mat at deck ends and at face of curbs where drainage runs down behind the backwalls. Concrete deck surface in good condition.

Field Maintenance Division No. 301 Cascade County
Br. No. 107-0910-0049 Novak Creek 43' Concrete T Beam
General Condition: Good
Remarks: Some slight disintegration of concrete surface of Bent 2 cross beams ends due to weathering. Oiled surface on deck in good condition.

Br. No. 107-0910-0064 Missouri River & G. N. Ry. 546.2' Steel Truss
Paint Condition: Good General Condition: Good
Remarks: Paint generally good. There are a number of scattered rust spots. Especially on the truss batter column face plates. Light rail damage both sides. One portal slightly damaged and a number of intermediate sway braces have been **scraped**. One corner post damaged. Concrete deck surface in good condition.

Br. No. 107-0910-0071 Pryetter Creek 79.2' Concrete T Beam
General Condition: Good
Remarks: Oiled surface on deck in good condition.

Br. No. 107-0910-0088 Hardy Creek 96.3' Concrete T Beam
General Condition: Good
Remarks: Oiled surface on deck in good condition.

Br. No. 107-0910-0101 Tingtinger Interchange 133' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: New in 1961

Br. No. 107-0910-0122 Frontage Road Separation 82' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: New in 1961

Br. No. 107-0910-0155 South Cascade Interchange 138' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: New 1961 - Roadway under construction.

Br. No. 107-0910-0170 North Cascade Interchange 123' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: New 1961

Br. No. 107-0910-0237 Little Muddy Creek 100' Continuous Concrete T Beam
Paint Condition: Good General Condition: Good

Br. No. 107-0910-0237P Little Muddy Creek 100' Continuous Concrete T Beam
Paint Condition: Good General Condition: Good

Br. No. 107-0910-0315 Ulm Interchange 130' Continuous Concrete T Beam
Paint Condition: Good General Condition: Good
Remarks: Exterior beam west side and the next beam in have been chipped above the center of the traffic lane into Ulm (high side). No clearances marked on structure.

Br. No. 107-0910-0405 G. N. Railway 174' Continuous Steel Girder
Paint Condition: Good General Condition: Good

Br. No. 107-0910-0409 Sun River 396.1' Steel Truss
Paint Condition: Poor General Condition: Good
Remarks: Some spalling of concrete deck of main span. Oiled surface wearing off. Concrete curb shows some wear. A line of reinforcing steel is exposed in two places. Southwest terminal section of metal rail damaged.

Br. No. 107-0910-0416	G. N. Railway	Underpass
Paint Condition: Good		General Condition: Good
Br. No. 107-0910-0489	County Road-Manchester Interchange	108' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 107-0910-0489P	County Road-Manchester Interchange	108' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Br. No. 107-0910-0530	I15-Vaughn Interchange	219' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: FAP Route 21 - #150-0910-0001		
Br. No. 107-0890-0532	C.M.ST.P.&P.R.R., & G.N. Ry.	138' Concrete T Beam
General Condition: Good		
Br. No. 107-0890-0534	Muddy Creek	146' Concrete Girder
General Condition: Good		
Br. No. 107-0890-0615	Mill Coulee Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Three broken sway braces. Bridge signs need repainting.		
Br. No. 107-0890-0636	Mill Coulee Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Bridge signs need repainting.		
Br. No. 107-0890-0671	Ashuelot Canal	25' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Bridge signs need repainting.		
Br. No. 107-0890-0710	Greenfields South Canal	60' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: New 1961		
Field Maintenance Division No. 301		Teton County
Br. No. 150-0890-0008	Irrigation Canal	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Paint good except for poor paint on some west side rail posts. One rail end shattered.		
Br. No. 150-0890-0193	Teton River	189.7' Steel Pony Truss
Paint Condition: Good		General Condition: Good
Br. No. 150-0890-0303	Drainage	20' Concrete Slab
Paint Condition: Good		General Condition: Good
Remarks: This structure widened with treated timber and a new corrugated metal rail with 8"x8" timber posts.		
Br. No. 150-0890-0333	Foster Creek	45' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Bridge signs need repainting.		

Br. No. 150-0890-0354	Big Muddy Creek	285' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Third spand from south, a broken stringer in center of span has been reinforced with a new stringer set in along side. Stringers throughout the length of the bridge have been tightened up with shingle wedges driven in at top of caps		
Br. No. 150-0890-0375	Jones Coulee	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Piling checked and found to be sound. No bridge signs.		
Br. No. 150-0890-0389	Drainage	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 150-0890-0395	Drainage	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 150-0890-0400	Bynum Canal	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 150-0890-0429	Farmers Coulee	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 150-0890-0450	Walenstein Coulee	38' Treated Timber Trestle
Paint Condition: Good to Fair		General Condition: Fair
Remarks: Due to settlement of north bent a double 6"x18" cap has been set in along side of the old cap and short lengths of pile set on 6"x18" timber sills are used for shores.		
Field Maintenance Division No. 301		Pondera County
Br. No. 137-0890-0003	Hines Coulee	114' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 137-0890-0025	Dry Fork Marias River	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 137-0890-0027	Dry Fork Marias River	75' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 137-0890-0052	Matchette Coulee	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 137-0890-0072	Dupuyer Creek	190' Untreated Timber Trestle
Paint Condition: Poor		General Condition: Fair
Remarks: Four bent caps have been replaced and are bolted to piles with grader blade sections. Three pile stubs have been set in at various locations and have concrete footings enclosed in oil barrel forms. At the south bent, east side, a 6"x18" timber cap bridging four stringers has been set against the old cap and two pile stubs are used for shores. The north end bent has also been repaired. Oil mat on deck is in good condition.		
Br. No. 137-0890-0076	Dupuyer Creek Overflow	57' Untreated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Both end bents have been reinforced with new bents with 12"x12" treated timber caps and treated pile stubs set on 6"x18" treated timber sills.		

Br. No. 137-0890-0078	Sheep Creek	57' Untreated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Third bent from south has been sway braced and a new 12"x12" cap has replaced the old cap. The north end bent has been reinforced with a new bent with a 12"x12" cap and pile stubs set on 6"x18" timber sills. 6"x18" timber used for backing plank. All replacement timber is treated.		
Br. No. 137-0890-0107	Valier Canal	57' Untreated Timber Trestle
Paint Condition: Fair to Poor		General Condition: Fair
Remarks: Piling and backing plank of south end bent replaced. Bent north side of canal has two treated piles set in along side the old piles on the west side and are set in concrete footings. The north end bent has been reinforced with a new bent, with 12"x12" cap and treated pile stubs set on a 6"x18" timber sill, with 6"x18" timber backing plank.		
Br. No. 137-0890-0128	Cartwright Coulee	38' Untreated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: End bents reinforced with new treated timber bents consisting of 12"x12" caps and pile stubs set on 6"x18" timber sills.		
Br. No. 137-0890-0171	Birch Creek	175' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 137-0890-0191	Blacktail Creek	53' Steel I Beam
Paint Condition: Steel Paint Good - Rail Poor		General Condition: Good
Remarks: At north end bent the fill is sloughing out from behind the cross-beam at the junction with the haunch. The opening is about one foot square and extends up two feet from base of beam.		
Br. No. 137-0890-0197	Badger Fisher Canal	39' Steel I Beam
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 301		Glacier County
Br. No. 118-0890-0073	Agency Creek	31' Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: East curb scraped and a few re-bars are exposed at ends and center.		
Br. No. 118-0890-0075	Badger Creek Overflow	63' Steel I Beam
Paint Condition: Steel-Good, Rail-East-Good, West-Poor.		
General Condition: Good		
Br. No. 118-0890-0076	Badger Creek	129.8' Steel Pony Truss
Paint Condition: Steel-Good, Timber Rail-West-Good, East-Poor		
General Condition: Good		
Remarks: Rockers on expansion side, and steel is butted against back wall. Cracks in wall near junction with wings, hairline crack in center of wall. Expansion rockers partially covered with gravel. Should be cleaned off. North end bent has been reinforced with a new treated timber bent consisting of a 12"x12" cap and pile stubs set on a 6"x18" timber sill.		
Br. No. 118-0890-0128	Two Medicine Creek	265' Steel Girder
Paint Condition: Good		General Condition: Good

Br. No. 118-0890-0135	Two Medicine Canal	50' Treated Timber Trestle
Paint Condition: Good to Fair		General Condition: Good
Br. No. 118-0890-0380	Drainage (Lake Creek)	42' Concrete Arch
General Condition: Good		
Remarks: Part of rail coping on each side is gone and one rail end has been knocked off.		
Br. No. 118-0890-0384	South Fork Cut Bank Creek	53' Concrete Arch
General Condition: Fair		
Remarks: Concrete coping section top of both rails is gone, otherwise, masonry rail is good. Due to ice and snow could not check erosion at arch water line.		
Br. No. 118-0890-0427	North Fork Cut Bank Creek	120' Steel Truss
Paint Condition: Fair		General Condition: Good
Remarks: One section of metal rail has been pushed out but not broken. Rockers on expansion side.		
Br. No. 118-0890-0465	Drainage	48' Concrete Arch
General Condition: Good		
Remarks: Mortar out of some joints of masonry rail.		
Br. No. 118-0890-0642	St. Mary's River	312' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 118-0890-0695	Kennedy Creek	121.5' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: New 1961		
Field Maintenance Division No. 301		Cascade County
Federal Aid Primary Route 3 Spur in Great Falls		
Br. No. 107-0910-0009	Missouri River-G.N. Ry.	2092.8 Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: FAP Rte. 41 - Br. No. 107-0875-0047. Deck surface in good condition.		
Federal Aid Primary Route 3 Old PTW		
Br. No. 107-0910-0235	Little Muddy Creek	74.4 Steel I Beam
Paint Condition: Poor		General Condition: Good
Remarks: Some spalling of concrete below a few beams on the faces of the bent caps, also on the west side haunch of one bent cap.		
Br. No. 107-0910-0308	Muddy Creek Slough	33' Steel I Beam
Paint Condition: Good to Fair		General Condition: Good
Remarks: West side rail has been hit forcing entire rail slightly to south, splitting posts and rail ends.		

FEDERAL AID PRIMARY ROUTE 4

Field Maintenance Division No. 501

Carbon County

Br. No. 105-3100-0005

U.S.R.S. Frannie Canal 57' Treated Timber Trestle

Paint Condition: Fair

General Condition: Good

Remarks: End spans so close to ground they are hard to see, but look okay.

Br. No. 105-3100-0042

Sage Creek

76' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Br. No. 105-3100-0121

C.B. & Q. Ry.

142.2' Concrete T Beam

Paint Condition: None needed

General Condition: Good

Remarks: Two small honeycomb spots (16 and 36 sq. in.) on bottom strut Bent 4.

Br. No. 105-3100-0235

Bridger Creek

57' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Remarks: Right rail leans out. Some posts cracked. Looks like wheel guard timber is pushed out.

Br. No. 105-3100-0237

Clark Fork Yellowstone River 300' Steel Girder

Paint Condition: Poor

General Condition: Good

Remarks: Very mild erosion showing at low water line of piers.

Br. No. 105-3100-0290

Sand Creek

57' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Remarks: Banks under end spans are eroding and may cause additional work. Some work has been done here and more may be required.

Br. No. 105-3100-0374

Elbow Creek

28.5' Combination T Beam
and I Beam

General Condition: Good

Paint Condition: Poor

Remarks: One rail post cracked through its anchor bolts. A few cracks in concrete backwall.

Br. No. 105-3100-0423

Rock Creek

137.3' Concrete T Beam

Paint Condition: None needed

General Condition: Good

Remarks: Stream is routing altogether near Bent 4.

Field Maintenance Division No. 501

Yellowstone County

Br. No. 156-3100-0018

N. P. Railway

Underpass

Paint Condition: Good

General Condition: Good

Br. No. 156-3100-0026

Yellowstone River

496' Steel Truss

Paint Condition: Fair

General Condition: Good

Remarks: Extensive checking on large corner posts Bent 1 and Bent 4.

Noticeable spalling on curb edges and slab edges. Piers showing age checks. Spalling top of columns Bent 4.

Br. No. 156-3100-0036

Drainage

25' Treated Timber Trestle

Paint Condition: Good

General Condition: Fair

Remarks: Has been burned underneath. Looks structurally okay. Some stringers so close to the ground, I could not see all of them.

Br. No. 156-3100-0038

N. P. Railway

Underpass

Paint Condition: Fair

General Condition: Good

Remarks: Extensive spalling on sidewalk up near tracks and curb of slab below. Curb about 10 percent gone. One large crack in slab across road near south end.

FEDERAL AID PRIMARY ROUTE 5

Field Maintenance Division No. 101

Br. No. 132-0930-0099 G. N. Railway

Paint Condition: Fair

Missoula County

125' Steel Beam

General Condition: Good

Field Maintenance Division No. 101

Br. No. 124-0930-0039 Jocko River

Paint Condition: Good

Lake County

104' Concrete T Beam

General Condition: Good

Br. No. 124-0930-0231 Post Creek

Paint Condition: Good

51' Concrete T Beam

General Condition: Good

Br. No. 124-0930-0261 Nine Pipe Reservoir

Paint Condition: Good

76' Treated Timber Trestle

General Condition: Good

Br. No. 124-0930-0295 Crow Creek

Paint Condition: Good

57' Treated Timber Trestle

General Condition: Good

Br. No. 124-0930-0341 Drainage

General Condition: Good

20' Concrete Slab

Remarks: Some light traffic scars on rail posts.

Br. No. 124-0930-0421 Pablo Feeder Canal

Paint Condition: Good

General Condition: Good

82' Continuous Concrete T Beam

Br. No. 124-0930-0462 Flathead River

Paint Condition: Good to Fair

2014' Treated Timber Trestle

General Condition: Good to Fair

Remarks: Signs at bridge ends - 30 M.P.H.. Paint on south side rail good. North side rail traffic scuffed. Two rail posts on north side posts traffic damaged. Curb ends of some plank in the sidewalk are broken. Original east end bent piling and cap pushed towards river by roadway fill. A new bent has been set in on the road side. Backing plank on the new bent extends partway down and backing plank on the old bent extends up a sufficient height to retain the fill. Some longitudinal bent to bent pile bracing and a number of sway braces are split or broken five to six spans out from each end bent could be visually inspected. The stringers and under side of deck look good. Surfacing on deck is intact and central portion not snow covered is in good condition.

Br. No. 124-0930-0672 Dayton Creek

General Condition: Good

61' Concrete T Beam

Field Maintenance Division No. 102

Br. No. 115-0930-0227 Stillwater River

Paint Condition: Good

Flathead County

155.3' Concrete T Beam

General Condition: Good

Br. No. 115-0930-0346 Whitefish River

Paint Condition: Fair to Good

215' Steel Beam

General Condition: Fair to Good

Remarks: At west end bent steel is butted against concrete backwall. The concrete at the exterior beam ends is chipped out to re-steel. At east end bent the concrete has spalled off under the southeast bearing plate, exposing about 2" of outside anchor bolt below the plate

base. This plate is 50 percent unsupported. The concrete at face of bearing seats of next three inside beams is spalling off. The same condition exists at northside bearing plate. These plates are still fully supported. Excessive deterioration of several rail units and post tops.

Br. No. 115-0930-0512 G. N. Railway Underpass
Paint Condition: Good General Condition: Good
Remarks: Bottom flanges all beams have been scraped.

Field Maintenance Division No. 102 Lincoln County
Br. No. 127-0930-0012 Stillwater River 60' Concrete T Beam
Paint Condition: Good General Condition: Good

Br. No. 127-0930-0133 Graves Creek 57' Concrete T Beam
General Condition: Good

Br. No. 127-0930-0136 Drainage 43' Concrete T Beam
General Condition: Good
Remarks: The center bent cap is cracked at each end at diagonally opposite points. The cracks extend up into the beam haunches and angle out to face of cap. One span central end post has a large spall ready to drop off, just below the bottom rail.

FEDERAL AID PRIMARY ROUTE 6

Field Maintenance Division No. 101		Sanders County
Br. No. 145-0105-0110	Bull River	161' Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 145-0105-0127	N. P. Ry. Overpass	346' Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 145-0105-0170	N. P. Ry. Overpass	315' Continuous Deck Plate Girder
Paint Condition: Good		General Condition: Good
Br. No. 145-0105-0281	Clark Fork	1061' Continuous Deck Plate Girder
Paint Condition: Good		General Condition: Good
Br. No. 145-0105-0314	N. P. Railway	Underpass
Paint Condition: Poor		General Condition: Good
Remarks: Considerable rust on girders.		
Br. No. 145-0105-0335	Beaver Creek	230' Steel Beam
Paint Condition: Good		General Condition: Good
Remarks: Right post Bent 1 has a vertical crack. Section of curb and outside edge of deck deteriorating.		
Br. No. 145-0105-0492	Clark Fork	949' Riveted Plate Girder
Paint Condition: Good		General Condition: Good
Br. No. 145-0105-0532	N. P. Railway	156' Steel Girder
Paint Condition: Good on rail-Fair structural steel		General Condition: Good
Remarks: Blast plate cover material gone, frame is intact. Piling and bracing timber span adjacent east side of steel span is bowed and span has shifted to the north side the width of the guard rail.		
Br. No. 145-0105-0561	Thompson River	426.5' Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: Rail post broken and tipped out 2" left side at Pier 2. Bevel bar broken out of deck expansion joint device at Bent 5. There is some rust along the truss bottom chord.		
Br. No. 145-0105-0729	Lynch Creek	83' Concrete T Beam
General Condition: Fair		
Remarks: Exterior beam haunches, span 2, pier 2, right beam lightly cracked and left beam has a heavy crack. Oil mat on deck extra thick at Bent 3 to fit present roadway grade and to correct a decided drop in the deck grade of span 2. The effect of the progressive shortening of the rail height is very noticeable.		
Br. No. 145-0105-0766	Boyer Creek	51.1' Concrete T Beam
General Condition: Good		
Remarks: One intermediate concrete rail post heavily cracked.		
Br. No. 145-0105-0826	Clark Fork	969.6' Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: One broken rail unit in the west approach span. End post traffic scarred.		

Br. No. 145-0105-0846 Clark Fork 455' Steel Truss
Paint Condition: Good General Condition: Good
Remarks: Portals and cross frames have been slightly bent. At Pier 2 there is
 approximately a 6" strip above the ice that shows surface erosion.
 Curb ends at Pier 2 are cracked.

Br. No. 145-0105-0922 Seepay Creek 31' Steel I Beam
Paint Condition: Good General Condition: Good
Remarks: Concrete under the south exterior beam, face of abutment, has spalled
 off the surface. Similar spalls under other beams have been patched.

Br. No. 145-0105-1003 Magpie Creek 39' Steel I Beam
Paint Condition: Good General Condition: Good
Remarks: One rail end split.

Field Maintenance Division No. 101 Lake County
Br. No. 124-0105-0007 N.P. Railway & Jocko River 332.4' Concrete T Beam
General Condition: Good

FEDERAL AID PRIMARY ROUTE 7

Field Maintenance Division No. 101

Ravalli County

Br. No. 141-0930-0129 East Fork Bitterroot River 140' Steel Beam

Paint Condition: Good

General Condition: Good

Remarks: Some traffic scratches and rock abrasions on rail, otherwise, paint good. Some surface spalls on concrete deck and at joints.

Br. No. 141-0930-0156 East Fork Bitterroot River 130' Continuous Steel Beam

Paint Condition: Good

General Condition: Good

Remarks: Deck rough textured, large aggregate shows, but is in good condition. Some edge chipping at junction of span slabs.

Br. No. 141-0930-0181 East Fork Bitterroot River 130' Continuous Steel Girder

Paint Condition: Good to Fair

General Condition: Good

Remarks: Substructure steel good. Rail paint fair. Curb edges deteriorating. Numerous small gouges in deck surface extending the length of the bridge. There are also a few large spalls of one square foot or more. Deck looks good on the underside.

Br. No. 141-0930-0259 Rye Creek

76' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Remarks: Oiled surface has some transverse cracks.

Br. No. 141-0930-0265 Bitterroot River

182' Pony Truss

Paint Condition: Good

General Condition: Good

Remarks: Several rail sections battered and sheared loose from brackets. Vertical truss hanger column angles twisted due to shearing of brackets from rail. Erosion on center pier below ice breaker nose angle is about 2" deep. Paint on lower part of truss end face plates is poor also areas adjacent to shoes. Some rail poor. Concrete deck good.

Br. No. 141-0930-0293 Fern Creek

209' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Remarks: Substructure good. Oil mat has some transverse cracks, but is intact.

Br. No. 141-0930-0299 Tincup Creek

57' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Remarks: Paint good except for one rail panel. Deck oiled surface intact. Shoulder fill sluffing out from curb end at northeast corner.

Br. No. 141-0930-0350 Rock Creek

95' Concrete T Beam

General Condition: Good

Remarks: At Bent 1, timber behind columns has rotted and the west half together with the roadway fill has run out. The opening behind the cap extends up to the base of oil mat. The opening is approximately 2'x5'x3.5'.

Br. No. 141-0930-0370 Lick Creek

76' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Remarks: Several rail posts tops and a few rail sections traffic scarred. One flared end terminal section lower rail broken. Oil mat has few holes and some alligator cracking.

Br. No. 141-0930-0376	Lost Horse Creek	137.3' Concrete T Beam
General Condition: Good		
Remarks: Corner of Bent 2 cross beam spalled off above the haunch on the up-stream side. Oil mat in good condition.		
Br. No. 141-0930-0399	Camas Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Part of one rail post split off and one rail traffic scarred. Sub-structure good. Oil mat on deck good.		
Br. No. 141-0930-0418	Gold Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: One broken stringer, Number 6 from west, third span from south, diagonal break across the base. Some rails and posts traffic scarred. North-east wing rail section gone. Deck oil mat has several chuck holes and some cracking, otherwise, intact.		
Br. No. 141-0930-0437	Bitterroot River	300' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Deck good. No oiled surface.		
Br. No. 141-0930-0451	Skalkaho Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Two rail posts split. Three post replaced with laminated posts made up of 2"x8" plank. Substructure looks good. Oiled surface is intact.		
Br. No. 141-0930-0486	Corvallis Creek	36' Concrete T Beam
General Condition: Good		
Br. No. 141-0930-0495	Bitterroot River	392' Continuous Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: Bent 3, Portal bent. Light deterioration of surface and end of Bent 2 coping, downstream, left corner Bent 3 at bearing seat and a few places along the curb. Curb face part of stationary plate of south expansion joint, right side, has been broken off. Concrete deck surface good.		
Br. No. 141-0930-0500	Irrigation Canal	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Grouted riprap breaking up. Oiled surface patched, good condition.		
Br. No. 141-0930-0503	Blodgett Creek(Signed Blodgett)	49' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface good.		
Br. No. 141-0930-0508	Sheafman Creek	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface good.		
Br. No. 141-0930-0546	Mill Creek	88' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Grouted riprap south side is breaking up.		

Br. No. 141-0930-0571	South Fork Bear Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Grouted riprap south side breaking up. None on north side. Oiled surface good.		
Br. No. 141-0930-0583	North Fork Bear Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Grouted riprap is undercut at end bents. Oiled surface good.		
Br. No. 141-0930-0597	Sweathouse Creek	81' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Grouted riprap breaking up. Four stringers of center span and two stringers of the north span, east side, have bolts with large washers at center of stringers up through deck. Could not see if stringers were checked or cracked. This bridge has a new plant mix surface and bolts may have been used to tighten deck to stringers. Plant mix surface good.		
Br. No. 141-0930-0616	Big Creek	114' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Riprap broken and at highwater creek washes against Bent 1 piles and under edge of backing plank. New plant mix surface on deck.		
Br. No. 141-0930-0651	McCalla Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: New plant mix surface on deck.		
Br. No. 141-0930-0661	McCalla Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Water undercutting grouted riprap. New plant mix surface on deck.		
Br. No. 141-0930-0662	Kootenai Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Part of grouted riprap at Bent 1 is washed out. Deck has new plant mix surface.		
Field Maintenance Division No. 101		Missoula County
Br. No. 132-0930-0062	Lolo Creek	140' Concrete T Beam
General Condition: Poor		
Remarks: On the north side of Bent 4 (from south) the concrete at the face and top of cap has spalled off under all three beam haunches and the re-steel is exposed due to settlement of west side of the Bent. The two west beam haunches are broken and have no support from the cap. The east beam haunch is cracked but has some support. Steel beam bolsters and plates have been set in on Bent 4 under the end diaphragms of spans 3 and 4 to support the span ends. The diaphragm haunch, span 4, at junction with west beam is cracked. The south end of span 3 at Bent 3 has shifted 2" west. Southwest end post and rail are broken off. Tops of Span 3 rail posts on west side are broken. The settlement is reflected in the grade and alignment of the rails. Deck oiled surface looks good.		
Br. No. 132-0930-0135	Bitterroot River	381' Steel Truss
Paint Condition: Fair		General Condition: Good
Remarks: Portal sway braces have been hit and slightly bent. Oiled surface extends to approximately 1.5' of the curb. Concrete surface in this area spalled. Some chipping out of concrete surface at deck joints.		

Oiled surface in general in good condition. Lattice type rail gone from southwest side of west approach span and has been replaced with steel beam type rail. Expansion rockers of east truss span in extreme expansion position and tight against the nuts (approximately 50°F.).

Br. No. 132-0930-0174 Clark Fork & C.M.ST.P.&P. R.R. 972' Riveted Plate Girder
Remarks: Under contract - Let 9-27-61 - Higgins Avenue Bridge

Federal Aid Primary Route 7 Orange Street Spur

Br. No. 132-0930-0012 C.M.ST.P.&P. R.R. 208.5' Concrete T Beam
Paint Condition: Fair General Condition: Good

Remarks: Substructure and under side of deck good. Ditch between north track and adjacent bent is an unloading area and ditch is filled with discarded packing materials, wood and cardboard. Fires have been built against the east and center columns of bent. Surface mortar worn from deck and there are a few small pot holes, otherwise, deck in good condition. Aluminum coat of paint wearing off exposing the prime coat.

Federal Aid Primary Route 7 Orange Street Spur

Br. No. 132-0930-0013 Clark Fork 503.2' Deck Truss
Paint Condition: Good-Structural Steel; Fair on Rail General Condition: Good
Remarks: Substructure and under side of deck good. Deck not oil surfaced. Surface mortar wearing off exposing large aggregate. There are a few oil patched areas and some large spalled surface areas. Deck good. Aluminum coat of paint wearing rail, exposing the prime coat.

Federal Aid Primary Route 7 Orange Street Spur

Br. No. 132-0930-0019 N. P. Railway Underpass
Paint Condition: Fair General Condition: Good
Remarks: Structure mounted signs: "Turn Lights On - Speed 15 M.P.H.", need repainting. Some sidewalk curb and retaining wall top surfaces are deteriorating. The 40' of pipe hand rail previously reported gone, has not been replaced. This rail is mounted on the left retaining wall and is for pedestrian inclined walk to underpass. Concrete approach and underpass concrete pavements are not oil surfaced. Coarse aggregate is exposed due to wear. There are a number of various sized pot holes and large and small spalled surface areas.

Federal Aid Primary Route 7 Madison Avenue Spur

Br. No. 132-0930-0012 Clark Fork & C.M.ST.P.&P. R.R. 551.6' Steel Plate Girder
Paint Condition: Good General Condition: Good
Remarks: Checked one set of overhead roadway signs. South side of structure vertical clearance is 17' 4".

FEDERAL AID PRIMARY ROUTE 8

Field Maintenance Division No. 101

Powell County

Br. No. 139-0120-0062 Little Blackfoot River & N. P. Railroad 462' Steel Girder

Paint Condition: Good

General Condition: Good

Remarks: Shoulder at southwest curb end sluffing out. At northeast curb end, edge of guard angle, there is a small hole in the oil mat where drainage enters and runs down behind the back wall.

Br. No. 139-0120-0118 Little Blackfoot River 107.3' Concrete T Beam

General Condition: Fair

Remarks: Beam haunches, east end of Span 2, are cracked and large pieces of concrete have spalled off. North end of west pier coping is crazed and corner has disintegrated. Pier 3 has settled approximately 4" on the right side. The down stream leg of this pier is eroding at the water line. Concrete spalled off curb for one rail panel length exposing one line of re-steel. At junction of Spans 1 and 2 from west, the center and south diaphragms have been bolstered up with short lengths of 12"x12" timbers set on top of cap.

Br. No. 139-0120-0131 Little Blackfoot River 95' Concrete T Beam

General Condition: Good

Remarks: Edge of coping, right side of Bent 3, spalling.

Br. No. 139-0120-0221 Little Blackfoot River 59' Concrete T Beam

General Condition: Good

Remarks: Heavy disintegration of curb faces and outside deck edges, especially on the south side. Re-steel exposed. Southeast end post top cut off and one intermediate post cracked vertically. Center pier eroding 2" to 3".

Field Maintenance Division No. 301

Lewis and Clark County

Br. No. 125-0120-0092 Ten Mile Creek

102.2' Concrete T Beam

General Condition: Good

Remarks: End of southwest wing wall spalling and re-steel exposed. South side outside curb face spalling for one rail panel length. Hair cracks in girder exterior faces.

Br. No. 125-0120-0178 I-15(Colonial Club Interchange) 260.5' Steel Girder

Paint Condition: Good

General Condition: Good

Remarks: FAP Rte. 3 - #125-0910-0020

Br. No. 125-0120-0178P I-15 Same as above.

Br. No. 125-0120-0202 G. N. Railway

148.8' Concrete T Beam

General Condition: Good

Remarks: Near center of structure on south side one intermediate rail post is cracked and both rails broken. Sidewalk ends, north and south side at expansion joint have broken ends forming open holes in walk.

Br. No. 125-0120-0203 N. P. Railway

211.5' Concrete T Beam

General Condition: Good

Remarks: Corner off northwest end post exposing re-steel. Some deteriorating of walk, curb face and ends. Underside of deck and girders are good. Oiled surface on deck in good condition.

Br. No. 125-0120-0216 Frickly Pear Creek 65.2' Concrete T Beam
General Condition: Good
Remarks: Oiled surface on deck in good condition.

Field Maintenance Division No. 201 Broadwater County
Br. No. 104-0120-0203 Missouri River 500' Continuous Plate Girder
Paint Condition: Good General Condition: Good
Remarks: Tops of a number of rail posts are traffic scarred. Oiled surface on deck in good condition. Southwest rocker at end bent partially covered with dirt.

Br. No. 104-2870-0229 Irrigation Canal 21.5' Concrete Slab
General Condition: Good
Remarks: Oiled surface on deck in good condition.

Br. No. 104-2870-0241 Deep Creek 65.5' Concrete T Beam
General Condition: Good
Remarks: Up stream side of Pier 3 is eroded. Face of column extends 15" up to bottom of haunch. This section is cracking above the eroded portion and will eventually spall off. Concrete at top of eroded area tests solid 2 1/2" in from column face. Due to ice cover could see only top edge of eroded area. Oiled surface on deck in good condition.

Br. No. 104-2870-0246 Deep Creek Overflow 22' Concrete Slab
General Condition: Good
Remarks: Oiled surface on deck in good condition.

Br. No. 104-2870-0313 Six Mile Creek 21.7' Concrete Slab
General Condition: Good
Remarks: Oiled surface on deck is in good condition.

Br. No. 104-2870-0321 N. P. Railway 385.5' Concrete T Beam
Paint Condition: Good General Condition: Good
Remarks: Drainage cutting in around end posts and curbs. Oiled surface on deck is in good condition.

Br. No. 104-2870-0323 Missouri River 689.5' Steel Girder
Paint Condition: Good General Condition: Good
Remarks: Oiled surface treatment on deck is in good condition.

Field Maintenance Division No. 301 Lewis and Clark County
Federal Aid Primary Route 8 Spur in Helena
Br. No. 125-0120-0002 G. N. Railway 206' Prestressed Concrete T Beam
Remarks: Under contract - Let 5-24-61

Br. No. 125-0120-0002P G. N. Railway 205.6' Concrete T Beam
General Condition: Good
Remarks: One intermediate concrete rail post and two rail units, south side near center, are broken. At expansion joint, near center of bridge, the outside corners of both sidewalks are broken off forming open hole in the walks that should be repaired. Cracks below rail post bases at intermediate bents. Deck surface in good condition and underside of structure looks good.

FEDERAL AID PRIMARY ROUTE 9

Field Maintenance Division No. 301

Lewis and Clark County

Br. No. 225-2870-0001 Little Prickly Pear Creek 151.5' Concrete T Beam

General Condition: Good

Remarks: At south end, second span from south, there are cracks in the exterior girder haunches extending up from edge of bearing plates to joint between spans.

Br. No. 225-2870-0040 Rock Creek

75' Concrete T Beam

General Condition: Good

Remarks: At center pier, west beam, north span concrete at inside face of beam haunch has spalled off exposing one bar of reinforcing steel.

Br. No. 225-2870-0155 Dearborn River

294' Steel Riveted Plate Girder

Remarks: Under contract - Let 12-20-61

Br. No. 225-2870-0263 Flat Creek

57' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 225-2870-0343 Stockpass

38' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Remarks: One rail end post split in two.

Br. No. 225-2870-0353 Dry Creek

38' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Remarks: Bridge signs broken off.

Br. No. 225-2870-0406 South Fork Sun River

41' Concrete T Beam

General Condition: Good

Br. No. 225-2870-0407 Slough

57' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 225-2870-0457 North Fork Sun River

315' Steel Girder

Paint Condition: Good

General Condition: Good

Remarks: Fill at southwest end post is sluffing out, starting at face of curb. Bridge signs need repainting.

Field Maintenance Division No. 301

Teton County

Br. No. 250-2870-0002 Floweree Canal

93' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Remarks: The south half of the fifth stringer in from the west, center span, has been repaired with a steel plate bolted to the side. At the center a 10" steel beam bridges six stringers and is pulled up against the stringers with through bolts to the deck. A similar beam section bridging four stringers is located against the cap of the south center bent.

Br. No. 250-2870-0036 U.S.R.S. Canal

100' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 250-2870-0155	Dry Wash	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Bridge signs need repainting.		
Br. No. 250-2870-0184	Deep Creek	150' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Third stringer from east of the third span from north has been replaced with a 12" x 12" timber blocked up from the caps. Signs need re-painting.		
Br. No. 250-2870-0203	Teton River	200' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: No bridge signs.		

FEDERAL AID PRIMARY ROUTE 10

Field Maintenance Division No. 301

Cascade County

Br. No. 107-0870-0005 Missouri River & US 87 Bypass 965.4' Concrete Arch

General Condition: Good

Remarks: Substructure and deck in good condition. Oiled surface on deck is in good condition. Old sidewalk and curb south side of bridge replaced. New walk and curb in good condition. Curb on north side is disintegrating and sidewalk surface is spalling. Railing concrete surfaces are rough due to weathering. Railing still substantial.

Br. No. 107-0870-0008

G. N. Railway

Underpass

Paint Condition: Good

General Condition: Good

Remarks: Due to volume and speed of traffic, Saturday, P.M., November 18, 1961 did not check vertical clearances. Should be checked with two men and using a more easily adjustable rod. There are no clearances marked on structure.

Br. No. 107-0870-0015

G. N. Railway

Underpass

Paint Condition: Fair to Good

General Condition: Good

Br. No. 107-0870-0016

C.M.ST.P.&P. R.R.

Underpass

Paint Condition: Good

General Condition: Good

Br. No. 107-0870-0021

Missouri River

1130' Concrete Arch

General Condition: Good

Remarks: Considerable cracking and spalling of concrete in the base of the east rail. Steel exposed in a few places. Rail posts, east side, that support pipe standards for lighting or communication lines, are cracked. Pier nose and heel coping shows some wear. Six concrete pickets are gone from one rail panel and the opening is boarded up with 2"x6" plank. A few rail units are short one or two pickets each. Bridge in general in good condition. Fill at southwest end post and 1.5' in towards roadway and above pipeline has sluffed out.

Field Maintenance Division No. 301

Chouteau County

Br. No. 108-0870-0045 Dry Course

76' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Remarks: One broken stringer, center of third span from south. Break extends from center back to cap.

Br. No. 108-0870-0300

G. N. Railway

126' Concrete T Beam

General Condition: Good

Br. No. 108-0870-0358

Marias River & G.N. Ry.

1150.5' Continuous Steel Truss

Paint Condition: Good

General Condition: Good

Remarks: Large spall on river side of third pier from south.

Br. No. 108-0870-0480

Spring Coulee

114' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Br. No. 108-0870-0509

Dry Course

25' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Br. No. 108-0870-0530	Dry Course	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Warp in south side rail.		
Br. No. 108-0870-0540	Dry Course	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 108-0870-0577	G. N. Railway	95' Treated Timber Trestle
General Condition: Good		
Br. No. 108-0870-0598	Dry Course	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 108-0870-0669	Big Sandy Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 108-0870-0689	Dry Course	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: One pile of second bent from north only half under the cap. Bearing increased by a 4" x 4" piece bolted to pile.		
Field Maintenance Division No. 302		Hill County
Br. No. 121-0870-0003	Box Elder Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Shoulder sloughing out at two end rail wing panels. Rail of one panel splintered. One broken stringer in each of two spans has been reinforced with an additional stringer bolted to it. Some stringers lack full bearing on the caps.		
Br. No. 121-0870-0102	Gravelly Coulee	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 121-0870-0180	Beaver Creek	103.5' Steel I Beam
Paint Condition: Fair		General Condition: Good
Remarks: Pier surfaces eroded at water line. Some chipping of concrete under beam seats.		
Federal Aid Primary Route 10 Spur in Great Falls		
Field Maintenance Division No. 301		Cascade County
Br. No. 107-0870-0018	Missouri River	1125.7' Riveted Plate Girder
General Condition: New four lane structure.		
Remarks: Old bridge removed. Construction of new bridge nearing completion. Construction items complete except for field painting of structural steel and steel bridge rail. Roadway approaches to structure not yet complete. (Note: East lane opened to traffic early in December. Temporary approach connections.)		

FEDERAL AID PRIMARY ROUTE 11

Field Maintenance Division No. 202		Park County
Br. No. 134-0890-0002	Yellowstone River	408.8' Steel Truss
Paint Condition:	Good	General Condition: Good
Remarks: Paint is good; there are scattered spots that could be touched up.		
Br. No. 134-0890-0204	Yellowstone River	450' Steel Plate Girder
Paint Condition:	Good	General Condition: Good
Br. No. 134-0890-0241	Big Creek	90' Continuous Concrete T Beam
Paint Condition:	Good	General Condition: Good
Remarks: On new alignment.		
Br. No. 134-0890-0262	Hay Wagon Pass	57' Treated Timber Trestle
Paint Condition:	Good	General Condition: Good
Br. No. 134-0890-0272	Six Mile Creek	31' Steel I Beam
Paint Condition:	Good	General Condition: Good
Br. No. 134-0890-0283	Emigrant Creek	31' Steel I Beam
Paint Condition:	Good	General Condition: Good
Remarks: Concrete at top and ends of two wing walls is disintegrating.		
Br. No. 134-0890-0364	Mill Creek	67' Steel I Beam
Paint Condition:	Good	General Condition: Good
Remarks: Concrete has spalled off under exterior beams at end bents.		
Br. No. 134-0890-0444	Pine Creek	20.8' Steel I Beam
Paint Condition:	Good	General Condition: Good
Remarks: West rail and posts are loose and one panel of east rail is broken.		
Br. No. 134-0890-0514	Yellowstone River	284.9' Reinforced Concrete Rib Arch
General Condition:	Good	
Remarks: End post at northeast corner hit and some concrete around the post pocket is broken off. Rail damage has been repaired. Some erosion of piers at water line.		
Br. No. 134-0890-0548	I-90-South Interchange	Underpass
Remarks: FAP Rte. 2 - #134-0100-0084 - Under contract		
Br. No. 134-0890-0548P	I-90-South Interchange	Underpass
Remarks: #0548 and 0548P one structure. - Under contract		
Br. No. 134-0890-0549	I-90-South Interchange	Underpass
Remarks: FAP Rte. 2 - #134-0100-0084P - Under contract		
Br. No. 134-0890-0549P	I-90-South Interchange	Underpass
Remarks: #0549 and 0549P one structure. - Under contract		
Br. No. 134-0890-0577	Yellowstone River	500' Cantilever Steel Girder
Paint Condition:	Good	General Condition: Good
Br. No. 134-0890-0597	I-90-East Interchange	279' Continuous Steel Girder
Remarks: FAP Rte. 2 - #134-0100-0133 - Under contract		

Br. No. 134-0890-0623 I-90-Mission Interchange 209.5' Prestressed Concrete Beam
 Remarks: FAP Rte. 2 - #134-0100-0159 - Under contract

Br. No. 134-0890-0628 N. P. Railway 128' Concrete T Beam
 Paint Condition: Good General Condition: Good

Br. No. 134-0890-0637 Yellowstone River 390' Steel Girder Deck Truss
 Paint Condition: Good General Condition: Good

Br. No. 134-0890-0654 Drainage 60' Concrete Slab
 General Condition: Good
 Remarks: West side curb face disintegrating; less on east curb.

Br. No. 134-0890-0699 Willow Creek 38' Treated Timber Trestle
 Paint Condition: Good General Condition: Good
 Remarks: Grouted riprap starting to break up.

Br. No. 134-0890-0724 Drainage 38' Treated Timber Trestle
 Paint Condition: Good General Condition: Good
 Remarks: One broken stringer repaired with steel plates with bolts up through deck.

Br. No. 134-0890-0734 Shields River 140.7' Steel Pony Truss
 Paint Condition: Good General Condition: Good
 Remarks: Curbs, corner posts, rail post brackets, and tops of pier surfaces are deteriorating.

Br. No. 134-0890-0744 Rock Creek 59' Steel I Beam
 Paint Condition: Good General Condition: Good
 Remarks: Paint on exterior face of the south beam is poor, otherwise beam paint is good. Concrete surface of pier top and curb faces are deteriorating.

Br. No. 134-0890-0788 Shields River 128.1' Steel Girder
 Paint Condition: Good General Condition: Good

Br. No. 134-0890-0866 Flathead Creek 55' Steel I Beam
 Paint Condition: Fair to Poor General Condition: Good
 Remarks: Paint on exterior face of outside beams is poor, otherwise, metal paint is fair.

Field Maintenance Division No. 202 Meagher County
 Br. No. 130-0890-0058 Lost Creek 38' Treated Timber Trestle
 Paint Condition: Good General Condition: Good
 Remarks: No bridge signs.

Br. No. 130-0890-0065 South Fork Sixteen Mile Creek 38' Treated Timber Trestle
 Paint Condition: Good General Condition: Good
 Remarks: No bridge signs.

Br. No. 130-0890-0071 C.M.ST.P.&P.R.R. & 245' Continuous Steel Girder
 Paint Condition: Good Sixteen Mile Creek General Condition: Good
 Remarks: Name plates are gone.

Br. No. 130-0890-0143 Paint Condition: Good	So. Fork Smith River	57' Treated Timber Trestle General Condition: Good
Br. No. 130-0890-0152 Paint Condition: Good	So. Fork Smith River	57' Treated Timber Trestle General Condition: Good
Br. No. 130-0890-0197 Paint Condition: Good	So. Fork Smith River	76' Treated Timber Trestle General Condition: Good
Br. No. 130-0890-0314 Paint Condition: Good	No. Fork Smith Creek	38' Treated Timber Trestle General Condition: Good
Br. No. 130-0890-0490 Paint Condition: Good Remarks: South side wing rails pulled away and split corner posts.	Sheep Creek	69' Treated Timber Trestle General Condition: Good
Field Maintenance Division No. 301		
Br. No. 107-0890-0063 General Condition: Good	Belt Creek	Cascade County 100' Concrete T Beam
Br. No. 107-0890-0118 General Condition: Good	Belt Creek	100' Concrete T Beam
Br. No. 107-0890-0137 General Condition: Good Remarks: Piers surfaces eroded at water line. Some girder haunches are cracked.	Belt Creek	83' Concrete T Beam
Br. No. 107-0890-0369 Paint Condition: Poor Remarks: North bent wall cracked vertically and truss shoes are covered with dirt and gravel. One broken stringer in the third deck panel from south end and one broken stringer in second deck panel from north.	Belt Creek	105' Steel Pony Truss General Condition: Good
Br. No. 107-0890-0383 Paint Condition: Steel-Fair; Wood Rail-Poor Remarks: Deck has been resurfaced since previous report and is in good condition. One rail broken for one panel length.	Belt Creek	105' Steel Pony Truss General Condition: Good
Br. No. 107-0890-0434 Paint Condition: Good	Otter Creek	75' Treated Timber Trestle General Condition: Good
Br. No. 107-0890-0438 Paint Condition: Good Remarks: Vertical crack in cross beam second bent from west. Crack extends through beam. Located near haunch at left column. Reflectors at all four corners. No number on bridge.	Belt Creek	156' Concrete T Beam General Condition: Good
Br. No. 107-0890-0550 General Condition: Good Remarks: Southeast end post chipped and cracked at base. One intermediate rail post, south side, cracked. Reflectors at all four corners.	Box Elder Creek	40' Concrete T Beam
Br. No. 107-0890-0584 Paint Condition: Good Remarks: Minor chipped concrete at joints of railroad track slab.	G. N. Railway	Underpass General Condition: Good

FEDERAL AID PRIMARY ROUTE 12

Field Maintenance Division No. 202

Gallatin County

Br. No. 116-1910-0044

South Fork Madison River

General Condition: Good

60' Reinforced Concrete Girder

FEDERAL AID PRIMARY ROUTE 13

Field Maintenance Division No. 202

Madison County

Br. No. 229-2870-0080

Madison River

259.5' Prestressed Concrete Beam

Remarks: Under contract. Road closed by snow. Barricaded and signed about 0.6 mile from bridge.

Br. No. 229-2870-0150

Papoose Creek

25' Concrete T Beam

General Condition: Good

Remarks: Some crazing of rail posts. Light cracks in girders and back walls. Oiled surface on deck is in good condition.

Br. No. 229-2870-0167

Squaw Creek

25' Concrete T Beam

General Condition: Good

Remarks: Some crazing of rail posts and slab edges. Underside closed with snow and ice. Oiled surface on deck is in good condition.

Br. No. 229-2870-0308

Indian Creek

83' Concrete T Beam

General Condition: Good

Remarks: Curb cracking at east side junction of spans 2 and 3. Hairline cracking in girders, pier caps, and in bent back walls. Oiled surface on deck is in good condition.

Br. No. 229-2870-0481

O'Dell Creek

122' Concrete T Beam

General Condition: Good

Remarks: Light crazing of end post surfaces. Hairline cracks in girders and back walls. Pier 2 eroded at nose and heel approximately 4" deep exposing re-steel. End spans, girder haunches on the piers are cracked. No oil surface treatment on deck. Concrete surface shows some wear but is in good condition.

Br. No. 229-2870-0483

Madison River Overflow

107' Concrete T Beam

General Condition: Good

Remarks: One lower rail on the west side is gone and one post is cracked. End posts surfaces crazing and cracking, especially the southwest post. Some cracks in girders and back walls previously reported could not be checked as underside of structure was snow and ice filled. No oiled surface treatment on deck. Concrete surface in good condition.

Br. No. 229-2870-0484

Madison River Overflow

81' Concrete T Beam

General Condition: Good

Remarks: One rail post cracked at curb. Light crazing of rail end posts. Underside of structure almost filled with snow and ice so that cracks in girders and back walls, and so forth could not be checked. However, where it was possible to check girders and back walls the cracking was generally the hairline type. No oiled surface treatment on deck. Concrete surface in good condition.

Br. No. 229-2870-0485

Madison River Overflow

107' Concrete T Beam

General Condition: Good

Remarks: End post surfaces crazed or cracked. Hairline cracks in girders. Spalling of concrete on downstream side of Pier 3 as previously reported, could not be checked as river is ice covered. No oiled surface on deck. Concrete deck surface in good condition.

Br. No. 229-2870-0486 Madison River 289.7' Thru Steel Truss
Paint Condition: Good to Fair
Remarks: Paint wearing off truss batter column face plates. Some scattered rust and flaked spots. No vertical clearance signs. End post surfaces heavily checked. Concrete at curb ends above center pier have split off. Ice is 42" below bottom truss chord. No oiled surface on deck. Concrete deck in good condition.

Br. No. 229-2875-0653 Warm Springs Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Fill is starting to slough out from behind the backing plank at the south bent. Oiled surface on the deck is in good condition.

Br. No. 229-2875-0680 Drainage 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Two sets of x-bridging removed where broken stringer has been spliced. Oiled surface on deck is in good condition.

Br. No. 229-2875-0736 Dry Hollow Creek 76' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: One rail end split. Oiled surface on deck is in good condition.

Br. No. 229-2875-0752 South Willow Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Two rail posts split. Traffic scars at southwest end of rail.

Field Maintenance Division No. 202 Gallatin County
Br. No. 216-2875-0016 N.P. Ry. & C.M.ST.P.&P.R.R. 370' Steel Girder
Paint Condition: Good General Condition: Good
Remarks: Light edge chipping of deck edges at contraction joints. Light cracks west side of Bents 6, 7, and 8 caps. Rail posts are set in pockets and were grouted in following setting of rail. At some posts the grout has cracked at the corners and the freezing of moisture entering the pockets has caused the sections of grout to pop up above the curb surface. These post pockets should be regouted.

Br. No. 216-2875-0022 Jefferson River 394.5' Thru Steel Truss
Paint Condition: Good to Fair
Remarks: Rust spots on truss batter column face plates. No vertical clearance signs. No load limit signs. The lower angle at north portal has been bent and at the south portal it has been broken. South side rockers are in the contraction position against the anchor bolt nuts. There is a vertical crack in the center pier and one anchor bolt missing from shoe at second pier from north. One rail unit and top of post cracked, west side, north approach span.

FEDERAL AID PRIMARY ROUTE 14

Field Maintenance Division No. 201
Br. No. 104-0120-0011 Montana Canal Broadwater County
Paint Condition: Good 25' Treated Timber Trestle
General Condition: Good
Remarks: Fourth stringer in from north side broken, the fifth stringer has a diagonal crack along base starting on cap and extending out 5' and a central crack is developing above it. East rail ends battered. Oiled surface on deck has a few cracks but is intact.

Br. No. 104-0120-0111 Deep Creek 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Oiled surface on deck is in good condition.

Field Maintenance Division No. 202
Br. No. 104-0120-0119 Deep Creek Broadwater County
Paint Condition: Fair 38' Treated Timber Trestle
General Condition: Good
Remarks: Rails traffic scarred. Oiled surface on deck in good condition. At northwest curb end there is a hole in the oil mat where drainage runs down behind the backing plank.

Br. No. 104-0120-0151 Deep Creek 39' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: One rightside top rail split. Oiled surface on deck in good condition.

Br. No. 104-0120-0173 Deep Creek 39' Treated Timber Trestle
Paint Condition: Fair General Condition: Good
Remarks: Oiled surface on deck in good condition.

Field Maintenance Division No. 202
Br. No. 130-0120-0257 Four Mile Creek Meagher County
Paint Condition: Good 25' Treated Timber Trestle
General Condition: Good

Br. No. 130-0120-0429 Flagstaff Creek 76' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 130-0120-0450 Cooper Creek 76' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: One broken stringer in third span from west. Break starts over cap and extends back. (This is the same stringer previously reported cracked).

Br. No. 130-0120-0463 Drainage 25' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 130-0120-0530 North Fork Musselshell River 95' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Field Maintenance Division No. 403
Br. No. 154-0120-0051 Daisy Dean Creek Wheatland County
Paint Condition: Good 57' Treated Timber Trestle
General Condition: Good
Remarks: One broken stringer, west span, south side.

Br. No. 154-0120-0077 Drainage (Signed Willis Coulee) 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 154-0120-0109	Haymaker Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 154-0120-0134	Willis Coulee (Not Signed)	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 154-0120-0164	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: A strip of oil mat along the north curb is breaking up and a section of deck is exposed.		
Br. No. 154-0120-0184	Hopley Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 154-0120-0202	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 154-0120-0232	C.M.ST.P.&P. R.R.	203.9' Continuous Steel Beam
Paint Condition: Good		General Condition: Good
Remarks: At southeast end of curb and walk, fill and oil mat has been washed out from 2' inside end post down and under back wall haunch. This hole is about 5' deep. Grouted riprap north side of Bent north of tracks starting to break up.		
Br. No. 154-0120-0274	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 154-0120-0280	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Rail slightly crooked.		
Br. No. 154-0120-0293	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 154-0120-0410	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Berm starting to go under the backing plank.		
Br. No. 154-0120-0427	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 501		
Br. No. 119-0120-0097	Drainage	Golden Valley County
Paint Condition: Good		38' Treated Timber Trestle
		General Condition: Good
Br. No. 119-0120-0110	Careless Creek	114' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 119-0120-0133	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 119-0120-0171	Nine Mile Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 119-0120-0015 Remarks: Not inspected.	G. N. Railway	Underpass
Br. No. 119-0120-0178 Paint Condition: Good	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 119-0120-0206 Paint Condition: Good	Five Mile Creek	76' Treated Timber Trestle General Condition: Good
Br. No. 119-0120-0218 Paint Condition: Good	Drainage	95' Treated Timber Trestle General Condition: Good
Br. No. 119-0120-0249 Paint Condition: Good	Twin Coulee	57' Treated Timber Trestle General Condition: Good
Br. No. 119-0120-0250 Paint Condition: Good	Twin Coulee	57' Treated Timber Trestle General Condition: Good
Br. No. 119-0120-0260 Paint Condition: Good	Drainage	76' Treated Timber Trestle General Condition: Good
Field Maintenance Division No. 501		Musselshell County
Br. No. 133-0120-0007 Paint Condition: Good	Dean Creek	76' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0030 Paint Condition: Good	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0097 Paint Condition: Good	Currant Creek	95' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0141 Paint Condition: Good	Pole Creek (Signed Horsethief Creek)	75' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0229 Paint Condition: Good	Willow Creek	76' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0238 Paint Condition: Good	Musselshell River	76' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0246 Paint Condition: Good Remarks: One reflectorized sign gone.	Musselshell River	76' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0257 Paint Condition: Good	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0273 Paint Condition: Good	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0289 Paint Condition: Good	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 133-0120-0311 Paint Condition: Good	Drainage	76' Treated Timber Trestle General Condition: Good

Br. No. 133-0120-0323	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: One sway brace broken.		
Br. No. 133-0120-0343	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0371	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0386	Irrigation Canal	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0396	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0402	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0413	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0428	Drainage	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0447	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0483	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0498	Old River Channel	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0120-0522	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Fair
Remarks: A lot of blocking and raising has been done underneath. Cap Bent has a curve in it.		
Br. No. 133-0120-0535	Drainage	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: One riprap section deteriorated about 20 percent.		
Br. No. 133-0120-0554	Musselshell River	224' Continuous Steel Girder
Paint Condition: Fair		General Condition: Good
Remarks: Both Pier shafts have a crack about centerline of roadway from ground line to bottom of cap.		
Field Maintenance Division No. 502		Rosebud County
Br. No. 144-0120-0008	Drainage	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 144-0120-0023	Home Creek	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Br. No. 144-0120-0089 Paint Condition: Good	Home Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0094 Paint Condition: Good	Home Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0097 Paint Condition: Good	Home Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0099 Paint Condition: Good	Home Creek	38' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0128 Paint Condition: Good	Dry Wash (Muggins Creek)	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0166 Paint Condition: Good	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0175 Paint Condition: Good	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0202 Paint Condition: Good Remarks: Corner posts have good sized cracks in them.	Dry Wash	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0222 Paint Condition: Good	Drainage	25' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0287 Paint Condition: Poor	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0310 Paint Condition: Poor	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0318 Paint Condition: Fair Remarks: Good size cracks in corner posts.	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0327 Paint Condition: Poor Remarks: Fairly good size cracks showing up in corner posts.	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0366 Paint Condition: Fair	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0382 Paint Condition: Fair	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0392 Paint Condition: Good	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0435 Paint Condition: Poor	Horse Creek	100' Treated Timber Trestle General Condition: Good

Br. No. 144-0120-0450 Paint Condition: Poor	Anderson Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0459 Paint Condition: Poor Remarks: One rail split slightly.	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0501 Paint Condition: Poor	Porcupine Creek	122' Steel Girder General Condition: Good
Br. No. 144-0120-0504 Paint Condition: Fair	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0526 Paint Condition: Poor Remarks: Small section of rail is battered up.	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0552 Paint Condition: Poor	Drainage	95' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0575 Paint Condition: Fair	McGraws Coulee	38' Treated Timber Trestle General Condition: Good
Br. No. 144-0120-0631 Yellowstone River, C.M. ST.P. & P. Railroad Paint Condition: Good		825.3' Steel Girder General Condition: Good

FEDERAL AID PRIMARY ROUTE 15

Field Maintenance Division No. 301

Br. No. 107-0870-0002 Otter Creek
Paint Condition: Good

Cascade County

123' Prestressed Concrete Beam
General Condition: GoodBr. No. 107-0870-0005 Otter Creek
Paint Condition: Good118' Prestressed Concrete Beam
General Condition: GoodBr. No. 107-0870-0008 Otter Creek
Paint Condition: Good118' Prestressed Concrete Beam
General Condition: Good

Remarks: On the north side, east end, the end rail post has been sheared off.
The next post west has been bent over to top of curb and the first rail section is off. All rail posts of the next six rail sections are slightly bent to the west. The bridge marker for the northeast end post is on the road at the northwest curb end. No reflectors.

Br. No. 107-0870-0015 Otter Creek
Paint Condition: Good101.5' Prestressed Concrete Beam
General Condition: GoodBr. No. 107-0870-0019 Otter Creek
Paint Condition: Good101.5' Prestressed Concrete Beam
General Condition: GoodBr. No. 107-0870-0022 Otter Creek
Paint Condition: Good91.5' Prestressed Concrete Beam
General Condition: GoodBr. No. 107-0870-0025 Otter Creek
Paint Condition: Good91.5' Prestressed Concrete Beam
General Condition: GoodBr. No. 107-0870-0030 Otter Creek
Paint Condition: Good101.5' Prestressed Concrete Beam
General Condition: GoodBr. No. 107-0870-0035 Otter Creek
Paint Condition: Good101.5' Prestressed Concrete Beam
General Condition: Good

Remarks: Northeast curb end chipped.

Field Maintenance Division No. 301

Br. No. 123-0870-0014 Otter Creek
Paint Condition: Good

Judith Basin County

81.5' Prestressed Concrete Beam
General Condition: Good

Remarks: New 1961. Bridge deck has not been sealed and chipped. Reflectors at four corners.

Br. No. 123-0870-0022 Otter Creek
Paint Condition: Good81.5' Prestressed Concrete Beam
General Condition: Good

Remarks: New 1961. Bridge deck has not been sealed and chipped. Reflectors at four corners.

Br. No. 123-0870-0037 Otter Creek
Paint Condition: Good81.5' Prestressed Concrete Beam
General Condition: Good

Remarks: New 1961. Bridge deck has not been sealed and chipped. Reflectors at four corners.

Br. No. 123-0870-0038 Otter Creek
Paint Condition: Poor76' Treated Timber Trestle
General Condition: Good

Remarks: No bridge signs. Reflectors at four corners.

Br. No. 123-0870-0043	Otter Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Northwest end rail post split. One stringer, fourth from south side, west end span, previously reported as split has been repaired. The break has been closed with metal straps. An 8"x8" shore has been set on each side of the break and wedged at top. The shores are loose, wedges need to be reset and shore toe nailed to stringer. Reflectors at four corners.		
Br. No. 123-0870-0148	McCarthy Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Reflectors at four corners.		
Br. No. 123-0870-0222	Fox Coulee	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Reflectors at four corners.		
Br. No. 123-0870-0238	Surprise Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Reflectors at four corners.		
Br. No. 123-0870-0247	Sun Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 123-0870-0278	Wolf Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Bridge sign west end broken off. One curb end at second bent from west, north side, split off.		
Br. No. 123-0870-0301	North Fork Skull Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 123-0870-0303	South Fork Skull Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 123-0870-0318	Coyote Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: At southeast corner curb end for one panel length is shattered. West end bridge marker is off and lying on the ground.		
Br. No. 123-0870-0329	Willow Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Bridge sign at east end broken.		
Br. No. 123-0870-0351	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 123-0870-0360	Sage Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 123-0870-0371	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Paint poor on two panels of south rail, otherwise, good.		

Br. No. 123-0870-0386	Dry Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 123-0870-0498	G. N. Railway	123' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: At the southeast bridge end, drainage off the structure has cut heavily into embankment slope. Cut starts 5' from bridge end and just inside roadway guard rail. At the northeast end there is a crack in the roadway starting 2' in from the face of the curb at the end of the deck and curving out around the first post of the roadway guard rail.		
Br. No. 123-0870-0511	Judith River	159' Concrete T Beam
General Condition: Good		
Remarks: Approximately two panel lengths of the face of the north rail curb has disintegrated and one line of reinforcing steel is exposed. Base of one rail post is cracked. The nose and heel of the east pier is disintegrating at the water line and the reinforcing steel is exposed. The next pier west has been repaired with a protective coping poured around the nose. The heel is disintegrating at the water line exposing some reinforcing steel.		
Br. No. 123-0870-0553	Ross Fork Creek	120.3' Concrete T Beam
General Condition: Good		
Remarks: Some spalling along deck edge for two rail panel lengths on the south side.		
Br. No. 123-0870-0559	Olson Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Signs on bridge spelled Olsen.		
Field Maintenance Division No. 403		Fergus County
Br. No. 114-0870-0050	Dry Coulee	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0052	Rock Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0075	Little Rock Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0081	King Coulee	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0096	Beaver Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0110	Cottonwood Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0151	C.M.St. P.&P. R.R.	165' Concrete T Beam
Paint Condition: None needed		General Condition: Good
Remarks: Track span slightly out of alignment ($\frac{1}{2}$ "). Expansion joint at this span looks like it is opened up a little more than necessary.		

Br. No. 114-0870-0179	Mill Ditch	25' Concrete T Beam
Paint Condition: None needed		General Condition: Good
Remarks: Minor spalling on edges in various spots. Water underneath, so this inspection was not very complete.		
Br. No. 114-0870-0192	Boyd Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0217	Boyd Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0311	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0363	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0393	Drainage	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0408	North Fork McDonald Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0421	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0429	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0433	Irrigation Reservoir	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0449	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0460	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0465	Drainage	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0472	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 114-0870-0480	South Fork McDonald Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 214-0200-0493	Charters Coulee	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 214-0200-0507	Gerdum Coulee	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 214-0200-0526	McDonald Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 214-0200-0554	Briggs Coulee	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 403		
Br. No. 235-0200-0220	Box Elder Creek	Petroleum County
Paint Condition: Good		184' Concrete T Beam
Remarks: Fence tied to rail.		General Condition: Good
Br. No. 235-0200-0345	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 235-0200-0350	Musselshell River	435.5' Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: Spalling on top edges of piers and ends of curbs. Many crossframes of steel have been hit and bent.		
Field Maintenance Division No. 403		
Br. No. 217-0200-0030	Drainage	Garfield County
Paint Condition: Good		114' Treated Timber Trestle
		General Condition: Good
Br. No. 217-0200-0040	Sage Hen Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0050	Dog Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0098	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0111	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0114	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0122	Calf Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0132	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0150	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0165	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0187	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0247	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0256	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 217-0200-0293	Dugout Coulee	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Cap on Bent 4 is developing a good sized crack.		
Br. No. 217-0200-0324	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0327	Drainage	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Cracked stringer, fourth in second span.		
Br. No. 217-0200-0338	Drainage	114' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0348	Drainage	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0357	Drainage	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0383	Drainage	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0387	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0403	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0415	Big Dry Creek	162' Steel Girder
Paint Condition: Wood-Good; Steel-Fair		General Condition: Good
Br. No. 217-0200-0422	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0439	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0464	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0477	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0491	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0501	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0519	Drainage	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0526	Drainage	114' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 217-0200-0537	Big Dry Creek	161' Steel Beam
Paint Condition: Fair		General Condition: Good
Remarks: Rockers are in expansion position at 5° below 0 at both ends of steel. Gap is closed between steel and timber.		
Br. No. 217-0200-0565	Vale Creek	63' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0591	Dry Wash	63' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0612	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0626	Drainage	63' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0637	Dry Wash	63' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0649	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0678	Big Dry Creek	396' Continuous Steel Beam
Paint Condition: Good		General Condition: Good
Remarks: One set of rockers at Bent 3, 5, and 8 are in expansion position at 10° below 0. Nosing timbers on Bent 6 are damaged.		
Br. No. 217-0200-0689	L - S Creek	125' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 217-0200-0713	Drainage	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 217-0200-0724	Drainage	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 217-0200-0739	Drainage	25' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 217-0200-0741	Drainage	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 217-0200-0759	Drainage	101' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 217-0200-0770	Drainage	93' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0806	Little Dry Creek	404' Steel Beam
Paint Condition: Good		General Condition: Good
Br. No. 217-0200-0888	Drainage	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Field Maintenance Division No. 401		McCone County
Br. No. 228-0200-0002	Timber Creek	125' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0011	Skull Creek	123' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Hard to check stringers on first span.		It is enclosed with grouted riprap.
Br. No. 228-0200-0044	Drainage	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0047	Drainage	85' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0061	Drainage	85' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0062	Drainage	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0067	Drainage	95' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0086	Coulee	75' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0133	Dirty Creek	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0185	Cotter Creek	63' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0218	Stoney Butte Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0232	Drainage	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0248	Antelope Creek	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0272	Drainage	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 228-0200-0281	Old Channel Redwater River	114' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0291	Drainage	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 228-0200-0316	Redwater River	267' Steel Girder
Paint Condition: Fair		General Condition: Good
Remarks: A few minor spalls at the curb edges.		

Br. No. 228-0200-0321 Paint Condition: Fair	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 228-0200-0352 Paint Condition: Fair	Buffalo Spring Creek	114' Treated Timber Trestle General Condition: Good
Field Maintenance Division No. 401 Br. No. 211-0203-0005 Paint Condition: Fair	Cottonwood Creek	Dawson County 76' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0029 Paint Condition: Fair	Berry Creek	95' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0060 Paint Condition: Fair	Drainage	76' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0084 Paint Condition: Good	Hay Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0095 Paint Condition: Good	Hay Creek	76' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0108 Paint Condition: Good	Sand Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0120 Paint Condition: Good	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0173 Paint Condition: Good	Upper Seven Mile Creek	114' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0177 Paint Condition: Fair	Drainage	76' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0182 Paint Condition: Good	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0198 Paint Condition: Good	Drainage	95' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0230 Paint Condition: Good	Drainage	76' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0243 Paint Condition: Good	Drainage	95' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0256 Paint Condition: Good	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 211-0203-0262 Paint Condition: Good	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 111-0100-0364 Paint Condition: Good	Dry Creek	120' Continuous Concrete T Beam General Condition: Good

Br. No. 111-0100-0364P	Dry Creek	120' Continuous Concrete T Beam
Paint Condition: Good		General Condition: Good
Br. No. 111-0100-0377	Yellowstone River	1317.5' Concrete Girder
Paint Condition: Good		General Condition: Good
Br. No. 111-0100-0389	Graveyard Coulee	90' Continuous Concrete Slab
Paint Condition: Poor		General Condition: Fair
Remarks: Extensive spalling on curb. Tops cracked on corner posts - Bent 1.		
Br. No. 111-0100-0411	Glendive Creek	180.3' Concrete T Beam
Paint Condition: None needed		General Condition: Good
Remarks: A few small spalls on curb edges.		
Br. No. 111-0100-0466	Griffith Creek	106' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Two flared ends of flex beam rail on wrong.		
Br. No. 111-0100-0503	Krug Creek	106' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: One flared end slightly bent, rockers in expansion position at 32°.		
Field Maintenance Division No. 401		Wibaux County
Br. No. 155-0100-0073	West Wibaux Interchange	Underpass
Remarks: Under contract - Let 10-25-61		
Br. No. 155-0100-0074	Beaver Creek	286' Prestressed Concrete Beam
Remarks: Under contract - Let 10-25-61		
Br. No. 155-0100-0075	East Wibaux Interchange	Underpass
Remarks: Under contract - Let 10-25-61		
Br. No. 155-0100-0067 (PTW)	Dry Creek	125' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 155-0100-0074 (PTW)	Beaver Creek	276' Continuous Steel Girder
Paint Condition: Fair		General Condition: Good
Remarks: A section of curb broken off at Bent 1 right.		
Br. No. 155-0100-0084 (PTW)	Yates Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

FEDERAL AID PRIMARY ROUTE 16

Field Maintenance Division No. 501		Big Horn County
Br. No. 102-0870-0040	Pass Creek	64.5' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 102-0870-0047	Pass Creek	64.5' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 102-0870-0131	Little Big Horn River	120' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 102-0870-0223	Lodge Grass Creek	63.9' Concrete T Beam
Paint Condition: Good		General Condition: Good
Br. No. 102-0870-0294	Little Big Horn River	136' Concrete T Beam
Paint Condition: Good		General Condition: Good
Br. No. 102-0870-0352	Little Big Horn River	156' Concrete T Beam
Paint Condition: Good		General Condition: Good
Br. No. 102-0870-0411	Little Big Horn River	156' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: Dirt Berms settling away from concrete	quite a little.	
Br. No. 102-0870-0418	Montana 8 Interchange	Underpass
Paint Condition: Good		General Condition: Good
Remarks: Also FAP Route 37 - Br. No. 102-2120-0001		
Br. No. 102-0870-0418P	Montana 8 Interchange	Underpass
Paint Condition: Good		General Condition: Good
Remarks: Br. No. 102-0870-0418 and 102-0870-0418P one structure.		
Br. No. 102-0870-0431	Little Big Horn River	130' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 102-0870-0431P	Little Big Horn River	164.5' Prestressed Concrete Beams
Paint Condition: Good		General Condition: Good
Remarks: Drift caught on one pier.		
Br. No. 102-0870-0431F	Little Big Horn River	153' Prestressed Concrete Beams
Paint Condition: Good		General Condition: Good
Remarks: Some large logs caught on pier.		
Br. No. 102-0870-0435	Crow Agency Interchange	133' Prestressed Concrete Beams
Paint Condition: Good		General Condition: Good
Remarks: End Bent fill dirt settling.		
Br. No. 102-0870-0435P	Crow Agency Interchange	133' Prestressed Concrete Beams
Paint Condition: Good		General Condition: Good
Remarks: Noticeable settlement of fill dirt at end bents.		
Br. No. 102-0870-0494	Dunmore Interchange	118' Prestressed Concrete Beams
Paint Condition: Good		General Condition: Good

Br. No. 102-0870-0494P	Dunmore Interchange	118' Prestressed Concrete Beams
Paint Condition: Good		General Condition: Good
Br. No. 102-0870-0546	Big Horn River	577.8' Steel Truss
Paint Condition: Fair		General Condition: Good
Br. No. 102-0870-0580	Two Leggin Canal	31' Concrete T Beam
Paint Condition: None needed		General Condition: Good
Remarks: Dirt is undercut quite badly west end under end bent beam.		
Br. No. 102-0870-0627	Perista Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-0870-0687	C.B. & Q. Railroad	232.8' Concrete T Beam
Paint Condition: None required		General Condition: Fair
Remarks: The track span west end, is opened 3 3/4". Looks like it has slipped sideways about 5". Dirt berms at end bents have settled away about 3'. Moderate amount of checking in end post concrete		
Br. No. 102-0870-0725	Fly Creek	57' Untreated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 501		Yellowstone County
Br. No. 156-0870-0137	East Fork Pryor Creek	55' Concrete Slab
Paint Condition: Poor		General Condition: Good
Br. No. 156-0870-0139	Pryor Creek	69' Concrete Slab
Paint Condition: Poor		General Condition: Good
Br. No. 156-0870-0231	Dry Creek	57' Untreated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Stringers have chipped places and small rotted spots.		
Br. No. 156-0870-0251	N. P. Railway	261.8' Continuous Steel Beam
Paint Condition: Poor		General Condition: Good
Remarks: Paint on steel directly over tracks looks like it has been burned away.		
Br. No. 156-0870-0253	Yellowstone River	540' Continuous Steel Truss
Paint Condition: Poor		General Condition: Good
Remarks: Dirt collected around rockers Bent 3. End posts Bent 3 badly cracked. Two vertical members twisted Span 2. Many crossframes have been hit and bent slightly. Vertical clearance is 14.80 feet. End posts Bent 1 cracked.		
Br. No. 156-0870-0253	Yellowstone River	945.2' Riveted Plate Girder
Remarks: Under contract - Let 5-25-60		
Br. No. 156-0870-0253P	Yellowstone River	938.2' Riveted Plate Girder
Remarks: Under contract - Let 5-25-60		
Br. No. 156-0870-0255	Sewer Ditch	35' Concrete T Beam
Paint Condition: None Required		General Condition: Good
Remarks: Left side filled in with dirt. Four corner posts broken off.		

Br. No. 156-0870-0297	Five Mile Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0870-0303	Billings Bench	39' Steel I Beam
Paint Condition: Good-Wood; Poor-Steel		General Condition: Good
Br. No. 156-0870-0349	Eleven Mile Creek	31.2' Steel I Beam
Paint Condition: Good-Wood; Poor-Steel		General Condition: Good
Br. No. 156-0870-0354	Middle Fork Twelve Mile Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0870-0357	North Fork Twelve Mile Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0870-0409	So. Fork Crooked Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0870-0416	No. Fork Crooked Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0870-0451	Dry Wash	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0870-0492	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 156-0870-0493	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 501		Musselshell County
Br. No. 133-0870-0016	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Berm getting away under both end bents.		
Br. No. 133-0870-0026	Drainage	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 133-0870-0045	Razor Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0870-0181	Half Breed Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 133-0870-0206	Half Breed Creek	31.2' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Steel stringers underneath are crooked. No structural harm.		
Br. No. 133-0870-0208	Half Breed Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 133-0870-0210	Half Breed Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 133-0870-0226 Paint Condition: Good	Half Breed Creek	76' Treated Timber Trestle General Condition: Good
Br. No. 133-0870-0229 Paint Condition: Fair	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 133-0870-0250 Paint Condition: Good Remarks: A little spalling on concrete sidewalk edges.	Musselshell River	229' Continuous Steel Beam General Condition: Good
Br. No. 133-0870-0254 Paint Condition: Poor-Underneath; Good-Top Remarks: Rockers and deck expansion plate in extreme expansion position at 5° below 0. Looks like steel touches concrete on both ends.	C.M.ST.P.&P. R.R.	167.7' Steel Truss General Condition: Good
Br. No. 133-0870-0351 Paint Condition: Good	South Willow Creek	76' Treated Timber Trestle General Condition: Good
Br. No. 133-0870-0362 Paint Condition: Good	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 133-0870-0417 Paint Condition: Good	Willow Creek	95' Treated Timber Trestle General Condition: Good
Field Maintenance Division No. 403 Br. No. 135-0870-0029 Paint Condition: Good Remarks: A number of plank are loose from the bents. Looks like ground heave has pulled them loose.	Flatwillow Creek	Petroleum County 133' Treated Timber Trestle General Condition: Good
Field Maintenance Division No. 403 Br. No. 114-0870-0023 Paint Condition: Good	Spring Creek	Fergus County 57' Treated Timber Trestle General Condition: Good
Br. No. 114-0870-0027 Paint Condition: Good	Pike Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 114-0870-0058 Paint Condition: Good	Pike Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 114-0870-0124 Paint Condition: Good	Elk Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 214-0192-0201 Paint Condition: Good Remarks: Under contract - Let 2-21-61 Small piece of concrete gone from cap center Bent (Upstream corner). Dirt banked around outside beams end bents.	McDonald Creek	91.5' Prestressed Concrete Beam General Condition: Good
Br. No. 214-0192-0212 Paint Condition: Good Remarks: Under contract - Let 2-21-61 Little chip of concrete gone right end wall Bent 3.	Chippewa Creek	81.5' Prestressed Concrete Beam General Condition: Good

Br. No 214-0192-0250	Fords Creek	91.5' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: Under contract - Let 2-21-61 A few little chips off of curb.		
Br. No. 214-0192-0273	Little Box Elder Creek	81.5' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: Under contract - Let 2-21-61		
Br. No. 214-0192-0307	South Fork Bear Creek	91.5' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: One flared end bent.		
Br. No. 214-0192-0361	North Fork Bear Creek	81.5' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: Two flared end bents. Concrete chip off of column center bent.		
Br. No. 214-0190-0415	Overflow Box Elder Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 214-0190-0624	Missouri River	698' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Name plate south gone. Surface patches scaling near ground line, Pier 3. Three nuts gone from north name plate.		
Field Maintenance Division No. 402		Phillips County
Br. No. 236-0190-0310	Beaver Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 236-0190-0364	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 236-0190-0368	Drainage	63' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 236-0190-0373	Little Warm Creek	138' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 236-0190-0418	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Roadway fills have narrowed at both bridge ends.		
Br. No. 236-0190-0452	Big Warm Creek	100' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 236-0190-0483	Wild Horse Creek Overflow	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 236-0190-0486	Wild Horse Creek	100' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 236-0190-0489	Wild Horse Creek	100' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Nose angles on bents are very rusty.		

Br. No. 236-0190-0507 Paint Condition: Fair	Three Mile Creek	38' Treated Timber Trestle General Condition: Good
Br. No. 236-0190-0519 Paint Condition: Fair	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 236-0190-0522 Paint Condition: Fair	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 236-0190-0551 Paint Condition: Fair Remarks: Bent 4 shimmed underneath.	West Alkali Creek	100' Treated Timber Trestle General Condition: Good
Br. No. 236-0190-0557 Paint Condition: Fair	Black Coulee	75' Treated Timber Trestle General Condition: Good
Br. No. 236-0190-0578 Paint Condition: Good	Halfway Coulee	76' Treated Timber Trestle General Condition: Good
Br. No. 236-0190-0612 Paint Condition: Fair Remarks: Cracks showing up at tops of piers.	Alkali Creek	156.5' Steel Pony Truss General Condition: Good Rockers too far to expansion position.
Br. No. 236-0190-0617 Paint Condition: Fair	Desjardin Coulee	57' Treated Timber Trestle General Condition: Good
Br. No. 236-0190-0660 Paint Condition: Fair Remarks: Reflector signs shot up quite a little.	South Fork Taylor Creek	75' Treated Timber Trestle General Condition: Good
Br. No. 236-0190-0662 Paint Condition: Good Remarks: Badly broken stringer third span, third	North Fork Taylor Creek	100' Treated Timber Trestle General Condition: Good stringer.
Br. No. 236-0190-0686 Paint Condition: Fair	Canal	100' Treated Timber Trestle General Condition: Good
Br. No. 236-0190-0693 Paint Condition: Good Remarks: Oakum raised out of many hand rail post holes. Third wall from north on east side, has moved in about 5/8" from fill pressure. One large chip from concrete at the joint. Fourth wall from north on west side, is moved in about 5/8". General checking on concrete posts along rail-road track on north side.	G. N. Railway	Underpass General Condition: Good

FEDERAL AID PRIMARY ROUTE 17

Field Maintenance Division No. 502

Custer County

Br. No. 109-0100-0052

Jr. Grade Separation

21.2' Concrete Slab

Remarks: Under contract - Let 4-19-61

Br. No. 109-0100-0181

Cottonwood Creek

171' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Br. No. 109-0100-0195

Miles Creek

57' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Br. No. 109-0100-0215

Macks Creek

38' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Field Maintenance Division No. 401

Prairie County

Br. No. 140-0100-0001

Williams Coulee

95' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Br. No. 140-0100-0028

Camp Creek

57' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Br. No. 140-0100-0065

Powder River

632.7' Continuous Steel Truss

Paint Condition: Good

General Condition: Good

Remarks: Very mild erosion and drift wear noticeable on pier nose in stream main flow.

Br. No. 140-0100-0088

Sand Coulee

114' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Br. No. 140-0100-0096

Conn's Coulee

57' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Br. No. 140-0100-0122

Drainage

38' Treated Timber Trestle

Remarks: Not inspected

Br. No. 140-0100-0134

Drainage

38' Treated Timber Trestle

Remarks: Not inspected

Br. No. 140-0100-0170

C.M.ST.P.&P. R.R.

Underpass

Paint Condition: Good

General Condition: Good

Br. No. 140-0100-0223

O'Fallon Creek

220' Continuous Steel Girder

Paint Condition: Good

General Condition: Good

Remarks: Bent 3 rockers in extreme expansion position at +20°. Steel girder is butted solid against concrete wall. Mild spalling corner post and curb Bent 3 left.

Br. No. 140-0100-0226

N. P. Railway

146' Concrete T Beam

Paint Condition: None required

General Condition: Good

Remarks: Most rockers tipped wrong.

Br. No. 140-0100-0245

Yellowstone River

1142.2' Steel Truss

Paint Condition: Good

General Condition: Good

Remarks: Portals have been hit and bent slightly. Few spalls in concrete under expansion device.

Br. No. 140-0100-0268	Hatchet Creek	64.5' Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: A few small cracks in rail posts.		
Field Maintenance Division No. 401		
Br. No. 111-0100-0011	Bad Route Creek	Dawson County
Paint Condition: Good		164.5' Steel I Beam
Remarks: A few small cracks in concrete posts.		General Condition: Good
Br. No. 111-0100-0058	Cracker Box Creek	164.5' Steel I Beam
Paint Condition: Good		General Condition: Good
Br. No. 111-0100-0106	U.S.R.S. Canal	65' Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: A few small cracks in top edges of concrete posts.		
Br. No. 111-0100-0107	Clear Creek	189.5' Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: A few small cracks in tops of posts.		
Br. No. 111-0100-0110	Canal	31' Steel I Beam
Paint Condition: Good		General Condition: Good
Br. No. 111-0100-0133	Whoopup Creek	64.5' Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: A few small spalls at outside of walk.		
Br. No. 111-0100-0156	U.S.R.S. Canal	39.5' Steel I Beam
Paint Condition: Good		General Condition: Good
Br. No. 111-0100-0157	Sand Creek	89.5' Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: Little cracks at top of most of the posts.		
Br. No. 111-0100-0159	U.S.R.S. Canal	21' Concrete T Beam
Paint Condition: None required		General Condition: Good
Remarks: Shoulder Berm Bent 2 is eroding.		
Br. No. 111-0100-0185	U.S.R.S. Canal	21' Concrete T Beam
Paint Condition: None required		General Condition: Good
Br. No. 111-0100-0201	Upper Seven Mile Creek	120' Continuous Concrete T Beam
Paint Condition: Good		General Condition: Good
Br. No. 111-0100-0201P	Upper Seven Mile Creek	120' Continuous Concrete T Beam
Paint Condition: Good		General Condition: Good

FEDERAL AID PRIMARY ROUTE 18

Field Maintenance Division No. 502

Custer County

Br. No. 209-0220-0012 Yellowstone River

971' Steel Girder

Paint Condition: Good

General Condition: Good

Remarks: Hair checks about every three feet downstream side of Pier 3. Deck expansion plate Pier 3, is noisy with traffic and plate is not flush with bottom plate.

Br. No. 209-0220-0040 South Fork Sunday Creek 164' Concrete T Beam

Paint Condition: None needed

General Condition: Good

Remarks: One cracked girder haunch Pier 4. Small chip knocked from curb joint Pier 2. One rail post chipped a little on top.

Br. No. 209-0220-0061 Drainage

38' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 209-0220-0067 Drainage

57' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 209-0220-0076 Drainage

57' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 209-0220-0092 Drainage

57' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 209-0220-0103 Drainage

38' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 209-0220-0112 North Sunday Creek

117.8' Concrete T Beam

Paint Condition: None needed

General Condition: Good

Br. No. 209-0220-0121 Owens Coulee

57' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 209-0220-0135 Drainage

57' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 209-0220-0143 North Sunday Creek

76' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 209-0220-0154 Drainage

38' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Br. No. 209-0220-0169 Drainage

38' Untreated Timber Trestle

Paint Condition: Poor

General Condition: Fair

Remarks: Some piling are rotten, others have had to be reinforced.

Br. No. 209-0220-0180 Grimes Creek

101.7' Prestressed Concrete Beams

Remarks: Under contract - Let 11-29-61

Field Maintenance Division No. 502

Rosebud County

Br. No. 244-0220-0051 Dry House Creek

95' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Remarks: In the process of being widened 1-16-62.

Br. No. 244-0220-0150 Paint Condition: Poor	Rock Springs Creek	38' Treated Timber Trestle General Condition: Good
Field Maintenance Division No. 502		
Br. No. 217-0220-0039 Paint Condition: Poor	Drainage	Garfield County 57' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0054 Paint Condition: Poor	Red Butte Creek	95' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0058 Paint Condition: Fair	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0069 Paint Condition: Good	Drainage	76' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0083 Paint Condition: Poor	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0097 Paint Condition: Poor	Thompson Creek	95' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0109 Paint Condition: Poor	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0137 Paint Condition: Fair	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0147 Paint Condition: Poor	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0209 Paint Condition: Fair	Little Dry Creek	171' Steel I Beam General Condition: Good
Br. No. 217-0220-0211 Paint Condition: Fair	White Horse Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0233 Paint Condition: Good	Red Horse Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0266 Paint Condition: Poor	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0326 Paint Condition: Good	Drainage	76' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0344 Paint Condition: Good	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 217-0220-0398 Paint Condition: Good	Sand Creek	153' Concrete T Beam General Condition: Good
Remarks: Two flared ends installed wrong.		

FEDERAL AID PRIMARY ROUTE 19

Field Maintenance Division No. 201

Br. No. 112-0105-0003 N.P. Ry. (Crackerville)

Paint Condition: Good

Deer Lodge County

136' Continuous Steel Girder

General Condition: Good

Br. No. 112-0105-0006

Clark Fork

52' Concrete T Beam

General Condition: Good

Remarks: Inside face and top of east span curbs are deteriorating. Center pier eroded at water line and light surface erosion on faces of end abutments. East side wings considerably weathered and south wing is cracked.

Br. No. 112-0105-0122

Warm Springs Creek

41' Concrete T Beam

General Condition: Good

Remarks: Some light wing wall and girder cracks.

Br. No. 112-0105-0185

Warm Springs Creek

41' Concrete T Beam

General Condition: Good

Remarks: North edge of deck spalling. Crack in northwest wing.

Field Maintenance Division No. 101

Br. No. 120-0105-0076

Fred Burr Creek

Granite County

63.4' Concrete T Beam

General Condition: Good

Remarks: Traffic nicks, north side end posts.

Br. No. 120-0105-0212

Boulder Creek

71.4' Concrete T Beam

General Condition: Good

Remarks: Concrete Pier 2 eroding at water line. Reinforcing steel exposed on down stream column.

Br. No. 120-0105-0256

Flint Creek

114' Concrete T Beam

General Condition: Good

Remarks: Light spalling of one Bent 1 wing wall.

Br. No. 120-0105-0320

Willow Creek

39' Steel I Beam

Paint Condition: Good

General Condition: Good

Remarks: Bent 1 eroded at water line.

Br. No. 120-0105-0357

Clark Fork

267' Steel Girder

Paint Condition: Good

General Condition: Good

Remarks: Some light cracking in curbs and rail posts.

Br. No. 120-0105-0360

Drainage

25' Treated Timber Trestle

Paint Condition: Good

General Condition: Good

Remarks: A few loose cross braces.

FEDERAL AID PRIMARY ROUTE 20

Field Maintenance Division No. 401
Br. No. 211-0160-0018 Drainage
Paint Condition: Good

Dawson County
76' Treated Timber Trestle
General Condition: Good

Br. No. 211-0160-0044
Drainage (Signed - Deer Creek)
Paint Condition: Good

190' Treated Timber Trestle
General Condition: Good

Br. No. 211-0160-0071 Three Mile Creek
Paint Condition: Good

76' Treated Timber Trestle
General Condition: Good

Br. No. 211-0160-0081 Drainage
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 211-0160-0102 Lower Seven Mile Creek
Paint Condition: Good

152' Treated Timber Trestle
General Condition: Good

Br. No. 211-0160-0127 Morgan Creek
Paint Condition: Good
Remarks: Fifth stringer, Seventh span, busted.

152' Treated Timber Trestle
General Condition: Good

Br. No. 211-0160-0157 Thirteen Mile Creek
Paint Condition: Good

190' Treated Timber Trestle
General Condition: Good

Br. No. 211-0160-0180 Linden Creek
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Field Maintenance Division No. 401
Br. No. 242-0160-0019 Burns Creek
Paint Condition: Good

Richland County
150' Treated Timber Trestle
General Condition: Good

Br. No. 242-0160-0061 Beef Slough
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 242-0160-0081 Garden Coulee
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 242-0160-0090 U.S.R.S. Canal
Paint Condition: Good

75' Treated Timber Trestle
General Condition: Good

Br. No. 242-0160-0093 Dunlap Creek
Paint Condition: Good

95' Treated Timber Trestle
General Condition: Good

Br. No. 242-0160-0095 U.S.R.S. Canal
Paint Condition: Good

63' Treated Timber Trestle
General Condition: Good

Br. No. 242-0160-0144 U.S.R.S. Canal
Paint Condition: Good

75' Treated Timber Trestle
General Condition: Good

Br. No. 242-0160-0147 Sears Creek
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 242-0160-0235 Paint Condition: Good	Fox Creek	76' Untreated Timber Trestle General Condition: Good
Br. No. 242-0160-0268 Paint Condition: Good	Ditch	38' Treated Timber Trestle General Condition: Good
Br. No. 242-0160-0285 Paint Condition: Good	Lone Tree Creek	114' Treated Timber Trestle General Condition: Good
Br. No. 242-0200-0364 Paint Condition: Poor	First Hay Creek	114' Treated Timber Trestle General Condition: Good
Br. No. 242-0200-0369 Paint Condition: Poor	Second Hay Creek	95' Treated Timber Trestle General Condition: Good
Br. No. 242-0200-0377 Paint Condition: Poor	Third Hay Creek	76' Treated Timber Trestle General Condition: Good

FEDERAL AID PRIMARY ROUTE 21

Field Maintenance Division No. 301 Cascade County
Br. No. 107-0910-0001
U.S. 89 - Vaughn Interchange Underpass
Remarks: FAP Route 3, #107-0890-0530 - #0001 and 0001P are one structure.

Br. No. 107-0910-0001P
U.S. 89 - Vaughn Interchange Underpass
Remarks: FAP Route 3, #107-0890-0530 - #0001 and 0001P are one structure.

Field Maintenance Division No. 301 Teton County
Br. No. 150-0910-0172 Teton River 267' Steel Girder
Paint Condition: Fair to Good General Condition: Good

Field Maintenance Division No. 302 Pondera County
Br. No. 137-0910-0142 Irrigation Canal 25' Concrete T Beam
General Condition: Good
Remarks: Top of one east side intermediate rail post above top rails, has been knocked off. Wing walls crazed.

Br. No. 137-0910-0154 Irrigation Canal 21.5' Concrete Slab
General Condition: Good

Br. No. 137-0910-0191 Dry Fork Marias River 113' Concrete T Beam
General Condition: Good

Br. No. 137-0910-0246 Irrigation Canal 63.6' Concrete T Beam
General Condition: Good

Field Maintenance Division No. 302 Toole County
Br. No. 151-0910-0029 Marias River 541.3' Continuous Steel Plate
Paint Condition: Good General Condition: Good
Remarks: Rockers of north end bent are dirt covered and should be cleaned off.

Br. No. 151-0910-0071 U.S. 2 & G.N. Ry. 360' Steel Beam
Paint Condition: Good General Condition: Good
Remarks: FAP Route 1 #151-0020-0151

Br. No. 151-0910-0071P U.S. 2 & G.N. Ry. 360' Steel Beam
Paint Condition: Good General Condition: Good
Remarks: FAP Route 1 #151-0020-0150

Br. No. 151-0910-0084 North Shelby Interchange Underpass
Paint Condition: Good General Condition: Good

Br. No. 151-0910-0084P North Shelby Interchange Underpass
Paint Condition: Good General Condition: Good
Remarks: #151-0910-0084 and 151-0910-0084P are one structure.

Br. No. 151-0910-0354
FAS Route 214 - Sunburst Interchange 168' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: FAS Route 214 - #214-51-0001

Br. No. 151-0910-0357	G. N. Railway	313' Steel Girder
Paint Condition: Good		General Condition: Good

Field Maintenance Division No. 302		Toole County
Federal Aid Primary Route 21 Old Alignment in	Shelby	
Br. No. 151-0910-0013	G. N. Railway	382' Steel Beam
Paint Condition: Good		General Condition: Good

Br. No. 151-0910-0033		
I 15 - North Shelby Interchange		276' Steel Girder
Remarks: See #151-0910-0084		

FEDERAL AID PRIMARY ROUTE 22

Field Maintenance Division No. 402		Daniels County
Br. No. 210-0130-0144	North Fork Eagle Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Field Maintenance Division No. 402		Sheridan County
Br. No. 246-0050-0026	North Fork Eagle Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 246-0050-0037	Eagle Creek	95' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 246-0050-0060	Redstone Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 246-0050-0076	Big Muddy Creek	125' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 246-0050-0084	Canal	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 246-0050-0188	Plentywood Creek	114' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Small amount of drift collected underneath.		
Br. No. 246-0050-0206	McCoy Creek	114' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 246-0050-0244	Box Elder Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 246-0050-0255	Marron Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 246-0160-0268	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 246-0160-0285	Ator Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 246-0160-0335	Antelope Creek	114' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 246-0160-0357	McLaughlin Creek	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 246-0160-0387	Reserve Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Left stringer, first span, broken.		
Br. No. 246-0160-0416	Neiser Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: A few loose nuts and a cracked wheel guard.		

Br. No. 246-0160-0478	Medicine Lake Overflow	95' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Could only see under two end spans. They are okay.		
Br. No. 246-0160-0479	Medicine Lake	190' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Could only see under two end spans. They are okay.		
Br. No. 246-0160-0532	Homestead Creek	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Field Maintenance Division No. 402		Roosevelt County
Br. No. 243-0160-0001	McCabe Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 243-0160-0010	Lost Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 243-0160-0040	Sheep Creek	106' Pony Truss
Paint Condition: Fair		General Condition: Good
Remarks: One minor bend in railing from being hit.		
Br. No. 243-0160-0177	Spring Creek & G.N.Ry.	264' Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 243-0160-0200	Missouri River	1169' Thru Steel Truss
Paint Condition: Good		General Condition: Good
Remarks: One anchor bolt gone from Pier 6. All crossframes and portals have slight bends from being hit.		
Field Maintenance Division No. 402		Richland County
Br. No. 242-0160-0005	Missouri River	95' Treated Timber Trestle
Paint Condition: Good	Overflow	General Condition: Good
Br. No. 242-0160-0014		
Dry Creek (Signed Day Creek)		76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 242-0160-0052	Sheep Camp Coulee	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 242-0160-0063	Lee Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 242-0160-0075	Shaw Coulee	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 242-0160-0085	Cherry Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 242-0160-0092		
Middle Fork Cherry Creek		38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Br. No. 242-0160-0103	Hackley Coulee	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 242-0160-0112		
South Fork Cherry Creek		76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 242-0160-0201		
North Fork First Hay Creek		76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: One rail post has a part split off.		
Br. No. 242-0160-0233		
South Fork First Hay Creek		95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 242-0160-0237	Stockpass	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 242-0160-0330	U.S.R.S. Canal	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Two piling wall plank gone. One spacer block between stringers is falling out.		

FEDERAL AID PRIMARY ROUTE 23

Field Maintenance Division No. 502		Custer County
Br. No. 109-3120-0018	I 94 Interchange	Underpass
Paint Condition: Good		General Condition: Good
Remarks: FAP Route 2 - Br. No. 109-0100-0182		
Br. No. 109-3120-0024	Irrigation Canal	50' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-3120-0064	Cowles Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-3120-0069	Irrigation Canal	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 109-3120-0079	Irrigation Canal	50' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 109-3120-0084	Log Creek	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 109-3120-0091	Mills Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 109-3120-0108	Squaw Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 109-3120-0155	Pumpkin Creek	138' Prestressed Concrete Beams
Paint Condition: Good		General Condition: Good
Remarks: Under contract - Let 4-19-61		
Br. No. 109-3120-0280	Drainage	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 109-3120-0298	Fire Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 109-3120-0311	Drainage	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 109-3120-0326	Drainage	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 109-3120-0338	Maggie Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Upstream piles showing some damage from drift.		
Br. No. 109-3120-0345	Chinnick Creek	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 109-3120-0351	Drainage	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Br. No. 109-3120-0366 Paint Condition: Poor	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 109-3120-0388 Paint Condition: Poor	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 109-3120-0399 Paint Condition: Poor	969 Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 109-3120-0411 Paint Condition: Poor	Betz Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 109-3120-0420 Paint Condition: Poor	Cottonwood Creek	38' Treated Timber Trestle General Condition: Good
Br. No. 109-3120-0431 Paint Condition: Poor	Basin Creek	57' Treated Timber Trestle General Condition: Good
Br. No. 109-3120-0444 Paint Condition: Poor	Pumpkin Creek	95' Treated Timber Trestle General Condition: Good
Br. No. 109-3120-0450 Paint Condition: Poor	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 109-3120-0454 Paint Condition: Poor Remarks: One rail post pushed slightly out of line. Many posts have large weather checks.	Drainage	95' Treated Timber Trestle General Condition: Good
Br. No. 109-3120-0463 Paint Condition: Poor	Drainage	95' Treated Timber Trestle General Condition: Good
Field Maintenance Division No. 502 Br. No. 138-3120-0077 Paint Condition: Poor	Drainage	Powder River County 76' Treated Timber Trestle General Condition: Good
Br. No. 138-3120-0096 Paint Condition: Poor	Lost Soldier Creek	38' Treated Timber Trestle General Condition: Good
Br. No. 138-3120-0163 Paint Condition: Poor	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 138-3120-0192 Paint Condition: Poor Remarks: Rail and curb show where a bent has either heaved or sunk as the rail has a hump in it.	Mizpah Creek	114' Treated Timber Trestle General Condition: Good
Br. No. 138-3120-0200 Paint Condition: Poor	Drainage	57' Treated Timber Trestle General Condition: Good
Br. No. 138-3120-0224 Paint Condition: Poor	Drainage	38' Treated Timber Trestle General Condition: Good
Br. No. 138-3120-0290 Paint Condition: Poor	Drainage	57' Treated Timber Trestle General Condition: Good

Br. No. 138-2120-0300	Powder River	591.8 Continuous Steel Truss
Paint Condition: Good		General Condition: Good
Br. No. 138-2120-0362	Little Powder River	297' Steel Truss
Paint Condition: Poor		General Condition: Good
Br. No. 138-2120-0365	East Fork Creek	114' Treated Timber Trestle
Remarks: Not inspected.		
Field Maintenance Division No. 502		Carter County
Br. No. 106-2120-0249	Willow Creek	92' Concrete Girder
Paint Condition: Good		General Condition: Good
Br. No. 106-2120-0325	Thompson Creek	90.3 Steel Beam
Paint Condition: Fair		General Condition: Good
Remarks: Rockers in expansion position at +20°.		
Br. No. 106-2120-0332	Drainage	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 106-2120-0342	Little Missouri River	178.7' Steel Pony Truss
Paint Condition: Fair		General Condition: Good
Remarks: Rockers in expansion position at +20°.		

FEDERAL AID PRIMARY ROUTE 24

Field Maintenance Division No. 101		Missoula County
Br. No. 232-0200-0055	Blackfoot River	360.8' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Some rail post tops scarred by traffic.		
Br. No. 232-0200-0090		West Twin Creek
Paint Condition: Good		75' Treated Timber Trestle
Remarks: Top and sides of concrete end posts are rapidly disintegrating. Out-		General Condition: Good
side top and faces of pier copings are also deteriorating due to weathering.		
Br. No. 232-0200-0093		East Twin Creek
Paint Condition: Good to Fair		75' Treated Timber Trestle
Remarks: Heavy disintegration of concrete end posts.		General Condition: Good
Br. No. 232-0200-0112		Blackfoot River
Paint Condition: Good		445.8' Continuous Deck Heel Truss
Remarks: Light to heavy scaling of concrete deck spans, both ends. Outside face		General Condition: Good
and ends of pier copings are deteriorating due to weather. Heavy		
disintegration of end posts.		
Br. No. 232-0200-0254		Elk Creek
Paint Condition: Good		55' Treated Timber Trestle
Remarks: Two east creek bent sway braces split.		General Condition: Good
Br. No. 232-0200-0266		Big Blackfoot River
Paint Condition: Good		244' Plate Girder
Remarks: Some minor spalling of concrete end posts and wing walls.		General Condition: Good
Br. No. 232-0200-0313		Clearwater River
Paint Condition: Good		113.3' Continuous Steel Beam
		General Condition: Good
Field Maintenance Division No. 101		Powell County
Br. No. 239-0200-0059		Monture Creek
Paint Condition: Good		100' Treated Timber Trestle
		General Condition: Good
Br. No. 239-0200-0141		North Fork Blackfoot River
Paint Condition: Good		182' Continuous Concrete T Beam
		General Condition: Good
Br. No. 239-0200-0223		Arrastra Creek
Paint Condition: Good		57' Treated Timber Trestle
Remarks: Paint generally good. Fair to poor on a few rails.		General Condition: Good
Field Maintenance Division No. 301		Lewis and Clark County
Br. No. 225-0200-0043		Keep Cool Creek
Paint Condition: Fair to Poor		38' Treated Timber Trestle
		General Condition: Good
Br. No. 225-0200-0047		Spring Creek
Paint Condition: Fair to Poor		38' Treated Timber Trestle
		General Condition: Good
Br. No. 225-0200-0056		Spring Creek Overflow
Paint Condition: Fair to Poor		25' Treated Timber Trestle
Remarks: Bridge sign bent.		General Condition: Good

Br. No. 225-0200-0123	Landers Fork	178' Continuous Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: East end post deteriorating. North curb face and south exterior deck edge also deteriorating due to weathering.		
Br. No. 225-0200-0131	Drainage	30' Treated Timber Trestle
Paint Condition: North side-Poor; South side-Good		
General Condition: Good		
Br. No. 225-0200-0139	Drainage	30' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 225-0200-0154	Drainage	30' Treated Timber Trestle
Paint Condition: North side-Poor; South side-Good		
General Condition: Good		
Remarks: One end post split in two.		
Br. No. 225-0200-0166	Drainage	30' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 225-0200-0174	Alice Creek	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 225-0200-0201	Cadotte Creek	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Bridge signs need repainting.		
Br. No. 225-0200-0325	Middle Fork Dearborn River	101' Treated Timber Trestle
Paint Condition: Fair to Poor		General Condition: Good
Br. No. 225-0200-0330	Drainage	25' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 225-0200-0335	Drainage	25' Treated Timber Trestle
Paint Condition: Fair to Poor		General Condition: Good
Remarks: Northeast top rail end shattered.		
Br. No. 225-0200-0341	Drainage	25' Treated Timber Trestle
Paint Condition: Good to Fair		General Condition: Good
Br. No. 225-0200-0370	Dearborn River	184.9' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Br. No. 225-0200-0457	Flat Creek	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: The cap of the bent on the east side of the creek has been blocked up over the two south piles with a 6"x12" timber under the cap. Rail looks good, no settlement.		
Field Maintenance Division No. 301		Cascade County
Br. No. 207-0200-0026	Drainage	63' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Grouted riprap on east side breaking up.		

Br. No. 207-0200-0092	Irrigation Canal	25' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Southeast end post split in two and core dry rotted. Three piles of the east bent have been spliced and tied with bar iron and lag screws. Fill behind the backing plank of the west bent is sloughing out. Up approximately 2.0' from bottom of lower plank and about 1.0' wide and runs for two pile panel lengths.		
Br. No. 207-0200-0217	Sun River	284.2' Steel Truss
Paint Condition: Good to Fair		General Condition: Good
Remarks: Portals have been hit. Center of east portal heavily bent; intermediates, lightly bent. Erosion of Pier 3 at water line.		
Br. No. 207-0200-0224	Mill Coulee	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: One split pile Bent 2. Paint almost gone from railing.		
Federal Aid Primary Route 24 Spur		
Br. No. 207-0210-0013	Simms Creek	150' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Oil mat breaking up along north curb.		
Federal Aid Primary Route 24 Augusta Spur		
Br. No. 207-0210-0022	Irrigation Canal	39' Concrete T Beam
General Condition: Good		
Federal Aid Primary Route 24 Augusta Spur		
Br. No. 207-0210-0031	Heppler Coulee	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Left corner post east bent, split in two.		
Federal Aid Primary Route 24 Augusta Spur		
Br. No. 225-0210-0062	Dry Creek	Lewis and Clark County
Paint Condition: Poor		76' Treated Timber Trestle
Remarks: Shoulder fill from inside face of curb has sloughed out at the south-west corner.		
Federal Aid Primary Route 24 Augusta Spur		
Br. No. 225-0210-0110	Spring Coulee	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Federal Aid Primary Route 24 Augusta Spur		
Br. No. 225-0210-0152	Drainage	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Federal Aid Primary Route 24 Augusta Spur		
Br. No. 225-0210-0153	South Fork Sun River	79' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: Lower rail end west span, north side, at center is broken and hanging by re-steel.		

FEDERAL AID PRIMARY ROUTE 25

Field Maintenance Division No. 401	McCone County
Br. No. 228-0130-0002 Horse Creek	114' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 228-0130-0017 Lone Tree Creek	38' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 228-0130-0025 Drainage	38' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 228-0130-0056 Lost Creek	76' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 228-0130-0085 South Fork Buffalo Creek	76' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 228-0130-0102 North Fork Buffalo Creek	76' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 228-0130-0149 Duck Creek	76' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 228-0130-0185 Drainage	57' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 228-0130-0202 Cow Creek	114' Treated Timber Trestle
Paint Condition: Fair	General Condition: Good
Remarks: Rail looks crooked.	
Br. No. 228-0130-0212 Drainage	57' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good
Br. No. 228-0130-0253 East Fork Wolf Creek	57' Treated Timber Trestle
Paint Condition: Fair	General Condition: Good
Br. No. 228-0130-0277 Wolf Creek	114' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good
Remarks: Drift collected on top of plank walls around piles.	
Br. No. 228-0130-0294 Drainage	76' Treated Timber Trestle
Paint Condition: Fair	General Condition: Good
Br. No. 228-0130-0315 Drainage	57' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 228-0130-0342 Drainage	57' Treated Timber Trestle
Paint Condition: Fair	General Condition: Good
Br. No. 228-0130-0354 Drainage	25' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good
Br. No. 228-0130-0388 Sheep Creek	57' Treated Timber Trestle
Paint Condition: Fair	General Condition: Good

Br. No. 228-0130-0420	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 228-0130-0465	Missouri River	1074' Steel Thru Truss
Paint Condition: Good		General Condition: Good
Remarks: About one-half of crossframes have been hit and bent. Portals also have been hit and bent. Mild surface spalls on deck.		
Field Maintenance Division No. 402		Roosevelt County
Br. No. 243-0134-0038	Little Wolf Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 243-0134-0049	Mosquito Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 243-0134-0062	G. N. Railway	Underpass
Paint Condition: Good		General Condition: Good
Remarks: Second and third section of retaining wall on northeast side are leaning in. Looks like the wall is cracked off at the curb line. This wall is out of line about one foot at the worst place. There must be a water condition behind these walls because the ice shows a flow through a crack between the walls and base. Water flows over curb and builds up ice. in gutter. Third section of retaining wall on northwest side is out of line about three inches. Slab rides rough and has spalled at most joints.		

FEDERAL AID PRIMARY ROUTE 26

Field Maintenance Division No. 401

Br. No. 242-0230-0003 Ditch

Paint Condition: Good

Richland County

57' Treated Timber Trestle

General Condition: Good

Br. No. 242-0230-0013 Yellowstone River

Paint Condition: Poor

1231' Steel Truss

General Condition: Good

Remarks: Paint badly scaled under first plate girder span. Rail has a few minor bends from being hit.

Br. No. 242-0230-0023 Drainage

Paint Condition: Good

57' Treated Timber Trestle

General Condition: Good

Br. No. 242-0230-0062 Bennie Peer Creek

Paint Condition: None required

113' Concrete T Beam

General Condition: Good

Remarks: Pier 3 has honeycomb sections at base of shaft. Erosion has partly exposed the footings at Pier 3.

FEDERAL AID PRIMARY ROUTE 27

Field Maintenance Division No. 502
Br. No. 206-0070-0007 Drainage
Paint Condition: Good

Br. No. 206-0070-0020 Drainage
Paint Condition: Good

Br. No. 206-0070-0030 Drainage
Paint Condition: Good

Br. No. 206-0070-0057 Drainage
Paint Condition: Good

Br. No. 206-0070-0068 Little Beaver Creek
Paint Condition: Good

Br. No. 206-0070-0071 Collins Creek
Paint Condition: Good

Br. No. 206-0070-0088 Canal
Paint Condition: Good

Br. No. 206-0070-0121 Drainage
Paint Condition: Good

Field Maintenance Division No. 502
Br. No. 213-0070-0063 Drainage
Paint Condition: Good

Br. No. 213-0070-0081 Drainage
Paint Condition: Good

Br. No. 213-0070-0094 Drainage
Paint Condition: Good

Br. No. 213-0070-0231 Drainage
Paint Condition: Good

Br. No. 213-0070-0237 Sandstone Creek
Paint Condition: Good

Field Maintenance Division No. 401
Br. No. 255-0070-0002 Ash Creek
Paint Condition: Good

Br. No. 255-0070-0027 Drainage
Paint Condition: Fair

Br. No. 255-0070-0060 Drainage
Paint Condition: Poor

Br. No. 255-0070-0072 Drainage
Paint Condition: Poor

Carter County
57' Treated Timber Trestle
General Condition: Good

38' Treated Timber Trestle
General Condition: Good

38' Treated Timber Trestle
General Condition: Good

57' Treated Timber Trestle
General Condition: Good

95' Treated Timber Trestle
General Condition: Good

57' Treated Timber Trestle
General Condition: Good

57' Treated Timber Trestle
General Condition: Good

57' Treated Timber Trestle
General Condition: Good

Fallon County
57' Treated Timber Trestle
General Condition: Good

57' Treated Timber Trestle
General Condition: Good

57' Treated Timber Trestle
General Condition: Good

57' Treated Timber Trestle
General Condition: Good

63' Treated Timber Trestle
General Condition: Good

Wibaux County
75' Treated Timber Trestle
General Condition: Good

38' Treated Timber Trestle
General Condition: Good

45' Treated Timber Trestle
General Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 255-0070-0133	Drainage	45' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 255-0070-0179	Drainage	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: All sway braces are broken.		
Br. No. 255-0070-0236	Beaver Creek	150' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 255-0070-0249	Beaver Creek	150' Steel Girder
Paint Condition: Fair		General Condition: Good
Br. No. 255-0070-0252	N. P. Railway	Underpass
Paint Condition: Fair		General Condition: Good
Remarks: Concrete posts on top weathered noticeable.		

Field Maintenance Division No. 501
Br. No. 105-2120-0058 Drainage
Paint Condition: None needed

Carbon County
25' Concrete T Beam
General Condition: Good

Br. No. 105-2120-0072 West Fork Rock Creek
Paint Condition: None needed

63' Concrete T Beam
General Condition: Good

Remarks: Minor erosion at base of columns of center pier. A few small spalls on sidewalk edges.

Br. No. 105-2120-0243 Rock Creek
Paint Condition: None needed

122' Concrete T Beam
General Condition: Good

Remarks: Dirt Berm Bent 4 is washing away somewhat. Small amount of erosion is noticeable on columns at low water line.

Br. No. 105-2120-0343 Rock Creek
Paint Condition: Fair

122.5' Steel I Beam
General Condition: Fair

Remarks: A lot of working over has been done on this bridge. Wing timbers right of Bent 5 are rotten. Some spalling on top of piers.

Br. No. 105-2120-0348 Drainage
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

FEDERAL AID PRIMARY ROUTE 29

Field Maintenance Division No. 202	Madison County
Br. No. 229-2870-0021 Weber Irrigation	25' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Right side rails scuffed. Oiled surface on deck is in good condition.	
Br. No. 229-2870-0166 Herman Gulch	45' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Grouted riprap at south end is breaking up. Oiled surface on deck is in good condition.	
Br. No. 229-2870-0179 Granite Creek	38' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Grouted riprap is breaking up at both ends. Left side curb bolt nuts are gone. Oiled surface on deck is in good condition.	
Br. No. 229-2870-0183 McNeal Gulch	38' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Paint is good except on a few rails and one post where it is poor. Grouted riprap on west side is breaking up. Oiled surface on deck is in good condition.	
Br. No. 229-2870-0188 Water Gulch	57' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: One new stringer has been set in near center of Span 1 and two in the center span. Grouted riprap breaking up at Bent 4. Oiled surface on deck is in good condition.	
Br. No. 229-2870-0259 Alder Creek	38' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Oiled surface on deck in good condition. A few checked stringers.	
Br. No. 229-2870-0284 Ramshorn Creek	38' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: East side rail paint is fair. Oiled surface on deck is in good condition.	
Br. No. 229-2870-0372 Wisconsin Creek	57' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Oiled surface on deck is in good condition. One checked stringer.	
Br. No. 229-2870-0498 Jefferson River	358.3' Steel Pony Truss
Paint Condition: Good to Poor	General Condition: Good
Remarks: Concrete surface of top and sides of piers at bearing seats is deteriorating. End posts and tower span surfaces show crazing and cracking. There is a vertical crack in Pier 2 and both piers are eroding at the water line.	
Br. No. 229-2870-0499 Irrigation Ditch	25' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Oiled surface on deck is in good condition.	
Br. No. 229-2870-0509 Drainage	25' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Oiled surface on deck is in good condition.	

Br. No. 229-0410-0519	Drainage	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface on deck is in good condition.		
Br. No. 229-0410-0521	Drainage	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface on deck is in good condition. Some stringers checked.		
Br. No. 229-0410-0522	Irrigation Ditch	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Center checks in one stringer running together and starting to form a central crack. Oiled surface on deck is in good condition.		
Br. No. 229-0410-0533	Irrigation Ditch	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface on deck is in good condition.		
Br. No. 229-0410-0536	Cherry Creek	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface on deck is in good condition.		
Br. No. 229-0410-0571	Little Cherry Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface on deck is in good condition.		
Field Maintenance Division No. 202		Silver Bow County
Br. No. 247-0410-0015	Fish Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface on deck is in good condition.		
Field Maintenance Division No. 201		Jefferson County
Br. No. 222-0410-0033	C.M.ST.P. & P. R..R.	135.5' Steel Beam
Paint Condition: Good		General Condition: Good
Remarks: Deck concrete surface in good condition.		
Br. No. 222-0410-0057	Little Pipestone Creek	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Two rail ends and curb traffic scuffed and split. Oiled surface on deck is in good condition.		

FEDERAL AID PRIMARY ROUTE 30

Field Maintenance Division No. 402
Br. No. 246-0050-0114 Dahl Creek
Paint Condition: Good

Sheridan County
57' Treated Timber Trestle
General Condition: Good

Br. No. 246-0050-0143 Main Creek
Paint Condition: Good

95' Treated Timber Trestle
General Condition: Good

Br. No. 246-0050-0153 Dry Creek
Paint Condition: Good

25' Treated Timber Trestle
General Condition: Good

Br. No. 246-0050-0171 Shallow Creek
Paint Condition: Good

76' Treated Timber Trestle
General Condition: Good

FEDERAL AID PRIMARY ROUTE 31

Field Maintenance Division No. 402
Br. No. 210-0130-0037 South Fork Whitetail Creek
Paint Condition: Fair

Daniels County
76' Treated Timber Trestle
General Condition: Good

Br. No. 210-0130-0063 Whitetail Creek
Paint Condition: Fair

76' Treated Timber Trestle
General Condition: Good

Br. No. 210-0130-0070 North Fork Whitetail Creek
Paint Condition: Fair

38' Treated Timber Trestle
General Condition: Good

FEDERAL AID PRIMARY ROUTE 32

Field Maintenance Division No. 402
Br. No. 243-0130-0081 Tule Creek
Paint Condition: None required
Remarks: Drift has wore concrete into re-bars at high water line on all columns.

Roosevelt County
89' Concrete T Beam
General Condition: Good

Br. No. 243-0130-0120 Bittner Coulee
Paint Condition: Fair

38' Treated Timber Trestle
General Condition: Good

Br. No. 243-0130-0147 South Fork Chelsea Creek
Paint Condition: Fair

57' Treated Timber Trestle
General Condition: Good

Br. No. 243-0130-0153 Chelsea Creek
Paint Condition: Fair

76' Treated Timber Trestle
General Condition: Good

Br. No. 243-0130-0203 Box Elder Creek
Paint Condition: Fair
Remarks: Rail shows a hump in grade.

95' Treated Timber Trestle
General Condition: Good

Br. No. 243-0130-0218 North Fork Box Elder Creek
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

Br. No. 243-0130-0276 Spague Coulee
Paint Condition: Good

76' Treated Timber Trestle
General Condition: Good

Br. No. 243-0130-0301 Midway Coulee
Paint Condition: Fair

57' Treated Timber Trestle
General Condition: Good

Br. No. 243-0130-0337 West Fork Poplar River
Paint Condition: Fair

76' Treated Timber Trestle
General Condition: Good

Br. No. 243-0130-0341 West Fork Poplar River
Paint Condition: Fair

114' Treated Timber Trestle
General Condition: Good

Br. No. 243-0130-0343 West Fork Poplar River
Paint Condition: Fair

185' Steel Pony Truss
General Condition: Good

Field Maintenance Division No. 402
Br. No. 210-0130-0029 Nielson Coulee
Paint Condition: Good

Daniels County
38' Treated Timber Trestle
General Condition: Good

Br. No. 210-0130-0057 Belknap Creek
Paint Condition: Fair

57' Treated Timber Trestle
General Condition: Good

Br. No. 210-0130-0087 Dickinson Coulee
Paint Condition: Fair

38' Treated Timber Trestle
General Condition: Good

Br. No. 210-0130-0099 Bricker Coulee
Paint Condition: Fair

76' Treated Timber Trestle
General Condition: Good

Br. No. 210-0130-0114 Poplar River
Paint Condition: Good

185' Steel Truss
General Condition: Good

Br. No. 210-0130-0129 Manternach Coulee
Paint Condition: Fair

57' Treated Timber Trestle
General Condition: Good

FEDERAL AID PRIMARY ROUTE 33

Field Maintenance Division No. 101
Br. No. 227-0370-0006 G. N. Railway
Paint Condition: Good
Remarks: Bridge signs need repainting.

Lincoln County
271' Continuous Steel Beam
General Condition: Good

Br. No. 227-0370-0007 Kootenai River
Paint Condition: Good
Remarks: Bridge signs are gone from end posts.

698' Riveted Plate Girder
General Condition: Good

Br. No. 227-0370-0385 Parsnip Creek
General Condition: Good
Remarks: Underside good.

23.8' Steel Girder

Br. No. 227-0370-0433 Big Creek
Paint Condition: Poor-Rail; Fair to Poor-Metal
Remarks: Small rust spots all along the flange and lower part of girder web.

60' Steel Girder
General Condition: Good

Br. No. 227-0370-0548 Kootenai River
Paint Condition: Fair to Poor on Rail; Good to Poor on Structural Steel
General Condition: Fair

482.5' Steel Truss

Remarks: Steel sheet casing on center pier above water has broken open and is hanging from pier. Re-steel is exposed below bottom of web wall. Some spalling of the cap surface. At west end, the shoulder fills are sloughing out. At the west portal, the sway brace has been hard hit and is bent downward restricting the vertical clearance.

Br. No. 227-0370-0583 Tobacco River
Paint Condition: Good

130' Steel Pony Truss
General Condition: Good

Remarks: Northwest curb end broken and re-steel exposed. Concrete above transverse floor beams at deck edges lightly chipped out. Some rust spots on metal rail.

FEDERAL AID PRIMARY ROUTE 35

Field Maintenance Division No. 101		Ravalli County
Br. No. 241-0380-0010	Republican Ditch	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Curb end reflectors for approach lanes are gone. Reflectors on each opposite curb ends. Oiled surface good.		
Br. No. 241-0380-0017 Hedges Ditch		25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Reflectors on curb end for approach lanes are gone. Oiled surface good.		
Br. No. 241-0380-0029 Skalkaho Creek		76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Plank spiked to stream face of east bent piles to retain roadway fill. West side below original backing plank is open and rock fill is beginning to slide out. Oiled surface is good.		
Br. No. 241-0380-0046 Bitterroot Valley Irrigation Ditch		50' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Plank spiked to ditch side of piles to retain roadway fill. Oiled surface is intact.		
Field Maintenance Division No. 101		Granite County
Br. No. 220-0380-0100	West Fork Rock Creek	45' Steel Pony Truss
Paint Condition: Good		General Condition: Good
Remarks: Concrete at face of abutments spalling off under all truss shoes.		
Br. No. 220-0380-0133	West Fork Rock Creek	45' Steel Pony Truss
Paint Condition: Good		General Condition: Poor
Remarks: Paint on superstructure is good, poor on lower chords of truss. Due to disintegration and spalling of concrete at face of both abutments under the truss shoes, approximately 30% to 50% of the bases of the bearing plates are unsupported. There is a vertical crack in the east abutment just inside the junction with the south wing. Bridge structure is good. Reported poor on account of condition at bearing plates. Under side of 2"x4" laminated deck looks good.		
Br. No. 220-0380-0159	Rock Creek	139.7' Concrete T Beam
General Condition: Good		
Remarks: Erosion of Bent 2 from west, at water line, heavier on Bent 3. Some disintegration of concrete surfaces along the south deck edge and at curb ends at expansion joints. All end posts are disintegrating, one intermediate post top broken and one rail unit broken. Portion of deck not snow or ice covered indicate deck to be in good condition.		
Br. No. 220-0380-0250	Trout Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Bridge markers painted over.		
Br. No. 220-0380-0276	Irrigation Ditch	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 220-0380-0279 Flint Creek 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: North half of deck is exposed and is wearing. West end rail posts back
of flared terminal posts are split in two and one rail end is damaged.

FEDERAL AID PRIMARY ROUTE 36

Field Maintenance Division No. 101 Sanders County
Br. No. 245-0280-0196 Hot Springs Creek 50' Prestressed Concrete Beams
Paint Condition: Good General Condition: Good
Remarks: One flared rail end bent.

Br. No. 245-0280-0267 Little Bitterroot River 57' Treated Timber Trestle
Paint Condition: Good, except on a few rail lengths.
General Condition: Good

Field Maintenance Division No. 102 Flathead County
Br. No. 215-0280-0008 Sullivan Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: End bent piles have been pushed in and top of north piles are in 5"
from inside cap face. South side piles are in $3\frac{1}{2}$ " to 5" from inside
face of cap. The piles have moved away from the top backing plank at
each bent.

FEDERAL AID PRIMARY ROUTE 37

Field Maintenance Division No. 501

Big Horn County

Br. No. 102-2120-0001 I-90 (Crow Agency Interchange)

209.5' Prestressed Concrete Beams

Remarks: See FAP Route 16 - Br. No. 102-0870-0418

Br. No. 102-2120-0082	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Cracked stringer, fourth in last span.		
Br. No. 102-2120-0094	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0129	West Fork Tullock Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0147	Drainage	76' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0157	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0165	Drainage	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0171	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Cracked stringer, fourth one, third span.		
Br. No. 102-2120-0250	Rosebud Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0256	Busby Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0279	Park Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0284	Drainage	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0293	East Porcupine Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0303	Two Moon Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0314	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0322	Killsnight Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 102-2120-0337	Ridgewalker Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 102-2120-0368	Muddy Creek	95' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Field Maintenance Division No. 502		Rosebud County
Br. No. 144-2120-0033	Lame Deer Creek	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 144-2120-0226	Tongue River	200' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Good sized chip knocked out of column Bent 1 left. A few honeycomb spots near water line Pier 2.		
Br. No. 144-2120-0244	Otter Creek	112' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Field Maintenance Division No. 502		Powder River County
Br. No. 138-2120-0032	East Fork Otter Creek	81' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 138-2120-0082	Drainage	38' Treated Timber Trestle
Remarks: Not inspected 1962.		
Br. No. 138-2120-0092	Drainage	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good

FEDERAL AID PRIMARY ROUTE 38

Field Maintenance Division No. 102
Br. No. 215-0400-0016 Whitefish River Flathead County
Paint Condition: Good 138' Steel Beam
General Condition: Good
Remarks: Excessive deterioration of a number of rail units and end posts. Some spalling of concrete on outside deck edges and curb ends at joints.

Br. No. 215-0400-0078 Flathead River 496' Steel Truss
Paint Condition: Fair General Condition: Good
Remarks: East portal and adjoining sway brace are bent. Fill sloughing out from behind the cap of the east bent.

FEDERAL AID PRIMARY ROUTE 39

Field Maintenance Division No. 302
Br. No. 218-0170-0121 Lee Creek Glacier County
208' Continuous Steel Beam
Remarks: Road barricaded and signed "Road Closed" due to snow.

FEDERAL AID PRIMARY ROUTE 40

Field Maintenance Division No. 301
No Bridges Cascade County

FEDERAL AID PRIMARY ROUTE 41

Field Maintenance Division No. 301
Br. No. 107-0875-0046 G. N. Railway Cascade County
109' Concrete T Beam
General Condition: Good

Br. No. 107-0875-0047 FAP Route 3-Spur Underpass
Paint Condition: Good General Condition: Good
Remarks: Crossing under Number 7 Span (=6th Steel Span) Missouri River
Bridge #107-0910-0009. See FAS 226 Br. No. 226-07-0001

Br. No. 107-0875-0055 G. N. Railway Underpass
Paint Condition: Fair General Condition: Good

Br. No. 107-0875-0058 FAP Route 10 Underpass
General Condition: Underpass Span Good
Remarks: Span concrete girders chipped by high loads.

Br. No. 107-0875-0059 C.M.ST.P.&P. R.R. Underpass
Paint Condition: Good to Fair General Condition: Good

FEDERAL AID PRIMARY ROUTE 42

Field Maintenance Division No. 401
Br. No. 228-0240-0034 Timber Creek
Paint Condition: Good

McGone County
204.5' Prestressed Concrete Beams
General Condition: Good

Field Maintenance Division No. 402
Br. No. 253-0240-0056 Barton Coulee
Paint Condition: Good

Valley County
57' Treated Timber Trestle
General Condition: Good

Br. No. 253-0240-0064 Galpin Coulee
Paint Condition: Good

76' Treated Timber Trestle
General Condition: Good

Br. No. 253-0240-0080 Galpin Coulee
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 253-0240-0134 Canal
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

Br. No. 253-0240-0155 Milk River Overflow
Paint Condition: Good

152' Treated Timber Trestle
General Condition: Good

Br. No. 253-0240-0156 Milk River
Paint Condition: Fair

472.7' Steel Thru Truss
General Condition: Good

Remarks: Rockers in extreme expansion position at +18°. Nuts gone from rocker bolts. South portal has been hit and bent.

Br. No. 253-0240-0170 Sprague Coulee
Paint Condition: Fair

57' Treated Timber Trestle
General Condition: Good

Br. No. 253-0240-0190 G. N. Railway
Paint Condition: Fair

Underpass
General Condition: Good

Remarks: Much general spalling of edges of concrete. Patchwork done on spalled spots not holding in place.

FEDERAL AID PRIMARY ROUTE 43

Field Maintenance Division No. 403
Br. No. 214-0190-0001 Spring Creek
Paint Condition: Good

Fergus County
33.7' Concrete Slab
General Condition: Good

Br. No. 214-0190-0007 Spring Creek
Paint Condition: None needed

63' Concrete T Beam
General Condition: Good

Remarks: Mild spalling in various places. Edges of rail and wing walls and nose of center pier cap.

Br. No. 214-0190-0101 Warm Springs Creek
Paint Condition: Fair

38' Treated Timber Trestle
General Condition: Good

Br. No. 214-0190-0381 Box Elder Creek
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 214-0190-0387 Box Elder Creek
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Remarks: Power line underneath touches wood and could be a fire hazard.

FEDERAL AID PRIMARY ROUTE 45

Field Maintenance Division No. 202

Br. No. 249-0190-0008 N. P. Railway

Paint Condition: Good

Remarks: Light cracks in wing walls.

Sweet Grass County

Underpass

General Condition: Good

Br. No. 249-0190-0010 Yellowstone River

Paint Condition: Good

Remarks: Montana State Highway plaque previously reported as half torn off is now set properly on the end post.

379.8' Continuous Steel Girder

General Condition: Good

Br. No. 249-0190-0018 Big Timber Creek

General Condition: Good

Remarks: One bridge sign broken. Cracks in some girder haunches. Rocker shoes were never painted field coats of paint.

137.3' Concrete T Beam

Br. No. 249-0190-0097 Drainage

Paint Condition: Good

Remarks: Lower portion of north side grouted riprap starting to break up.

57' Treated Timber Trestle

General Condition: Good

Br. No. 249-0190-0100 South Fork Ten Mile Creek

Paint Condition: Good

63' Treated Timber Trestle

General Condition: Good

Br. No. 249-0190-0114 Ten Mile Creek

Paint Condition: Good

57' Treated Timber Trestle

General Condition: Good

Br. No. 249-0190-0140 Wheeler Creek

Paint Condition: Good

63' Treated Timber Trestle

General Condition: Good

Br. No. 249-0190-0152 Drainage

Paint Condition: Good

Remarks: Stringer previously reported broken, has been repaired with a series of steel base plates with bolts up through the deck.

57' Treated Timber Trestle

General Condition: Good

Br. No. 249-0190-0163 Otter Creek

Paint Condition: Good

88' Treated Timber Trestle

General Condition: Good

Br. No. 249-0190-0181 Drainage

Paint Condition: Good

57' Treated Timber Trestle

General Condition: Good

Br. No. 249-0190-0183 Sweet Grass Creek

Paint Condition: Good

Remarks: Some surface erosion on Pier 1.

184' Continuous Steel Girder

General Condition: Good

Br. No. 249-0190-0204 Cayuse Creek

Paint Condition: Good

Remarks: North side riprap cracking.

38' Treated Timber Trestle

General Condition: Good

Field Maintenance Division No. 403

Br. No. 254-0190-0009 Fish Creek

Paint Condition: Good

Remarks: One east side sway brace in each of the two tower spans is broken out.

Wheatland County

113' Treated Timber Trestle

General Condition: Good

Br. No. 254-0190-0033 Drainage

Paint Condition: Good

38' Treated Timber Trestle

General Condition: Good

Br. No. 254-0190-0045	South Fork of American Fork	28.6' Concrete and Steel I Beam
Paint Condition:	Good	General Condition: Good
Br. No. 254-0190-0047	American Fork	40' Concrete T Beam
Paint Condition:	Good	General Condition: Good
Remarks:	Bridge sign reads American Creek.	
Br. No. 254-0190-0082	Dry Wash	25' Treated Timber Trestle
Paint Condition:	Good	General Condition: Good
Remarks:	North side hand laid riprap breaking up.	
Br. No. 254-0190-0087	Lebo Creek	25' Treated Timber Trestle
Paint Condition:	Good	General Condition: Good
Br. No. 254-0190-0098	Spring Creek	25' Treated Timber Trestle
Paint Condition:	Good	General Condition: Good
Br. No. 254-0190-0151	Musselshell River	190' Continuous Steel Cantilever
Paint Condition:	Fair	General Condition: Good
Remarks:	Steel road oil spattered from drip when deck was surfaced.	
Br. No. 254-0190-0153	C.M.ST.P.&P. R.R.	186' Steel Pony Truss
Paint Condition:	Good	General Condition: Good
Remarks:	Some wear on deck. Surface texture slightly roughened.	
Br. No. 254-0190-0345	G. N. Railway	200' Continucus Steel Girder
Paint Condition:	Good	General Condition: Good
Field Maintenance Division No. 403		Fergus County
Br. No. 214-0190-0016	Drainage	38' Treated Timber Trestle
Paint Condition:	Good	General Condition: Good
Remarks:	Bridge signed "Ross Fork Creek".	
Br. No. 214-0190-0020	Ross Fork	25' Treated Timber Trestle
Paint Condition:	Good	General Condition: Good
Remarks:	Signed "Ross Fork Creek".	
Br. No. 214-0190-0112	Buffalo Creek	25' Treated Timber Trestle
Paint Condition:	Good	General Condition: Good
Field Maintenance Division No. 403		Judith Basin County
Br. No. 223-0190-0012	Little Trout Creek	57' Treated Timber Trestle
Paint Condition:	Good	General Condition: Good
Field Maintenance Division No. 403		Fergus County
Br. No. 214-0190-0179	C.M.ST.P.&P. R.R.	240.8' Concrete T Beam
General Condition:	Good	

FEDERAL AID PRIMARY ROUTE 46

Field Maintenance Division No. 201		Beaverhead County
Br. No. 201-0430-0064	Trail Creek	38' Reinforced Concrete Girder
Remarks: Road closed by snow. Not inspected.		
Br. No. 201-0430-0090 Trail Creek		60' Reinforced Concrete Slab
Remarks: Not inspected. Road closed due to snow.		
Br. No. 201-0430-0098 Trail Creek		60' Reinforced Concrete Slab
Remarks: Not inspected. Road closed due to snow.		
Br. No. 201-0430-0141 Trail Creek		60' Reinforced Concrete Slab
Remarks: Not inspected. Road closed due to snow.		
Br. No. 201-0430-0158 Ruby Creek		60' Reinforced Concrete Slab
Remarks: Not inspected. Road closed due to snow.		
Br. No. 201-0430-0249 Big Hole River		214.5' Prestressed Concrete Beam
Remarks: Under contract - Let 7-19-61		
Br. No. 201-0430-0283 Steel Creek		38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface on deck in good condition.		
Br. No. 201-0430-0420 Big Hole River		234.5' Prestressed Concrete Beam
Paint Condition: Good		General Condition: Good
Remarks: Deck sealed and chipped and in good condition.		
Field Maintenance Division No. 201		Deer Lodge County
Br. No. 212-0430-0066	Fishtrap Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: New plant mix surface on deck. Oiled surface to top of curbs.		
Br. No. 212-0430-0082 LaMarche Creek		81' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Lower plank Pier 2 not bolted to piling. New plant mix surface on deck.		
Br. No. 212-0430-0112 Seymour Creek		38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Northeast reflector broken off at ground line. Reflector set against end post temporarily. Bent 3 cap has only partial bearing on northeast pile. New plant mix surface on deck.		
Br. No. 212-0430-0124 Deep Creek		75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Southeast top rail end split and reflector gone. New plant mix surface on deck.		
Field Maintenance Division No. 102		Silver Bow County
Br. No. 247-0430-0017	Big Hole River	325' Riveted Steel Plate Girder
Paint Condition: Good		General Condition: Good
Remarks: Oiled surface treatment on deck surface is partially worn off. Deck is in good condition.		

Field Maintenance Division No. 201 Beaverhead County
Br. No. 201-0430-0651 Branch Wise River 29' Steel I Beam
Paint Condition: Fair to Poor General Condition: Good
Remarks: Concrete spalled off under one end of an exterior girder. Underside of deck good. New plant mix surface on deck. Paint on exterior face of both exterior girders and on all bottom flanges is poor. Concrete eroded at water line of east abutment.

Br. No. 201-0430-0653 Branch Wise River 44.2' Steel I Beam
Paint Condition: Fair to Poor General Condition: Good
Remarks: Section of concrete rail topping at northwest end has peeled off. Concrete under both west ends of exterior girders and at east end of south exterior girder has spalled off. Underside of deck good. New plant mix surface on deck. Paint on exterior face of exterior girders and all bottom flanges is poor.

Br. No. 201-0430-0654 Branch Wise River 42.8' Steel I Beam
Paint Condition: Fair to Poor General Condition: Good
Remarks: Piece of concrete at face bearing seat at northwest end of exterior girders has spalled off. Underside of deck is good. One wing rail broken and pushed out about 3". Paint on outside face of exterior girders and on bottom flanges is poor. Oil mat on deck is good.

Br. No. 201-0430-0741 Big Hole River 232' Thru Steel Truss
Paint Condition: Fair to Good General Condition: Good
Remarks: One diagonal and one vertical truss members hit and channel edge bent. Batter column, end panel west truss section, edge bent. Southwest end rail section bent over batter column. A few knee braces hit and slightly bent. Underside of pony truss deck good. Underside of thru truss spans have scattered spalled areas where a few re-bars are exposed. Oil mat on deck is in good condition. Some deterioration of curb ends and south side pier top edge and face.

Field Maintenance Division No. 201 Silver Bow County
Br. No. 247-0430-0031 Divide Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Some substructure nuts and washers missing.

FEDERAL AID PRIMARY ROUTE 47

Field Maintenance Division No. 201 Deer Lodge County
Remarks: No Bridges

FEDERAL AID PRIMARY ROUTE 48

Field Maintenance Division No. 501
Br. No. 202-0470-0009 Drainage
Paint Condition: Good

Big Horn County
25' Treated Timber Trestle
General Condition: Good

Br. No. 202-0470-0015 Drainage
Paint Condition: Good

68' Treated Timber Trestle
General Condition: Good

Br. No. 202-0470-0055 Low Line Ditch
Paint Condition: Good

31' Treated Timber Trestle
General Condition: Fair

Remarks: Badly burned underneath about 1 $\frac{1}{4}$ " of charred lumber.

Br. No. 202-0470-0075 Drainage
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

Br. No. 202-0470-0081 Low Line Ditch
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

Remarks: One span so low to ground it can't be looked at.

Br. No. 202-0470-0083 Low Line Ditch
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 202-0470-0114 Drain Ditch
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

FEDERAL AID PRIMARY ROUTE 49

Field Maintenance Division No. 201
Br. No. 201-0410-0071 Irrigation Ditch
Paint Condition: Good

Beaverhead County
25' Treated Timber Trestle
General Condition: Good

Br. No. 201-0410-0091 Stone Creek
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

Remarks: One broken stringer in north span has been reinforced with an additional stringer set in along side. Area under bridge in front of end bents appears to have been cleaned out and leveled up for use by adjacent landowner. Bottom of channel is 3' below bottom backing plank. The fill on the north side is out for 1' above lower plank and extends back 2' so that fill is free to run as loosened.

Field Maintenance Division No. 201
Br. No. 229-0410-0010 Beaverhead River
Paint Condition: Good
Remarks: Rail and posts, downstream side, lightly traffic scarred.

Madison County
150' Steel Girder
General Condition: Good

Br. No. 229-0410-0138 Beaverhead River
Paint Condition: Good

180.6' Steel Girder
General Condition: Good

Remarks: Aluminum coat of paint is wearing off top rail exposing undercoat, otherwise, paint is good. One north side rail picket broken loose from lower rail.

FEDERAL AID PRIMARY ROUTE 50

Field Maintenance Division No. 202
Br. No. 116-1910-0037 Madison River
General Condition: Fair

Gallatin County
133.8' Concrete Girder

Remarks: There does not seem to be any further progression in the damage previously reported, caused by the 1959 earthquake. The spalled off concrete, west end bent, at top of columns and ends of concrete girders, has exposed the column corner bars and the bottom bar layer of the beams. Pier 2 is eroded at the water line.

Br. No. 116-1910-0076 Cougar Creek
General Condition: Poor

34.8' Concrete Girder

Remarks: At the construction joint between the column tops and concrete girder seats where the concrete was shattered, as previously reported by the 1959 earthquake exposing re-steel, there does not seem to be much change. It has been necessary to maintain the roadway fill adjacent to the end bent backwalls and this is now stabilized. The underside of the deck and girders above the breaks look good.

Br. No. 116-1910-0082 Duck Creek
General Condition: Fair

88.8' Concrete Girder

Remarks: There are numerous cracks of various degrees of tightness distributed over the various members of the bridge, however, the structure appears to be in fair condition to continue serving existing traffic.

Br. No. 116-1910-0099 Grayling Creek
Paint Condition: Good

104.9 Reinforced Concrete Girder
General Condition: Good

Remarks: This structure widened, contract let May, 1961.

Br. No. 116-1910-0234 West Gallatin River
Paint Condition: Good

120' Continuous Concrete T Beam
General Condition: Good

Br. No. 116-1910-0262 Specimen Creek
Paint Condition: Good

63.7' Continuous T Beam
General Condition: Good

Remarks: Paint good except for some abrasion on pickets due to chips thrown off oiled surface.

Br. No. 116-1910-0325 West Gallatin River
Paint Condition: Good

122' Concrete Girder
General Condition: Good

Remarks: Bridge rail paint has been touched up where required.

Br. No. 116-1910-0337 Taylor Creek
Paint Condition: Good

70' Cantilever Concrete Girder
General Condition: Good

Br. No. 116-1910-0479 West Fork Creek
Paint Condition: Fair to Good

80' Cantilever Concrete Girder
General Condition: Good

Remarks: On some areas along top of rail and on a few pickets, the aluminum coat is worn exposing under coat of paint.

Br. No. 116-1910-0497 West Gallatin River
Paint Condition: Fair to Poor

160' Concrete T Beam
General Condition: Good

Remarks: Heavy abrasions and flaking off of aluminum coat from bottom rail and pickets show rust spots. On the top rail the prime coat is showing through the worn aluminum finish coat.

Br. No. 116-1910-0572	Swan Creek	54' Reinforced Concrete
Paint Condition: Fair		General Condition: Good
Remarks: Prime coat paint showing on parts of top rail. Considerable flaking and abrasions on pickets due to flying rock chips from oiled surface.		
Br. No. 116-1910-0613	West Gallatin River	234.3' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Aluminum paint wearing off on sections of rail exposing prime coat. Structural steel paint is good.		
Br. No. 116-1910-0680	Spanish Creek	68.6' Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: On sections of top rail the aluminum coat is wearing off exposing the prime coat. Some abrasion of rail and pickets due to battering by rock chips.		
Br. No. 116-1910-0703	West Gallatin River	260' Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Drift collecting at north pier.		
Br. No. 116-1910-0781	Canal	20' Concrete Slab
Paint Condition: Good		General Condition: Good
Remarks: End and top of wing walls and curbs beginning to disintegrate.		
Br. No. 116-1910-0834	Middle Creek	30' Concrete Girder
Paint Condition: Good		General Condition: Good

FEDERAL AID PRIMARY ROUTE 51

Field Maintenance Division No. 401	McCone County
Br. No. 228-0200-0004	Buffalo Springs Creek 88' Treated Timber Trestle
Paint Condition: Good	General Condition: Good

Br. No. 228-0200-0072	Cottonwood Creek	88' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Field Maintenance Division No. 401	Dawson County
Br. No. 211-0200-0024	Drainage 88' Treated Timber Trestle
Paint Condition: Good	General Condition: Good

Br. No. 211-0200-0053	Drainage	88' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 211-0200-0090	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Field Maintenance Division No. 401	Richland County
Br. No. 242-0200-0372	U.S.R.S. Canal 75' Treated Timber Trestle
Paint Condition: Poor	General Condition: Poor
Remarks: Badly burned underneath and upstream rail. Charred lumber about 1" thick under deck and some rail posts are $\frac{1}{2}$ charred lumber.	

FEDERAL AID PRIMARY ROUTE 52

Field Maintenance Division No. 102	Flathead County
Br. No. 215-0350-0027	Swan River 219.8' Continuous Steel Girder
Paint Condition: Good	General Condition: Good

Br. No. 215-0350-0071	Drainage	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 215-0350-0126	Mill Creek	95' Treated Timber Trestle
Remarks: Three of the corner posts back of the flared end terminal posts are split in two.		

FEDERAL AID PRIMARY ROUTE 53

Field Maintenance Division No. 501

Br. No. 256-0020-0011 E.B.W.A. Canal

Paint Condition: None needed

Yellowstone County

35' Treated Timber Trestle

General Condition: Good

Br. No. 256-0030-0088 South Fork Alkali Creek

Paint Condition: Good

95' Treated Timber Trestle

General Condition: Good

Br. No. 256-0030-0109 North Fork Alkali Creek

Paint Condition: Good

57' Treated Timber Trestle

General Condition: Good

Br. No. 256-0030-0136 South Fork Five Mile Creek

Paint Condition: Good

76' Treated Timber Trestle

General Condition: Good

Br. No. 256-0030-0137 North Fork Five Mile Creek

Paint Condition: Good

57' Treated Timber Trestle

General Condition: Good

Field Maintenance Division No. 501

Br. No. 219-0030-0026 Dry Wash

Paint Condition: Good

Golden Valley County

57' Treated Timber Trestle

General Condition: Good

Br. No. 219-0030-0030

Dry Wash

Paint Condition: Good

25' Treated Timber Trestle

General Condition: Good

Br. No. 219-0030-0050

Dry Wash

Paint Condition: Good

76' Treated Timber Trestle

General Condition: Good

Br. No. 219-0030-0056

Painted Robe Creek

Paint Condition: Good

95' Treated Timber Trestle

General Condition: Good

Br. No. 219-0030-0106

Big Coulee Creek

Paint Condition: Good

101' Prestressed Concrete Beams

General Condition: Good

Br. No. 219-0030-0112

Musselshell River

Paint Condition: Good

143' Prestressed Concrete Beams

General Condition: Good

FEDERAL AID SECONDARY ROUTE 201

Field Maintenance Division No. 402
Br. No. 201-28-0133 Redwater River
Paint Condition: Good

McCone County
321' Concrete T Beam
General Condition: Good

Field Maintenance Division No. 402
Br. No. 201-42-0588 North Fork Hay Creek
Paint Condition: Good

Richland County
76' Treated Timber Trestle
General Condition: Good

Br. No. 201-42-0633 Second Hay Creek
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 201-42-0693 Main Canal
Paint Condition: Poor
Remarks: One rail section busted.

51' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 202

Field Maintenance Division No. 101
Br. No. 202-45-0218 Bull River
General Condition: Good

Sanders County
78.8' Concrete Slab

Br. No. 202-45-0313 Bull River
Paint Condition: Good

83' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 203

Field Maintenance Division No. 101
Br. No. 203-41-0052 Bitterroot River
Paint Condition: Good

Ravalli County
374' Riveted Plate Girder
General Condition: Good

Remarks: Shoulder fill sloughing and washing out at south side of bridge ends, especially on the west. The west side opening extends in 1.5' from curb face, 2.0' out and approximately 1.5' to 3.0' deep. The same condition to a lesser degree exists on the east bridge end.

Br. No. 203-41-0055 Drainage
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 204

Field Maintenance Division No. 402
Br. No. 204-36-0013 Milk River
Paint Condition: Good

Phillips County
240' Steel Plate Girder
General Condition: Good

Br. No. 204-36-0014 U.S.R.S. Canal
Paint Condition: Good

63' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 206

Remarks: No bridges

FEDERAL AID SECONDARY ROUTE 207

Remarks: No bridges

FEDERAL AID SECONDARY ROUTE 208

Field Maintenance Division No. 102
Br. No. 208-15-0058 Flathead River Flathead County
686' Steel Girder
Paint Condition: Good General Condition: Good
Remarks: Shoulder fill at end of curbs and along faces of end posts, west end of structure, is sloughing out and should be back filled. Similar condition starting at southeast curb end.

FEDERAL AID SECONDARY ROUTE 209

Field Maintenance Division No. 102
Br. No. 209-15-0037 Swan River Flathead County
251' Steel Howe Truss
Paint Condition: Good General Condition: Poor
Remarks: Paint on structural steel is good. No paint on timber rail. Southeast end vertical hanger rods have been broken above the eyes and repaired by welding. The rods have been reinforced with a 3/4" cable clamped around the top to bottom pins. Bridge posted: Speed limit 10 m.p.h.; G.V.W. 10 tons; One-lane traffic.

Field Maintenance Division No. 102
Br. No. 209-24-0058 Swan River Lake County
255' Timber Trestle
Paint Condition: Good General Condition: Fair
Remarks: Bridge posted: Load Limit 10 Tons. Some recent work has been done on west end span, a new stringer and solid bridging has been set in.

Br. No. 209-24-0214 Lost Creek
Paint Condition: Good
Remarks: This bridge has been raised. A new deck has been constructed above the original 2"x6" laminated deck and is decked with 2" plank.

Br. No. 209-24-0300 Goat Creek
Paint Condition: Fair to Poor
57' Treated Timber Trestle
General Condition: Good

Br. No. 209-24-0346 Lion Creek
Paint Condition: Fair to Poor
69' Treated Timber Trestle
General Condition: Good

Field Maintenance Division No. 101
Br. No. 209-32-0530 Holland Creek Missoula County
57' Treated Timber Trestle
Paint Condition: Poor General Condition: Good

Br. No. 209-32-0808 Morrell Creek
Paint Condition: Poor
Remarks: Bridge signs need repainting.
75' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 211

No bridges.

FEDERAL AID SECONDARY ROUTE 212

Field Maintenance Division No. 101
Br. No. 212-24-0124 Post Creek (Rd Plans) Lake County
Paint Condition: Good
Remarks: Mission Creek on county map.
75' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 213

No bridges.

FEDERAL AID SECONDARY ROUTE 214

Field Maintenance Division No. 302
Br. No. 214-51-0001 I 15 Sunburst Interchange Underpass
Remarks: See FAP Route 21 # 151-0910-0354

Toole County

FEDERAL AID SECONDARY ROUTE 215

No bridges.

FEDERAL AID SECONDARY ROUTE 216

Field Maintenance Division No. 301
Br. No. 216-37-0053 Soberup Creek
Paint Condition: Good
Remarks: No reflectors. No bridge signs.

Pondera County
57' Treated Timber Trestle
General Condition: Good

Br. No. 216-37-0095 Dupuyer Creek
Paint Condition: Good
Remarks: Fill at northwest curb end is sloughing out. Fill is starting to run out from behind the cap of the west bent and it is now open about 9" wide between columns and extends up 1' from base of cap.

150' Treated Timber Trestle
General Condition: Good

Br. No. 216-37-0117 Irrigation Canal
Paint Condition: Good
Remarks: At center bent the cap is split diagonally across the bottom above the second pile from the south. The split runs 2' to 3' each side of pile head.

38' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 218

Field Maintenance Division No. 302
Br. No. 218-37-0011 Pondera Coulee
Paint Condition: Poor
Remarks: Several rail posts split.

Pondera County
38' Treated Timber Trestle
General Condition: Good

Br. No. 218-37-0107 Pondera Coulee
Paint Condition: Good
Remarks: Reflectors have been placed on all four end posts since previous inspection.

50' Treated Timber Trestle
General Condition: Good

Br. No. 218-37-0199 Drainage
Paint Condition: Poor

22.5' Treated Timber Trestle
General Condition: Good

Field Maintenance Division No. 302
Br. No. 218-26-0295 Pondera Coulee
Paint Condition: Poor
Remarks: Drift collected on bottom, south chord of truss, as reported on previous inspection.

Liberty County
46' Treated Timber Truss
General Condition: Good

FEDERAL AID SECONDARY ROUTE 219

Field Maintenance Division No. 301
Br. No. 219-50-0031 Farmers Coulee
Paint Condition: Fair

Teton County
57' Treated Timber Trestle
General Condition: Good

Field Maintenance Division No. 301
Br. No. 219-37-0176 Drainage
Paint Condition: Poor

Pondera County
38' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 220

No bridges.

FEDERAL AID SECONDARY ROUTE 221

Field Maintenance Division No. 301
Br. No. 221-50-0049 Teton River
Paint Condition: Good

Teton County
267.7' Steel I Beam
General Condition: Good

Remarks: At expansion joint there is a separation of 3/4" between plates.
Bridge signs need repainting. West river pier is eroded on the stream
face and the heel of the pier is more heavily eroded.

FEDERAL AID SECONDARY ROUTE 223

Field Maintenance Division No. 301
Br. No. 223-08-0013 Teton River
Paint Condition: Good

Chouteau County
297.5' Concrete T Beam
General Condition: Good

Field Maintenance Division No. 302
Br. No. 223-26-0379 Marias River
Paint Condition: Poor

Liberty County
360' Thru Steel Truss
General Condition: Poor

Remarks: At the second bent from the south treated timber piles have been set
in on the concrete footing and crossbraced. A number of planks are
toed against the footing and extend back and up against the end bent
built up cap to prevent it from being forced in by the roadway fill.
On the truss span a number of x-bracing are hanging and some stringers
are cracked and others split. At the end bent of the north timber
approach span the embankment on each side has been cut down vertically
for a considerable depth; the cut extends in to the second stringer
on the west side and the third stringer on the east side the end bent
condition cannot be determined as it is in the embankment and an additional
sill of planks has been set under the stringers several feet ahead of
the bent on the central block of embankment, the sides of which are
vertical as noted above. Rail has a few breaks and is old. Signs
are old and need to be repainted. Deck tread is fair to good.

Br. No. 223-26-0435 Drainage
Paint Condition: Poor
Remarks: One rail post split in two.

57' Treated Timber Trestle
General Condition: Good

Br. No. 223-26-0473 Nine Mile Coulee 38' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: Three piles have been set in on the north bent to reinforce dry rotted piles. One broken center bent outside pile is reinforced with small poles each side with through bolts. One inside pile is reinforced with a pile set in on a rock sill. No sway bracing on this bent. Both end wing rail sections, west side, are smashed. Deck surfacing is rough. No load limit posted. No reflectors.

Br. No. 223-26-0500 Cottonwood Creek 76' Untreated Timber Trestle
Paint Condition: Poor General Condition: Fair
Remarks: Northeast end post broken. West pile of second bent from north rotted through just below ground line. The outside piles of the south end bent show considerable dry rot; cores are solid. Surfacing on portions of deck is gone and top longitudinal layer of planking is wearing. No reflectors. Bridge load and speed limit sign on north side only.

FEDERAL AID SECONDARY ROUTE 224

No bridges.

FEDERAL AID SECONDARY ROUTE 225

Field Maintenance Division No. 301 Cascade County
Br. No. 225-07-0024 Drainage 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Paint good except for some scuffing of rails. No reflectors.

Field Maintenance Division No. 301 Chouteau County
Br. No. 225-08-0298 Teton River 152' Steel Pratt Truss
Paint Condition: Poor General Condition: Poor
Remarks: Bridge posted as follows: Slow - Load Limit 20,000# G.V.W., Speed Limit 10 M.P.H.. North side portal timber is gone. Deck and stringers are all intact. North side pier has been pushed toward river by fill and the truss has only partial support on rollers.

FEDERAL AID SECONDARY ROUTE 226

Field Maintenance Division No. 301 Cascade County
Br. No. 226-07-0001 Spur FAP Route 3 (6th Steel Span) Underpass
General Condition: Good
Remarks: Crossing under sixth steel span, Missouri River, Tenth Avenue Bridge. See Spur Route 3, Br. No. 107-0910-0009. See Route 41, Br. No. 107-0875-0046.

Br. No. 226-07-0036 Sand Coulee 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Fill at south end bent is sloughing out from behind the backing plank and the opening is 2.5' to 3.5' wide and approximately 11.0' long and extends up 4.0' from the bottom backing plank, or 6" above the bottom of the cap. There is a heavy oil mat above the opening east side of roadway (northbound lane). Oil mat surface is within 2" of top of curb timber and the combined thickness of oil mat and fill above the opening is approximately 2.5'. Fill at northwest corner is sloughing out under curb flared terminal section. No number on bridge. No reflectors.

FEDERAL AID SECONDARY ROUTE 227

No bridges.

FEDERAL AID SECONDARY ROUTE 228

Field Maintenance Division No. 301 Cascade County
Br. No. 228-07-0105 Red Coulee 57' Treated Timber Trestle
Paint Condition: Fair General Condition: Good
Remarks: Southwest end rail post split. Rail end split. Red Coulee signs need repainting. Deck oiled surface good. No reflectors.

Br. No. 228-07-0164 Belt Creek 186' Steel I Beam
Paint Condition: Poor-Bridge Rail; Good-Steel Girders General Condition: Good
Remarks: Southwest end rail post split. Belt Creek signs need repainting. Surfacing on deck slightly rough but intact for length of bridge. Shoulder fill at northwest corner washing and sloughing out from 2' inside curb and 3' back from end bent. Shoulder fill at northeast corner sloughing out from curb and 1.5' back. The fill behind the bent cross beam adjacent to the east column has run out and there is an opening 3.5' up above base of beam and runs towards center of roadway behind the cap. At the southwest corner the fill has run out from behind the crossbeam and there is an opening about 3'x3' and extends up 4' above the base of the beam.

Field Maintenance Division No. 301 Chouteau County
Br. No. 228-08-0223 Highwood Creek 75' Treated Timber Trestle
Paint Condition: Fair General Condition: Good
Remarks: End of one rail broken off. Deck surfacing intact except for one spot of approximately four square feet at northeast end of deck.

FEDERAL AID SECONDARY ROUTE 230

Field Maintenance Division No. 301 Chouteau County
Br. No. 230-08-0002 G. N. Railway 128' Concrete T Beam
Paint Condition: Good General Condition: Good

Br. No. 230-08-0024 Missouri River 708' Riveted Plate Girder
Remarks: New bridge under construction. Contract let 2-19-61.

Br. No. 230-08-0040 Shonkin Creek 125' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Corner posts cracked.

Br. No. 230-08-0086 Boyle Coulee (O'Hanlon) 75' Treated Timber Trestle
Paint Condition: Poor General Condition: Good
Remarks: Two corner posts split in two.

Br. No. 230-08-0132 Drainage 38' Treated Timber Trestle
Paint Condition: Poor General Condition: Good

Br. No. 230-08-0097 Drainage 57' Treated Timber Trestle
Paint Condition: Poor General Condition: Good
Remarks: One corner post split in two and reflector hanging.

Br. No. 230-08-0322	Drainage	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Piece split off one top rail for one panel length.		
Br. No. 230-08-0331	Flat Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: At south end of deck, the surfacing is worn off two wheel lanes for a length of several feet and the deck is wearing. One cracked stringer, north span, second from east side.		
Br. No. 230-08-0341	Tributary Flat Creek	25' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 230-08-0416	Cowboy Steel Creek	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Four sets of x-bridging, north span, have not been nailed at bottom ends. Two damaged rail ends and cracked posts.		
Br. No. 230-08-0420	Butte Creek	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 230-08-0467	Arrow Creek	250' Treated Timber Trestle
Paint Condition: Good to Poor		General Condition: Good
Remarks: Bridge widened and lengthened. Paint on rail of the widened side (east) is good. Paint on the west side for the two new added spans is good and poor on the original eight spans.		
Field Maintenance Division No. 301		Judith Basin County
Br. No. 230-23-0611	Wolf Creek	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Paint is poor on four panel lengths of rail. Some rail post deeply checked.		

FEDERAL AID SECONDARY ROUTE 231

Field Maintenance Division No. 302		Hill County
Br. No. 231-21-0090	O'Brien Coulee	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Bridge signs need repainting.		
Br. No. 231-21-0138	Little Sage Creek	38' Treated Timber Trestle
Paint Condition: Fair to Poor		General Condition: Good
Remarks: Gravel surfacing worn off and deck wearing.		
Br. No. 231-21-0186	Sage Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Broken stringer repaired with two spaced steel plates with bolts up through the deck.		

FEDERAL AID SECONDARY ROUTE 232

Field Maintenance Division No. 302		Hill County
Br. No. 232-21-0001	G. N. Railway	826.2' Steel I Beam
Paint Condition: Good		General Condition: Fair
Remarks: Extensive surface wear and spalling on deck. Re-steel showing up in numerous places. Rockers out of adjustment and expansion joint Pier 2 nearly closed at +32°. Fire damage about 15% on south timber spans. All blast plates are gone.		

Br. No. 232-21-0002	Milk River	286.6' Steel Truss
Paint Condition: Poor		General Condition: Fair
Remarks: Deck slab on approach span shows extensive wear. North end bent has moved and been repaired. Ten Ton posted limit sign on north end. No sign on south end. Some crossframes of truss have been hit and bent.		

FEDERAL AID SECONDARY ROUTE 233

No bridges.

FEDERAL AID SECONDARY ROUTE 234

Field Maintenance Division No. 302	Hill County
Br. No. 234-21-0020	Scott Coulee Canal
Paint Condition: Fair	95.6' Steel Pony Truss
	General Condition: Good
Remarks: Structurally okay. Wood timbers underneath show a few years age.	

FEDERAL AID SECONDARY ROUTE 235

Field Maintenance Division No. 403	Fergus County
Br. No. 235-14-0004	Warm Springs Creek
Paint Condition: None needed	50' Concrete Slab
	General Condition: Good
Remarks: A few cracks where wing walls connect to main wall. Small chunk of concrete gone from rail.	

Br. No. 235-14-0033	Warm Springs Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 235-14-0085	Irrigation Canal	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Rail has been hit recently and a section busted.		

Br. No. 235-14-0090	Warm Springs Creek	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: One wing rail section has pulled away from structure and split the corner post.		

Br. No. 235-14-0100	Warm Springs Creek	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Three corner posts busted from wing rail sections pulling away.		

Br. No. 235-14-0175	Judith River	177' Steel Girder
Paint Condition: Good		General Condition: Good

Br. No. 235-14-0179	Sage Creek	175' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Barbed wire fence is nailed to stringers.		

Br. No. 235-14-0225	Dry Wolf Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Br. No. 235-14-0299	Wolf Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Cracked stringer fourth in second span.		

Br. No. 235-14-0364	Coffee Creek	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Fair
Remarks: Broken stringer first span fourth one.		

FEDERAL AID SECONDARY ROUTE 236

Field Maintenance Division 403		Fergus County
Br. No. 236-14-0042	Dog Creek	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good

Br. No. 236-14-0063	Little Dog Creek	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Br. No. 236-14-0095	Dog Creek	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Br. No. 236-14-0101	Dog Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Br. No. 236-14-0493	Missouri River	Free Ferry
Remarks: Approximate size 18 x 50. Ferry not working 11-17-61.		

Field Maintenance Division No. 301		Chouteau County
Br. No. 236-08-0552	Chip Coulee	98' Treated Timber Trestle
Paint Condition: Poor		General Condition: Poor
Remarks: Bridge looks old and dilapidated. Some piles at backwall are very rotten. Deck planks are loose. Curb boards are missing.		

Br. No. 236-08-0636	Chip Coulee	52' Treated Timber Trestle
Paint Condition: Poor		General Condition: Poor
Remarks: Piling are rotting fairly bad and one piling is rotted completely in two. Probably structurally safe for some time yet.		

Br. No. 236-08-0660	Chip Coulee	38' Treated Timber Trestle
Paint Condition: Timber was never painted.		
Remarks: One hole through 2x4 deck.		

Br. No. 236-08-0720	Eagle Creek	64' Treated Timber Trestle
Paint Condition: Poor		General Condition: Poor
Remarks: About 1/3 of truss members are bent. Each tension point underneath is supported with two piles and a cap. One of these caps is broken. Steel in the truss is very light gauge metal.		

FEDERAL AID SECONDARY ROUTE 237

Field Maintenance Division No. 403		Fergus County
Br. No. 237-14-0019	Big Springs Creek	50' Steel Howe Truss
Paint Condition: Poor		General Condition: Poor
Remarks: Concrete eroded at low water line Bent 2 exposing steel piling. Steel truss has a broken connection on one vertical member. Rail crooked.		

FEDERAL AID SECONDARY ROUTE 238

Field Maintenance Division No. 403
Br. No. 238-14-0004 Mill Ditch Fergus County
Paint Condition: Good 49' Reinforced Concrete Slab
Remarks: One flared end is gone and some angle iron patched in its place. General Condition: Good

Br. No. 238-14-0192 Drainage 30' Untreated Timber Trestle
Remarks: Road closed from snow 14 miles out. Not inspected.

FEDERAL AID SECONDARY ROUTE 239

Field Maintenance Division No. 301 Judith Basin County
Br. No. 239-23-031 Judith River 65' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: There is a crack across the top of the backwall starting at the stream face and extending from the outside of the curb to junction with the wing wall at both bents on south side. There is a similar but lighter and shorter crack at the northwest corner.

FEDERAL AID SECONDARY ROUTE 240

Field Maintenance Division No. 302 Blaine County
Br. No. 240-03-0015 Milk River 160' Thru. Steel Truss
Paint Condition: Poor General Condition: Fair
Remarks: Wing walls broken at both end bents. Signs gone. Rail bent and portals have been hit.

Br. No. 240-03-0018 Drainage 50' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Now is a 50' Steel I Beam.

Br. No. 240-03-0029 Three Mile Creek 40' Steel I Beam
Paint Condition: Poor General Condition: Good
Remarks: Some rails broken from being hit.

Br. No. 240-03-0076 Six Mile Creek 74' Steel I Beam
Paint Condition: Poor General Condition: Good
Remarks: Rail appearance is bad. Some broken and general aged condition. Bottom sill, Bent 3, is rotting.

Br. No. 240-03-0124 Bean Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 240-03-0166 Snake Creek 38' Treated Timber Trestle
Paint Condition: Fair General Condition: Good

Br. No. 240-03-0250 Peoples Creek 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Okay underneath. Tar and ballast worn off in patches on the deck.

FEDERAL AID SECONDARY ROUTE 241

Field Maintenance Division No. 302 Blaine County
Br. No. 241-03-0002 Thirty Mile Creek 88' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 241-03-0010	Buckley Coulee	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Sign bent.		
Br. No. 241-03-0042	Fogey Creek	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 241-03-0075	West Fork Wayne Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 241-03-0091	Wayne Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Riprap south berm washed out 25 percent.		
Br. No. 241-03-0097	East Fork Wayne Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Riprap north washing out a little. Bridge sign says Oriley Creek.		
Br. No. 241-03-0110	Drainage	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Bridge sign says North Fork Wayne Creek.		
Br. No. 241-03-0122	West Savoy Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Bridge sign says Savoy Creek.		
Br. No. 241-03-0375	Woody Island Creek	117' Steel I Beam
Paint Condition: Poor		General Condition: Good
Remarks: Many rail posts cracked.		

FEDERAL AID SECONDARY ROUTE 242

Field Maintenance Division No. 402	Phillips County	
Br. No. 242-36-0055	Circle Diamond Coulee	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Run off causing slight fill damage on north end.		
Br. No. 242-36-0060	Assiniboine Creek	114' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: A few nuts gone from curb bolts.		
Br. No. 242-36-0152	Cottonwood Creek	100' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 242-36-0174	Little Cottonwood Creek	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Many curb nuts loose.		
Br. No. 242-36-0470	Whitewater Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

FEDERAL AID SECONDARY ROUTE 243

Field Maintenance Division No. 402
Br. No. 243-36-0007 Drainage
Paint Condition: Good

Phillips County
57' Treated Timber Trestle
General Condition: Good

Br. No. 243-36-0010 Drainage
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

Br. No. 243-36-0012 U.S.R.S. Ditch
Paint Condition: Good

95' Treated Timber Trestle
General Condition: Good

Br. No. 243-36-0013 Drainage
Paint Condition: Good
Remarks: Curb shows being battered up a little

57' Treated Timber Trestle
General Condition: Good

Br. No. 243-36-0014 Drainage
Paint Condition: Good

57' Treated Timber Trestle
General Condition: Good

Br. No. 243-36-0016 Drainage
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

Br. No. 243-36-0018 Drainage
Paint Condition: Good

114' Treated Timber Trestle
General Condition: Good

Br. No. 243-36-0022 Drainage
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

Br. No. 243-36-0058 Milk River
Paint Condition: Good

250' Steel Plate Girder
General Condition: Good

Br. No. 243-36-0096 White(Stinky Water)Creek
Paint Condition: Poor (Probably never painted)
Remarks: Looks structurally okay underneath, but members too light for general traffic. Is old and dilapidated looking.

61.6' Steel I Beam
General Condition: Poor

Br. No. 243-36-0101 Whitewater Creek
Paint Condition: Poor
Remarks: A lot of recent repairs have been made and bridge is probably structurally all right. It has a general patched up and dilapidated look.

117' Steel I Beam
General Condition: Poor

FEDERAL AID SECONDARY ROUTE 244

Field Maintenance Division No. 403
Br. No. 244-35-0024 Drainage
Paint Condition: Fair
Remarks: Tumble weeds collected underneath.

Petroleum County
38' Treated Timber Trestle
General Condition: Good

Br. No. 244-35-0058 Flatwillow Creek
Paint Condition: Poor
Remarks: No signs. No reflectors. Nuts missing on some rail bolts. Other nuts loose.

133' Treated Timber Trestle
General Condition: Good

Br. No. 244-35-0121 Pike Creek
Paint Condition: Poor
Remarks: No signs. No reflectors.

38' Treated Timber Trestle
General Condition: Good

Br. No. 244-35-0123	Drainage	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 244-35-0185	Yellow Water Creek	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 244-35-0233	McDonald Creek	125' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: No signs. No reflectors.		

FEDERAL AID SECONDARY ROUTE 245

No bridges.

FEDERAL AID SECONDARY ROUTE 246

Field Maintenance Division No. 402		Valley County
Br. No. 246-53-0007	Cherry Creek	120' Continuous Concrete T Beam
Paint Condition: Good		General Condition: Good
Remarks: New 1960.		
Br. No. 246-53-0011	Drainage	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: New 1960		
Br. No. 246-53-0021	Milk River	400' Riveted Steel Plate Girder
Paint Condition: Good		General Condition: Good
Remarks: New 1960		
Br. No. 246-53-0067	Antelope Creek	75' Untreated Timber Trestle
Paint Condition: Very Poor		General Condition: Fair
Remarks: Structurally sound, but old and patched up looking. One section of rail gone on southwest end.		

FEDERAL AID SECONDARY ROUTE 247

Field Maintenance Division No. 402		Valley County
Br. No. 247-53-0066	East Fork Cherry Creek	150' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Middle stringer second span cracked.		
Br. No. 247-53-0254	Dry Fork Creek	125' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 247-53-0281	West Fork Porcupine Creek	114' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Rail shows a distortion of grade line. One wing section of rail broken off.		
Br. No. 247-53-0351	Drainage	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 247-53-0394	Middle Fork Porcupine Creek	100' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Repair on stringer and piles in good shape.		

Br. No. 247-53-0400 Alkali Creek
Paint Condition: Fair
Remarks: One rail post broken.

76' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 248

Field Maintenance Division No. 402
Br. No. 248-10-0025 Drainage
Paint Condition: Fair

Daniels County
25' Treated Timber Trestle
General Condition: Good

Br. No. 248-10-0030 East Fork Poplar River
Paint Condition: Good
Remarks: Rockers in expansion position at OOF.

277.6' Steel Pony Truss
General Condition: Good

Br. No. 248-10-0032 Drainage
Paint Condition: Fair
Remarks: No reflectors.

76' Treated Timber Trestle
General Condition: Good

Br. No. 248-10-0036 Butte Creek
Paint Condition: Fair
Remarks: One badly broken stringer in last span.

127' Treated Timber Trestle
General Condition: Good
No reflectors.

Br. No. 248-10-0093 Drainage
Paint Condition: Good

25' Treated Timber Trestle
General Condition: Good

Br. No. 248-10-0106 Spring Creek
Paint Condition: Poor
Remarks: No reflectors.

75' Treated Timber Trestle
General Condition: Good

Br. No. 248-10-0220 Drainage
Paint Condition: Poor

57' Treated Timber Trestle
General Condition: Good

Br. No. 248-10-0225 Drainage
Paint Condition: Poor

76' Treated Timber Trestle
General Condition: Good

Br. No. 248-10-0243 Drainage
Paint Condition: Poor

57' Treated Timber Trestle
General Condition: Good

Br. No. 248-10-0289 Drainage
Paint Condition: Poor

75' Treated Timber Trestle
General Condition: Good

Br. No. 248-10-0290 Old Overflow Channel
Paint Condition: Poor
Remarks: Reflectors shot up badly.

50' Treated Timber Trestle
General Condition: Good

Field Maintenance Division No. 402
Br. No. 248-53-0291 West Fork Poplar River
Paint Condition: Poor
Remarks: About 10 percent of the nuts missing from bolts. About 25 percent of the nuts are loose.

Valley County
200' Treated Timber Trestle
General Condition: Good

Br. No. 248-53-0293 Overflow West Fork Poplar River
75' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Remarks: Ten percent of the nuts are missing. Many of the nuts are loose.

Br. No. 248-53-0316	Spring Creek	50' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

FEDERAL AID SECONDARY ROUTE 249

Field Maintenance Division No. 402	Valley County
Br. No. 249-53-0020	Milk River
Paint Condition: Good	369' Steel Girder
Remarks: Two rail posts have been hit and bent.	General Condition: Good

Br. No. 249-53-0072	Drainage	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Fair
Remarks: Badly burnt underneath. An average of about 1 inch charred timber.		

Br. No. 249-53-0098	Overflow Missouri River (posted Galpin)	
286' Steel I Beams		
Paint Condition: Good		General Condition: Good

FEDERAL AID SECONDARY ROUTE 250

No bridges.

FEDERAL AID SECONDARY ROUTE 251

Field Maintenance Division No. 402	Roosevelt County
Br. No. 251-43-0118	Drainage
Paint Condition: Fair	25' Treated Timber Trestle
	General Condition: Good

Br. No. 251-43-0155	Drainage	25' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: One rail board broken.		

Br. No. 251-43-0178	Kirn Coulee	25' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good

Br. No. 251-43-0207	Drainage	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 251-43-0217	Hay Creek	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Remarks: Two corner posts cracked.		

Field Maintenance Division No. 402	Daniels County
Br. No. 251-10-0409	Smoke Creek
Paint Condition: Poor	25' Treated Timber Trestle
	General Condition: Good

Br. No. 251-10-0498	Eagle Creek	25' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: One section rail broken out and two other sections broken		

FEDERAL AID SECONDARY ROUTE 252

Field Maintenance Division No. 401	McCone County
Br. No. 252-28-0015	Horse Creek
Paint Condition: Fair	100' Treated Timber Trestle
	General Condition: Good

Br. No. 252-28-0070	Denwoody Creek	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 252-28-0080	Horse Creek	75' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 252-28-0130	Horse Creek	57' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good
Br. No. 252-28-0141	Drainage	38' Treated Timber Trestle
Paint Condition: Fair		General Condition: Fair

FEDERAL AID SECONDARY ROUTE 253

Field Maintenance Division No. 401		Prairie County
Br. No. 253-40-0009	Yellowstone River	825' Riveted Plate Girders
Paint Condition: Good		General Condition: Good
Remarks: Rockers, Bent 2, in expansion position at +20°F.		
Br. No. 253-40-0036	Drainage	50' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: No signs. No reflectors. Two rail posts damaged.		
Br. No. 253-40-0046	Cherry Creek	362.5' Steel I Beam
Paint Condition: Poor		General Condition: Good
Remarks: Two rail posts damaged.		
Br. No. 253-40-0080	Brackett Creek	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 253-40-0094	Cedar Creek	133' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 253-40-0147	Drainage	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: One wing wall hit and knocked over.		
Br. No. 253-40-0174	Drainage	76' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 253-40-0188	Drainage	95' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 253-40-0224	Cedar Creek	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 253-40-0269	Cedar Creek	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Field Maintenance Division No. 401		McCone County
Br. No. 253-28-0371	East Duck Creek	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 253-28-0462	Redwater River	150' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Fourth stringer sixth span cracked.		

FEDERAL AID SECONDARY ROUTE 254

Field Maintenance Division No. 401	Dawson County
Br. No. 254-11-0175 Lower Seven Mile Creek	25' Treated Timber Trestle
Paint Condition: Fair	General Condition: Good
Remarks: Tumble weeds present a fire hazard under this bridge.	

Br. No. 254-11-0229 South Fork Thirteen Mile Creek	
25' Treated Timber Trestle	
Paint Condition: Fair	General Condition: Good
Remarks: Tumble weeds have collected under this bridge.	

Br. No. 254-11-0288 Middle Fork Burns Creek	25' Treated Timber Trestle
Paint Condition: Fair	General Condition: Good
Remarks: Road berms are eroding away.	

Br. No. 254-11-0532 Redwater River	98' Steel and Concrete
Paint Condition: Poor	General Condition: Poor
Remarks: All concrete badly spalled and weathered. Part of the deck has been ripped away making the roadway narrow. No signs. No rail. No reflectors. Part of the curb is gone and the bridge looks old and dilapidated.	

FEDERAL AID SECONDARY ROUTE 256

Field Maintenance Division No. 402	Sheridan County
Br. No. 256-46-0064 McCoy Creek	28' Steel I Beam
Paint Condition: Poor	General Condition: Good

FEDERAL AID SECONDARY ROUTE 257

Field Maintenance Division No. 101	Mineral County
Br. No. 257-31-0001 C.M.ST.P.&P. R.R.	Underpass
Paint Condition: Fair	General Condition: Good
Remarks: In Superior.	

Br. No. 257-31-0002 Clark Fork	459.4' Steel Pratt Truss
Paint Condition: Fair to Poor	General Condition: Good
Remarks: In Superior. Rail paint poor. Truss ends at portals are rusted and there are many scattered rust spots over the length of the structure. Underside of corrugated metal deck base and stringers (many new) look good. Deck oil mat in good condition.	

Br. No. 257-31-0003 Interstate 90(U.S. 10)	Underpass
Paint Condition: Good	General Condition: Good

Br. No. 257-31-0004 Interstate 90(U.S. 10)	Underpass
Paint Condition: Good	General Condition: Good

Br. No. 257-31-0012 Cedar Creek	110' Concrete T Beam
Paint Condition: Good	General Condition: Good
Remarks: Deck oiled surface is good.	

Br. No. 257-31-0037 N. P. Railway 188' Concrete T Beam
Paint Condition: Good General Condition: Good
Remarks: The sloughing of the fill at Bent 1 previously reported has been
 taken care of. Deck oiled surface is good.

FEDERAL AID SECONDARY ROUTE 258

Field Maintenance Division No. 402 Sheridan County
Br. No. 258-46-0002 Big Muddy Creek 150' Treated Timber Trestle
Paint Condition: Fair General Condition: Good
Remarks: About $\frac{1}{2}$ of the nuts are gone from bolts holding wheel guard on. Rail
 shows hump in grade.

Br. No. 258-46-0008 Drainage 113' Treated Timber Trestle
Paint Condition: Fair General Condition: Good
Remarks: About 25 percent of the nuts are gone from wheel guard timber bolts.
 Rail shows quite a hump in the grade.

FEDERAL AID SECONDARY ROUTE 261

Field Maintenance Division No. 401 Wibaux County
Br. No. 261-55-0004 Dry Creek 56' Steel Girder
Paint Condition: None required. General Condition: Good
Remarks: A few small spalls on curb. No signs. No reflectors.

Field Maintenance Division No. 401 Richland County
Br. No. 261-42-0435 O'Brien Creek 28' Treated Timber Trestle
Remarks: Not inspected.

FEDERAL AID SECONDARY ROUTE 262

No bridges.

FEDERAL AID SECONDARY ROUTE 263

No bridges.

FEDERAL AID SECONDARY ROUTE 264

No bridges.

FEDERAL AID SECONDARY ROUTE 265

No bridges.

FEDERAL AID SECONDARY ROUTE 266

No bridges.

FEDERAL AID SECONDARY ROUTE 267

Field Maintenance Division No. 101 Missoula County
Br. No. 267-32-0001 N. P. Railway Underpass
General Condition: Fair

Br. No. 267-32-0044 Rattlesnake Creek 50' Untreated Timber & Concrete
Paint Condition: None on rail General Condition: Fair
Remarks: Center pier settled on upstream side. Posted 3 Ton load limit.

FEDERAL AID SECONDARY ROUTE 268

No bridges.

FEDERAL AID SECONDARY ROUTE 269

Field Maintenance Division No. 101 Ravalli County
Br. No. 269-41-0034 Irrigation Ditch 21.8' Concrete Slab
Paint Condition: Fair to Poor General Condition: Good
Remarks: Northwest rail ends broken off. Paint poor west side rail. Fair east side rail.

Br. No. 269-41-0053 Irrigation Ditch 25' Treated Timber Trestle
Paint Condition: Fair to Poor General Condition: Good
Remarks: Paint fair west rail, poor east rail. Deck oil mat good.

Br. No. 269-41-0208 Bitterroot River Overflow 75' Treated Timber Trestle
Paint Condition: Poor, Northside; Fair, South side
General Condition: Good

Br. No. 269-41-0210 Bitterroot River 324' Continuous Steel Girder
Paint Condition: Good General Condition: Good

FEDERAL AID SECONDARY ROUTE 270

Field Maintenance Division No. 502 Carter County
Br. No. 270-06-0036 Horse Creek 35' Steel I Beam
Paint Condition: Poor General Condition: Good
Remarks: Chipped out spot on Bent 1 under right beam.

Br. No. 270-06-0066 Little Missouri River 142' Steel Pratt Truss
Remarks: Portals have been hit and bent. Rail bent. Old concrete wall bent 4, is pushing against new pile bent.

Br. No. 270-06-0189 Cottonwood Creek 60' Steel Pony Truss
Paint Condition: Poor General Condition: Fair

Br. No. 270-06-0198 Hackberry Creek 23' Steel I Beam
Paint Condition: Poor General Condition: Good

FEDERAL AID SECONDARY ROUTE 271

Field Maintenance Division No. 101 Powell County
Br. No. 271-39-0202 Nevada Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Also listed Br. No. 272-39-0284

Br. No. 271-39-0257 Big Blackfoot River 179' Steel Pony Truss(re-erected)
Paint Condition: Good General Condition: Good

FEDERAL AID SECONDARY ROUTE 272

Field Maintenance Division No. 272

Br. No. 272-39-0117 Rhine Creek

Paint Condition: Poor

Remarks: One end post and two intermediate posts split. End of northwest rail section split off.

Powell County

38' Treated Timber Trestle

General Condition: Good

Br. No. 272-39-0133 Nevada Creek

Paint Condition: Good

57' Treated Timber Trestle

General Condition: Good

Br. No. 272-39-0284 Nevada Creek

Paint Condition: Good

Remarks: Also listed Br. No. 271-39-0202

38' Treated Timber Trestle

General Condition: Good

Br. No. 272-39-0354 Big Blackfoot River

Paint Condition: Good

189' Steel Pony Truss (re-erected)

General Condition: Good

Br. No. 272-39-0419 North Fork Blackfoot River 152' Steel Pratt Truss

Paint Condition: Poor

General Condition: Poor

Remarks: Additional bent under truss is located at the third truss panel from south end. Support under south side truss is a length of c.m.p. culvert pipe filled with concrete. The one on the east side, previously reported as washed out, has been replaced with an 8"x8" timber shore with blocks and wedges at top with timber footing.

FEDERAL AID SECONDARY ROUTE 273

Field Maintenance Division No. 201

Br. No. 273-12-0007 Warm Springs Creek

Paint Condition: None

Remarks: Bent 1 has a vertical crack at center. Due to ice cover, Pier 2 footing could not be inspected. Previous report stated that footing was being washed away. No load limit posted for this structure.

Deer Lodge County

42' Steel I Beam

General Condition: Good

FEDERAL AID SECONDARY ROUTE 274

Field Maintenance Division No. 201

Br. No. 274-12-0016 Mill Creek

Paint Condition: Fair

Remarks: Some rail paint poor due to paint flaking off.

Deer Lodge County

25' Treated Timber Trestle

General Condition: Good

Br. No. 274-12-0122 Big California Creek

Paint Condition: Poor

Remarks: End of east side top rail broken. Bridge markers need painting.

57' Treated Timber Trestle

General Condition: Good

Br. No. 274-12-0164 French Gulch

Paint Condition: Fair

Remarks: Markers need painting.

57' Treated Timber Trestle

General Condition: Good

Br. No. 274-12-0198 French Gulch

Paint Condition: Poor

Remarks: At south end bent, two west piles are $1\frac{1}{2}$ " to 2" below the cap. Space should be wedged. South side bridge marker is gone.

57' Treated Timber Trestle

General Condition: Good

FEDERAL AID SECONDARY ROUTE 275

Field Maintenance Division No. 201	Deer Lodge County
Br. No. 275-12-0018 Willow Creek	30' Treated Timber Trestle
Paint Condition: Poor	General Condition: Poor
Remarks: East and center bent piles are deeply rotted. Laminated 2"x4" deck and 6"x12" curbs are treated lumber. Balance of structure is untreated. Southwest corner post split and the flared end terminal section is gone. Fill at southwest corner is sloughing out from 1' inside curb. Load limit sign on east side of structure only. Load limit 10,000 pounds. Central part of oil mat good. Outside areas are cracked.	

Br. No. 275-12-0021 Clark Fork	37' Timber Truss Span
Paint Condition: Poor	General Condition: Good
Remarks: Bridge posted as follows: Signs painted on approach wing top rail: "Load Limit 10,000 Lbs!". Oil mat on deck is good. This truss now has a center bent with a 12"x12" cap. Three 12"x12" short timber piles set on concrete footings.	

FEDERAL AID SECONDARY ROUTE 276

No bridges.

FEDERAL AID SECONDARY ROUTE 277

Field Maintenance Division No. 502	Carter County
Br. No. 277-06-0209 Whitetail Creek	23.1' Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Pressure cracks at wing wall corners. No signs. No reflectors.	

Br. No. 277-06-0253 Muskrat Creek	62.2' Treated Timber Trestle
Paint Condition: Poor	General Condition: Fair
Remarks: Stringers look too light for their spans. No signs. No reflectors.	

Br. No. 277-06-0290 Corral Creek	51' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good
Remarks: Piles and backing plank are new. The rest of the lumber is old. No signs or reflectors.	

Br. No. 277-06-0315 Box Elder Creek	104' Steel I Beam
Paint Condition: Poor	General Condition: Good
Remarks: No signs or reflectors.	

FEDERAL AID SECONDARY ROUTE 278

Field Maintenance Division No. 201	Beaverhead County
Br. No. 278-01-0186 Grasshopper Creek	50' Treated Timber Trestle
Paint Condition: Good	General Condition: Good

Br. No. 278-01-0342 Bull Creek	25' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: The cap of Bent 2(south) is not bearing on two piles left side by 3/4" on one and 1" on another. The gaps should be wedged. Gravel surfacing on the deck.	

Br. No. 278-01-0432 Warm Springs Creek 35' Untreated Log Trestle
Paint Condition: None General Condition: Good
Remarks: Underside of deck and log stringers look good.

Br. No. 278-01-0433 Drainage 37.4' Concrete and Steel
Paint Condition: Fair to Good
Remarks: Concrete at face of bearing wall at shoe seats has chipped off.
 Nothing serious. Underside of deck looks good.

FEDERAL AID SECONDARY ROUTE 279

Field Maintenance Division No. 301 Lewis and Clark County

Br. No. 279-25-0001 I 15 - Lincoln Road Interchange
204.5' Prestressed Concrete Beams

Remarks: Under contract - Let 12-20-61

Br. No. 279-25-0179 Little Prickly Pear Creek 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Bridge deck has oiled surface with a chip sealcoat.

Br. No. 279-25-0200 Canyon Creek 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Bridge deck has an oiled surface with a chip sealcoat.

Br. No. 279-25-0212 Canyon Creek 57' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Northwest curb end and lower rail end split.

Br. No. 279-25-0217 Canyon Creek 63' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: At the south end of the east curb there is a 1.5' diameter hole in the
 oil mat that extends down behind the backing plank. Should be filled
 as drainage will continue to enlarge the opening.

FEDERAL AID SECONDARY ROUTE 280

Field Maintenance Division No. 301 Lewis and Clark County

Br. No. 280-25-0004 I 15 - York Road Separation
214.5' Prestressed Concrete Beam

Remarks: Under construction. Superstructure forms in place. Contract let 5-24-61.

Br. No. 280-25-0013 Irrigation Canal 34.3' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Northeast end post and wing post and rail panels torn out.

Br. No. 280-25-0026 Big Prickly Pear Creek 31.4' Steel I Beam
Paint Condition: Good to Poor General Condition: Good
Remarks: South rail paint good; northside, poor. Abutments and pier eroded at
 water line. Exterior steel beam paint poor, good on interior beams.

Br. No. 280-25-0146 Missouri River 544.5' Steel Thru Truss
Paint Condition: Good General Condition: Good

FEDERAL AID SECONDARY ROUTE 281

Field Maintenance Division No. 201
Br. No. 281-22-0027 Little Boulder River
Paint Condition: Fair to Poor
Remarks: Markers need repainting.

Jefferson County
57' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 283

No bridges.

FEDERAL AID SECONDARY ROUTE 284

Field Maintenance Division No. 301
Br. No. 284-25-0047 Helena Valley Canal
Paint Condition: Good

Lewis and Clark County
71.7' Treated Timber Trestle
General Condition: Good

Br. No. 284-25-0089 Missouri River
Paint Condition: Good Canyon Ferry

1000' Concrete Dam
General Condition: Good

FEDERAL AID SECONDARY ROUTE 285

Field Maintenance Division No. 201
Br. No. 285-04-0064 Crow Creek
Paint Condition: Poor

Broadwater County
25' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 286

Field Maintenance Division No. 202
Br. No. 286-16-0030 Gallatin River
Remarks: Bridge posted: Load Limit 8 Tons. Rockers in extreme expansion position.
Some light cracks in beam seat caps and piers. Two truss diagonals
have been hit. No reflectors.

Gallatin County
154' Steel Pratt Truss

FEDERAL AID SECONDARY ROUTE 287

Field Maintenance Division No. 201
Br. No. 287-16-0079 Willow Creek
Paint Condition: Poor
Remarks: Three end and some intermediate rail posts heavily checked. Nuts
missing from various bridge members.

Gallatin County
25' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 288

Field Maintenance Division No. 202
Br. No. 288-16-0050 Camp Creek
Paint Condition: Poor
Remarks: On the west side one intermediate rail post gone and one rail end split.

Gallatin County
25' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 289

Field Maintenance Division No. 202
Br. No. 289-29-0079 Madison River
Paint Condition: Good
Remarks: Paint good one side and fair to poor on other side. Anchor bolt nuts,
northside of east bent, are gone.

Madison County
250' Steel Truss

Br. No. 289-29-0096	Cherry Creek	38' Treated Timber Trestle
Paint Condition: Fair to Poor		General Condition: Good
Field Maintenance Division No. 202		Gallatin County
Br. No. 289-16-0151	Elk Creek	21' Concrete T Beam
Paint Condition: Poor (Pipe rail)		General Condition: Good
Br. No. 289-16-0279	West Gallatin River	120' Steel Thru Truss
Paint Condition: Fair		General Condition: Good
Remarks: Both portals damaged, west end hit and one member gone from east portal. Deck oil mat intact except for transverse cracks at plank deck joints, due to some movement under traffic. At southwest corner the curb end has been damaged at the bearing seat, surface concrete has deteriorated. Deck underside is intact and is in fair condition.		
Br. No. 289-16-0282	Fork of West Gallatin	39' Steel and Concrete
Paint Condition: None		General Condition: Good
Remarks: Deck is oil surfaced and underside of timber deck is intact. Rail has been battered by traffic but is still intact.		

FEDERAL AID SECONDARY ROUTE 290

Field Maintenance Division No. 202		Gallatin County
Br. No. 290-16-0045	East Gallatin	50' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 290-16-0047	East Gallatin River	50' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 290-16-0053	Smith Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 290-16-0108	Dry Creek	26' Steel I Beam
Paint Condition: Fair		General Condition: Good
Remarks: Paint on interior beams is fair; on the exterior face of the outside beams, the paint is poor; also poor on the angle iron guard rail. South rail is battered, but still intact.		

FEDERAL AID SECONDARY ROUTE 291

No bridges.

FEDERAL AID SECONDARY ROUTE 292

No bridges.

FEDERAL AID SECONDARY ROUTE 293

Field Maintenance Division No. 202		Gallatin County
Br. No. 293-16-0016	East Gallatin River	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Two corner posts at the end wing panels are split in two. A single sway brace has been bolted to each of the two intermediate bents. No reflectors.		

Br. No. 293-16-0108	Bridger Creek	25' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Meagher County
50' Treated Timber Trestle
General Condition: Good

75' Steel Girder
General Condition: Good

Br. No. 294-30-0273 South Fork Musselshell River 100' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Lower part of south end hand laid riprap washed out.

Park County
Underpass

Br. No. 295-34-0004 Interstate 90 Underpass
General Condition: Good

Wheatland County
85' Steel Pony Truss
General Condition: Good

30' Untreated Timber Trestle
General Condition: Fair

Remarks: Some work has been done on this structure since previous report. Wing wall plank look good and deck planking are intact.

FEDERAL AID SECONDARY ROUTE 297

Field Maintenance Division No. 403	Wheatland County
Br. No. 297-54-0009	Deadman's Basin Canal
Paint Condition: Good	57' Treated Timber Trestle
	General Condition: Good

FEDERAL AID SECONDARY ROUTE 298

Field Maintenance Division No. 202	Sweet Grass County
Br. No. 298-49-0085	Boulder River
Paint Condition: Fair	120' Steel Thru Truss
Remarks: Bridge posted with old load limit signs that requires close inspection to make out the words: Gross Limit 15 Tons.	General Condition: Good

Br. No. 298-49-0130	Boulder River	150' Continuous Steel Girder
Paint Condition: Good		General Condition: Good
Remarks: Several cords of drift collected against Pier 1.		

Br. No. 298-49-0162	Boulder River	60' Steel Pony Truss
Paint Condition: Good		General Condition: Good
Remarks: Bridge posted with old signs that need repainting, "Gross Limit 15 Tons".		

FEDERAL AID SECONDARY ROUTE 299

Field Maintenance Division No. 501	Golden Valley County
Br. No. 299-19-0044	Careless Creek
Paint Condition: Good-Steel; Poor-Wood	80' Steel Pony Truss
Remarks: Truss members are out of adjustment. Some x-bracing bent.	General Condition: Fair

FEDERAL AID SECONDARY ROUTE 300

Field Maintenance Division No. 501	Golden Valley County
Br. No. 300-19-0002	Musselshell River
Remarks: Under contract Let 12-20-61	141.5' Prestressed Concrete Beams

Br. No. 300-19-0012	Fish Creek	63' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: About 50 percent of the tar and gravel gone from the deck.		

Br. No. 300-19-0086	Big Coulee Creek	49' Untreated Timber Trestle
Paint Condition: Poor		General Condition: Fair
Remarks: Structurally satisfactory. . Lumber looks old. Rail is only 1' high.		

Br. No. 300-19-0088	Big Coulee Creek	40' Steel Queen Truss
Paint Condition: Fair		General Condition: Fair
Remarks: Quite a little patching up has been done on truss. Most lumber decking is new. It has recently been partly painted. Rail crooked.		

FEDERAL AID SECONDARY ROUTE 302

Field Maintenance Division No. 501	Yellowstone County
Br. No. 302-56-0090	G. N. Railway
Paint Condition: Good	Underpass
Remarks: Berm dirt sloughing downslopes, past curb and onto roadway.	General Condition: Good

FEDERAL AID SECONDARY ROUTE 303

Field Maintenance Division No. 501	Yellowstone County
Br. No. 303-56-0072 Arrow Creek	23.5' Steel I Beam
Paint Condition: Poor	General Condition: Poor
Remarks: One broken wood stringer. Steel stringers okay. Rail crooked.	
Br. No. 303-56-0082 Canal	35.5' Steel I Beam
Paint Condition: Poor	General Condition: Poor
Remarks: Extensive spalling of concrete pier near normal water line. Rail rusty and bent. Deck concrete shows extensive wear.	
Br. No. 303-56-0150 Canal	22.5' Steel I Beam
Paint Condition: Okay-Rail; Poor-Steel	General Condition: Good
Br. No. 303-56-0159 Canal	25.5' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: No signs or reflectors.	

FEDERAL AID SECONDARY ROUTE 304

No bridges.

FEDERAL AID SECONDARY ROUTE 305

Field Maintenance Division No. 501	Yellowstone County
Br. No. 305-56-0036 Canyon Creek	120' Continuous Concrete T Beam
Paint Condition: Good	General Condition: Good
Br. No. 305-56-0049 Big Ditch(B.B.W.A. Canal)	25' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Br. No. 305-56-0101 B.B.W.A. Canal	29' Treated Timber Trestle
Paint Condition: Good	General Condition: Good

FEDERAL AID SECONDARY ROUTE 306

Field Maintenance Division No. 501	Stillwater County
Br. No. 306-48-0036 Keyser Creek	30' Steel I Beam
Paint Condition: Poor	General Condition: Good
Remarks: Erosion exposed piles on south end bent. Left rail damaged and partly gone.	
Br. No. 306-48-0058 Keyser Creek	95' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good
Remarks: A couple of solid bridging blocks have fallen out.	

FEDERAL AID SECONDARY ROUTE 307

Field Maintenance Division No. 501	Carbon County
Br. No. 307-05-0129 West Fork Red Lodge Creek	25' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good
Remarks: Water has routed itself along Bent 2 side.	

Br. No. 307-05-0198 East Rosebud Creek 110' Continuous Concrete T Beam
Paint Condition: Good General Condition: Good

Field Maintenance Division No. 501 Stillwater County
Br. No. 307-48-0262 East Rosebud Creek 153' Prestressed Concrete Beams
Paint Condition: Good General Condition: Good

Br. No. 307-48-0301 Butcher Creek 30' Concrete I Beam
Paint Condition: Poor General Condition: Good
Remarks: Good shape for its age.

Br. No. 307-48-0349 Beaver Creek 50' Treated Timber Trestle
Paint Condition: Poor General Condition: Good

Br. No. 307-48-0454 Shayne Creek 63' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 307-48-0461 Yellowstone River 576' Riveted Plate Girder
Paint Condition: Good General Condition: Good
Remarks: Piece of concrete fallen out under curb expansion plate Bent 1 left.

FEDERAL AID SECONDARY ROUTE 308

Field Maintenance Division No. 501 Carbon County
Br. No. 308-05-0001 Rock Creek 62' Steel I Beam
Paint Condition: Poor General Condition: Good
Remarks: Corner post and section of rail gone. Small hunk of curb gone. Minor concrete erosion showing up at base of columns.

Br. No. 308-05-0158 Clark Fork Yellowstone River
244' Steel Girder
Paint Condition: Good General Condition: Good
Remarks: Noticeable erosion of concrete at low water line of piers. Looks like about 3/4" at Pier 2 and less at Pier 3.

Br. No. 308-05-0175 Silver Tip Creek 57' Treated Timber Trestle
Paint Condition: Poor General Condition: Good

Br. No. 308-05-0183 Clark Fork Yellowstone River
261' Steel Girder
Paint Condition: Poor General Condition: Good
Remarks: Rocker anchor bolts are setting high up out of their holes. One about 10" at Pier 2 and 4. One wood post off bridge end rotted off at bottom.

FEDERAL AID SECONDARY ROUTE 309

Field Maintenance Division No. 501 Musselshell County
Br. No. 309-33-0040 Drainage 38' Treated Timber Trestle
Paint Condition: Poor General Condition: Good
Remarks: No signs. No reflectors.

FEDERAL AID SECONDARY ROUTE 310

Field Maintenance Division No. 501	Yellowstone County
Br. No. 310-56-0010	Yellowstone River
Paint Condition: Poor	676' Steel Thru Truss
Remarks: Ten Ton load limit posted. Pier nose angle is separated from concrete by a large crack. All concrete is checked with cracks.	General Condition: Fair

Field Maintenance Division No. 501	Musselshell County
Br. No. 310-33-0417	Musselshell River
Remarks: Not inspected - New 1960.	193' Prestressed Concrete Beams

FEDERAL AID SECONDARY ROUTE 311

Field Maintenance Division No. 501	Treasure County
Br. No. 311-52-0001	Buckingham Coulee
Paint Condition: Poor	88' Treated Timber Trestle
Remarks: Badly broken stringer, center one, third span.	General Condition: Good

Br. No. 311-52-0034	Yellowstone River	835' Steel Thru Truss
Paint Condition: Poor		General Condition: Poor
Remarks: Ten Ton load limit posted. All pier concrete is deteriorated, checks and cracks are opened up throughout. Pier 1 has been chipped away at water line with ice and drift about 6" deep on upstream side. Pier 2 has lost nose angle and concrete is chipped away about 1'. This pier is out of plumb and has been reworked to fit trusses. New decking and many stringers new. Some of the truss members are loose, while others are very tight.		

Br. No. 311-52-0073	Drainage	62' Untreated Timber Trestle
Paint Condition: Poor		General Condition: Poor
Remarks: Rail all torn off. Lumber old looking.		

FEDERAL AID SECONDARY ROUTE 312

No Bridges.

FEDERAL AID SECONDARY ROUTE 313

Field Maintenance Division No. 501	Big Horn County
Br. No. 313-02-0018	Williams Creek
Paint Condition: Good	25' Treated Timber Trestle
Remarks: One rail board broken.	General Condition: Good

Br. No. 313-02-0055	Two Leggin Canal	45.2' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: About $\frac{1}{2}$ of the nuts are gone from curb timber bolts.		

Br. No. 313-02-0070	Two Leggin Canal	50' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: One end rail section broken off.		

Br. No. 313-02-0072	Overflow Ditch	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: One broken stringer, fifth, first span.		

Br. No. 313-02-0075	Big Horn River	576' Riveted Plate Girder
Paint Condition: Good		General Condition: Good
Remarks: Pier 4 has a crack in concrete about 4' right of centerline and extends from top of Pier to ground line.		

Br. No. 313-02-0230	Rotten Grass Creek	64' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Fourth stringer center span cracked. No signs or reflectors.		

Br. No. 313-02-0319	Soap Creek	24' Steel I Beam
Paint Condition: Poor		General Condition: Fair
Remarks: An extra support installed in center of span. Looks structurally okay.		

FEDERAL AID SECONDARY ROUTE 314

No bridges.

FEDERAL AID SECONDARY ROUTE 315

Field Maintenance Division No. 502	Rosebud County
Br. No. 315-44-0081	Armells Creek
Paint Condition: Poor	60.6' Steel Howe Truss
Remarks: Very dangerous appearance because it is so narrow. One-way traffic is necessary. Diagonal rods of truss are loose. Upstream members bent by drift. Center vertical member bent with traffic.	General Condition: Poor

Br. No. 315-44-0133	Sheep Creek	57' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

Br. No. 315-44-0136	East Fork Armells Creek	125' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Third span, sixth stringer broken.		

Br. No. 315-44-0155	Drainage	76' Treated Timber Trestle
Paint Condition: Fair		General Condition: Good

Br. No. 315-44-0180	Seven Mile Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 315-44-0213	McGilvrey Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 315-44-0228	Corral Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 315-44-0259	Stocker Creek	57' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

Br. No. 315-44-0347	Miller Creek	100' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Sign rusted.		

Br. No. 315-44-0385	Rosebud Creek	113' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Remarks: Signs bent and rusted.		

FEDERAL AID SECONDARY ROUTE 317

No bridges.

FEDERAL AID SECONDARY ROUTE 318

No bridges.

FEDERAL AID SECONDARY ROUTE 319

No bridges.

FEDERAL AID SECONDARY ROUTE 320

Field Maintenance Division No. 502	Fallon County
Br. No. 320-13-0022 Cottonwood Creek	95' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
Remarks: Badly cracked stringer in fourth span.	

Field Maintenance Division No. 502	Custer County
Br. No. 320-09-0051 Station Creek	36' Steel I Beam
Paint Condition: Poor	General Condition: Fair
Remarks: Structurally okay. Concrete looks pretty old and is spalling at base of walls. Rails bent and patched up.	

Br. No. 320-09-0053 O'Fallon Creek	202' Steel Pony Truss
Paint Condition: Poor	General Condition: Poor
Remarks: One steel span is made of riveted angles and is in fair shape structurally. Two spans have trusses of link steel units and round bars with screw adjustment connectors. These are bent and out of adjustment. The Piers have been patched up considerable. Have timber nosing additions. Rail is dilapidated.	

FEDERAL AID SECONDARY ROUTE 321

Field Maintenance Division No. 502	Fallon County
Br. No. 321-13-0060 Pennel Creek	100' Treated Timber Trestle
Paint Condition: Good	General Condition: Good

FEDERAL AID SECONDARY ROUTE 322

Field Maintenance Division No. 502	Fallon County
Br. No. 322-13-0111 Little Beaver Creek	133' Steel Girder
Paint Condition: Good	General Condition: Good
Remarks: Four rail posts split. Curb expansion plate ripped up.	

FEDERAL AID SECONDARY ROUTE 323

Field Maintenance Division No. 502	Carter County
Br. No. 323-06-0026 Russell Creek	57' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good
Remarks: No signs or reflectors.	
Br. No. 323-06-0177 Box Elder Creek	183' Concrete T Beams
Paint Condition: Good	General Condition: Good

Br. No. 323-06-0565 Little Missouri River 172' Steel Pratt Truss
Paint Condition: Poor General Condition: Fair
Remarks: 15 m.p.h. speed limit. Corner posts split. One concrete pier concrete
 has scaled off exposing re-steel over 75 percent of surface area.

FEDERAL AID SECONDARY ROUTE 324

Field Maintenance Division No. 201 Beaverhead County
Br. No. 324-01-0001
I 15 Horse Prairie Interchange 133' Prestressed Concrete Beam
Remarks: FAP Route 3 Br. No. 101-0910-0443 Future Junction - Let 3-22-61

FEDERAL AID SECONDARY ROUTE 325

Field Maintenance Division No. 302 Blaine County
Br. No. 325-03-0003 Drainage 38' Treated Timber Trestle
Paint Condition: Fair General Condition: Good

Br. No. 325-03-0004 Drainage 76' Treated Timber Trestle
Paint Condition: Poor General Condition: Good

Br. No. 325-03-0005 Canal 38' Treated Timber Trestle
Paint Condition: Fair General Condition: Good

FEDERAL AID SECONDARY ROUTE 326

No bridges.

FEDERAL AID SECONDARY ROUTE 327

Field Maintenance Division No. 402 Roosevelt County
Br. No. 327-43-0039 Little Muddy Creek 100' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 327-43-0123 G. N. Railway Underpass
General Condition: Good

FEDERAL AID SECONDARY ROUTE 328

No bridges.

FEDERAL AID SECONDARY ROUTE 329

Field Maintenance Division No. 501 Yellowstone County
Br. No. 329-56-0017 Yellowstone River 536.5' Steel Thru. Truss
Paint Condition: Poor General Condition: Poor
Remarks: Right girder span one bearing plate is only setting on support for about
 20 percent of its area. Concrete broken out underneath. Pretty good
 size cavities showing at low water line center pier. General age shows
 on concrete. Most concrete spalled and checked. 15 Ton limit posted.

Br. No. 329-56-0022 Duck Creek 59' Untreated Timber Girder
Paint Condition: Poor General Condition: Fair
Remarks: This bridge has steel stringers (old truck frames) and concrete deck.
 Seems to be structurally okay. Rail crooked. No signs or reflectors.

Br. No. 329-56-C024 Duck Creek
Paint Condition: Poor
Remarks: Structurally satisfactory.

39' Concrete and Timber
General Condition: Fair

FEDERAL AID SECONDARY ROUTE 330

Field Maintenance Division No. 301
Br. No. 330-07-0003 Missouri River
Paint Condition: Good

Cascade County
559' Steel Howe Truss
General Condition: Good

Remarks: Load limit sign northwest end 25' in advance of bridge. Bridge load limit - G.V.W. 15 Ton. No load limit sign on southeast end. Sign 500' in advance: Slow-Bridge. Oil mat good. East abutment wall cracked at bearing seat.

Br. No. 330-07-0050 Smith River
Paint Condition: Good

130' Steel Girder
General Condition: Good

Remarks: Expansion rockers, east and west abutments, canted excessively to the expansion side. Shoulders adjacent to east deck end have been rock filled, however, additional fill should be placed to raise shoulders to deck level and fill out to curbs. At northeast corner, junction of footing and crossbeam, the fill is sloughing out from behind the beam for a height of 3' above the base of the beam.

Br. No. 330-07-0366 Missouri River
Paint Condition: Good

648' Steel Plate Girder
General Condition: Good

Remarks: Shoulders at end of curb and walk at northwest and southwest ends have sloughed out and need to be backfilled.

FEDERAL AID SECONDARY ROUTE 331

Field Maintenance Division No. 301
Br. No. 331-07-0011 G. N. Railway
Paint Condition: Fair

Cascade County
Underpass
General Condition: Good

Remarks: Surface of wing, north side of west abutment, has spalled off. Exposed face of concrete sound.

FEDERAL AID SECONDARY ROUTE 332

Field Maintenance Division No. 502
Br. No. 332-09-0009 Pumpkin Creek
Paint Condition: Good

Custer County
138' Prestressed Concrete Beams
General Condition: Good

Br. No. 332-09-0105 Ash Creek
Paint Condition: Poor

38' Treated Timber Trestle
General Condition: Good

Remarks: Corner posts have some fairly large splits in them.

Br. No. 332-09-0106 Ash Creek Overflow
Paint Condition: Poor

38' Treated Timber Trestle
General Condition: Good

Br. No. 332-09-0109 Ash Creek Overflow
Paint Condition: Poor

38' Treated Timber Trestle
General Condition: Good

Br. No. 332-09-0138 Jack Creek
Paint Condition: Poor

25' Treated Timber Trestle
General Condition: Good

Br. No. 332-09-0157 Brown Creek 25' Treated Timber Trestle
Paint Condition: Poor General Condition: Good

Br. No. 332-09-0173 Haddow Creek 38' Treated Timber Trestle
Paint Condition: Poor General Condition: Good

Br. No. 332-09-0198 Foster Creek 38' Treated Timber Trestle
Paint Condition: Poor General Condition: Good
Remarks: Some drift starting to collect at Bent 2.

Field Maintenance Division No. 502 Rosebud County
Br. No. 332-44-0396 Tongue River 152' Steel and Concrete
Remarks: Not inspected.

FEDERAL AID SECONDARY ROUTE 333

Field Maintenance Division No. 502 Custer County
Br. No. 333-09-0081 Drainage 23' Steel I Beam
Paint Condition: Poor General Condition: Fair
Remarks: Wood is all old. Structurally it looks satisfactory.

Br. No. 333-09-0142 Streve11 Creek 40' Steel Pony Truss
Paint Condition: Poor General Condition: Poor
Remarks: One diagonal member broken. Its dual member is very tight with tension.
End walls seem to be pushing truss together.

Br. No. 333-09-0160 Mizpah Creek 138' Steel Thru Truss
Paint Condition: Poor General Condition: Poor
Remarks: Members out of adjustment. Concrete spalled at low water line. Rail
dilapidated. Rotten planks in berm wing walls.

FEDERAL AID SECONDARY ROUTE 334

Field Maintenance Division No. 402 Daniels County
Br. No. 334-10-0039 East Fork Poplar River 143' Concrete T Beam
Paint Condition: Good General Condition: Good

Br. No. 334-10-0079 East Fork Poplar River 143' Concrete T Beam
Paint Condition: Good General Condition: Good
Remarks: Checked area on outside of northwest post.

Br. No. 334-10-0110 Cow Creek 50' Treated Timber Trestle
Paint Condition: Good General Condition: Good

FEDERAL AID SECONDARY ROUTE 335

Field Maintenance Division No. 401 Dawson County
Br. No. 335-11-0004 N. P. Railway Underpass
Paint Condition: Fair General Condition: Good
Remarks: A lot of spalled edges on concrete. Slab is rough and broken at joints.

Br. No. 335-11-0115 Cedar Creek 200' Treated Timber Trestle
Paint Condition: Good General Condition: Good

FEDERAL AID SECONDARY ROUTE 336

Field Maintenance Division No. 502
Br. No. 336-13-0053 Fork of Beaver Creek
Paint Condition: Fair

Fallon County
50' Treated Timber Trestle
General Condition: Good

Br. No. 336-13-0070 Beaver Creek
Paint Condition: Good

75' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 338

No bridges.

FEDERAL AID SECONDARY ROUTE 339

Field Maintenance Division No. 202
Br. No. 339-34-0002 Flathead Creek
Paint Condition: Fair
Remarks: Paint has flaked off in spots on some posts.

Park County
50' Treated Timber Trestle
General Condition: Good

Br. No. 339-34-0037 Shields River
Paint Condition: Good

70.8' Concrete T Beam
General Condition: Good

Br. No. 339-34-0141 Shields River
Paint Condition: Good

25' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 340

Field Maintenance Division No. 401
Br. No. 340-40-0019 Plum Creek
Paint Condition: Good
Remarks: Broken stringer fourth from right in first span.

Prairie County
63' Treated Timber Trestle
General Condition: Good

Br. No. 340-40-0154 Drainage
Paint Condition: Poor
Remarks: Lumber is old. Stringers have been patched up and reinforced. No signs or reflectors.

36' Untreated Timber Trestle
General Condition: Poor

FEDERAL AID SECONDARY ROUTE 341

No bridges.

FEDERAL AID SECONDARY ROUTE 342

No bridges.

FEDERAL AID SECONDARY ROUTE 343

Field Maintenance Division No. 302
Br. No. 343-51-0250 Strawberry Creek
Paint Condition: Poor
Remarks: West rail bent out and east rail skewed to the north. Plank deck in good condition.

Toole County
24' Steel I Beam
General Condition: Fair

FEDERAL AID SECONDARY ROUTE 344

Field Maintenance Division No. 402

Br. No. 344-43-0007 Sheep Creek

Paint Condition: Good

Roosevelt County

50' Treated Timber Trestle

General Condition: Good

Br. No. 344-43-0040 Big Muddy Creek

Paint Condition: Good

110' Continuous Concrete T Beam

General Condition: Good

Br. No. 344-43-0121 Smoke Creek

Paint Condition: Good

Remarks: New 1960.

110' Continuous Concrete T Beam

General Condition: Good

FEDERAL AID SECONDARY ROUTE 345

Field Maintenance Division No. 202

Br. No. 345-16-0044 Middle Creek

Paint Condition: Poor

Gallatin County

21' Concrete Slab & Steel I Beams

General Condition: Good

FEDERAL AID SECONDARY ROUTE 346

Field Maintenance Division No. 202

Br. No. 346-16-0019 Baker Creek

Paint Condition: None

Remarks: No reflectors.

Gallatin County

38' Treated Timber Trestle

General Condition: Good

Br. No. 346-16-0022 West Gallatin River

Paint Condition: Good

Remarks: Deck and stringers are in good condition. Oiled surfacing on deck.
Roller nests, previously reported packed with dirt, have been cleaned.
Bridge posted: Load Limit 14 Ton.

120' Steel Howe Truss

General Condition: Good

Br. No. 346-16-0063 East Gallatin River

Paint Condition: Fair

Remarks: Treated stringers and untreated plank deck are in good condition. No surfacing on deck. Bearing seats are covered with dirt.

80' Steel Pony Truss

General Condition: Good

FEDERAL AID SECONDARY ROUTE 347

Field Maintenance Division No. 202

Br. No. 347-16-0027 Baker Creek

Paint Condition: Good

Remarks: Bridge signs are gone and bridge is short two reflectors.

Gallatin County

93.7' Steel Girder

General Condition: Good

Br. No. 347-16-0034 West Gallatin River

Paint Condition: Good

178' Steel Girder

General Condition: Good

FEDERAL AID SECONDARY ROUTE 348

Field Maintenance Division No. 101

Br. No. 348-20-0004 Flint Creek

Paint Condition: Good

Granite County

38' Treated Timber Trestle

General Condition: Good

Br. No. 348-20-0139 Rock Creek

Paint Condition: Good

101.5' Prestressed Concrete Beam

General Condition: Good

FEDERAL AID SECONDARY ROUTE 349

No bridges.

FEDERAL AID SECONDARY ROUTE 350

Field Maintenance Division No. 402	Sheridan County
Br. No. 350-46-0030 Big Muddy Creek	110' Continuous Concrete T Beam
Paint Condition: Good	General Condition: Good
Remarks: Left rail has been hit and one post bent out of line about 3".	

FEDERAL AID SECONDARY ROUTE 352

No bridges.

FEDERAL AID SECONDARY ROUTE 353

Field Maintenance Division No. 101	Lake County
Br. No. 353-24-0001 N. P. Railway	Underpass
General Condition: Good	
Remarks: No clearance signs on underpass. There are some board strips that have been covered with N.P. Railway Co. signs.	

FEDERAL AID SECONDARY ROUTE 354

Field Maintenance Division No. 101	Lake County
Br. No. 354-24-0068 Irrigation Canal	68.5' Untreated Timber Trestle
Paint Condition: Poor	General Condition: Good

FEDERAL AID SECONDARY ROUTE 355

No bridges.

FEDERAL AID SECONDARY ROUTE 356

Field Maintenance Division No. 301	Lewis and Clark County
Br. No. 356-25-0001 Ten Mile Creek	65' Steel Pony Truss
Paint Condition: Fair	General Condition: Good
Remarks: Bridge posted: Load Limit 8 Tons. Underside of deck and stringers are good. Bridge deck surface in good condition. Truss shoes covered with dirt.	
Br. No. 356-25-0035 Seven Mile Creek	28' Steel I Beam
Paint Condition: Good	General Condition: Good
Remarks: Underside of deck looks good. Concrete deck surface in good condition.	

FEDERAL AID SECONDARY ROUTE 357

No Bridges.

FEDERAL AID SECONDARY ROUTE 358

Field Maintenance Division No. 301
Br. No. 358-37-0074 Birch Creek
Paint Condition: Fair

Pondera County
132' Steel I Beam
General Condition: Good

Br. No. 358-37-0174 Two Medicine Creek 194' Steel Truss
Paint Condition: Fair-Steel; Poor-Wood rail. General Condition: Good
Remarks: No reflector signs. Surfacing on deck is worn from the traffic lane.
Deck is wearing. Bridge portals slightly bent.

Field Maintenance Division No. 302
Br. No. 358-18-0275 Spring Creek
Paint Condition: None

Glacier County
36' Untreated Timber Trestle
General Condition: Fair

Remarks: 2"x6" laminated deck and 6"x18" stringers. Additional spreaders have been set in between bents to hold in place.

FEDERAL AID SECONDARY ROUTE 359

Field Maintenance Division No. 201
Br. No. 359-22-0003 Channel of Jefferson River
Paint Condition: None

Jefferson County
30' Steel Truss
General Condition: Good

Remarks: No surfacing on deck. Deck wearing but in good condition. Underside of deck and stringers look good.

Br. No. 359-22-0012 Jefferson River
Paint Condition: Poor

310" Steel Truss
General Condition: Fair

Field Maintenance Division No. 202
Br. No. 359-29-0017 Slough
Paint Condition: Good

Madison County
38' Treated Timber Trestle
General Condition: Good

Br. No. 359-29-0050 South Boulder River
Paint Condition: Good

50' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 360

Field Maintenance Division No. 202
Br. No. 360-30-0004 North Fork Smith River
Remarks: Under contract - Let 10-25-61

Meagher County
29' Treated Timber Trestle

Br. No. 360-30-0163 Smith River
Paint Condition: Fair

61' Pratt Steel Truss
General Condition: Fair

Remarks: The top chord of the right side truss has a slight dip at center due to previous damage to the center and end vertical posts which have been repaired with welded sections. Deck is intact. Posted: 20 Ton Limit.

FEDERAL AID SECONDARY ROUTE 362

Field Maintenance Division No. 202
Br. No. 362-34-0008 Yellowstone River
Paint Condition: Good

Park County
300' Steel Girder
General Condition: Good

Br. No 362-34-0011 Armstrong Irrigation Canal 25' Treated Timber Trestle
Paint Condition: Fair General Condition: Good
Remarks: No signs or reflectors.

FEDERAL AID SECONDARY ROUTE 363

Field Maintenance Division No. 402 Phillips County
Br. No. 363-36-0013 Milk River 218.5' Steel Thru Truss
Paint Condition: Poor General Condition: Poor
Remarks: East approach span is in poor shape. It just sets on the dirt.
Structure has a general old looking appearance.

Br. No. 363-36-0088 Alkali Creek 74' Steel Girder
Paint Condition: Good General Condition: Good
Remarks: West piling shows some drift damage. One diagonal brace broken.

Br. No. 363-36-0113 Irrigation Canal 73' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: Quite a little repair and reinforcing work underneath. No rail on the bridge.

FEDERAL AID SECONDARY ROUTE 364

No bridges.

FEDERAL AID SECONDARY ROUTE 365

No bridges.

FEDERAL AID SECONDARY ROUTE 366

Field Maintenance Division No. 302 Pondera County
Br. No. 366-37-0023 Coulee & Canal Overflow 25' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 366-37-0059 Dry Fork Marias River 106' Continuous Steel Girder
Paint Condition: Good General Condition: Good

FEDERAL AID SECONDARY ROUTE 367

Field Maintenance Division No. 101 Ravalli County
Br. No. 367-41-0004 Irrigation Canal 33' Steel & Timber
Paint Condition: Fair General Condition: Good
Remarks: No paint on one foot high steel rail. Deck structural steel paint fair. Deck surface oiled and in good condition.

FEDERAL AID SECONDARY ROUTE 368

No bridges.

FEDERAL AID SECONDARY ROUTE 369

Field Maintenance Division No. 302

Br. No. 369-37-0003

Pondera Coulee

Pondera County

39' Treated Timber Trestle

Paint Condition: Poor

General Condition: Good

Remarks: Rail section east side broken; rail in general is poor.

FEDERAL AID SECONDARY ROUTE 370

Field Maintenance Division No. 101

Br. No. 370-41-0005

Bitterroot River Branch

Ravalli County

57' Untreated Timber Trestle

Paint Condition: Fair to Poor

General Condition: Fair

Remarks: No timber curbs. Oiled surface on deck is wearing through on many plank, also there are a number of new plank which have not been surface treated. Stringers and deck look good on the underside. Load Limit: 10 Tons Gross.

Br. No. 370-41-0006

Bitterroot River Branch

93' Untreated Timber Trestle

Paint Condition: Fair to Poor

General Condition: Fair

Remarks: Stringer and underside of deck look good. One cracked stringer, Span 1, reinforced with a new stringer set in along side. Deck oiled surface good except on a few plank where it has been peeled off. Some plank are loose. No timber curbs. Load Limit: 10 Tons Gross.

Br. No. 370-41-0007

Branch of Bitterroot River 162' Untreated Timber Trestle

Paint Condition: Fair to Poor

General Condition: Fair

Remarks: Bent 1 (west) has been pushed in at the southwest side, also wing backing plank on this side. The fill from 1.5' in from the deck edge has sloughed out and should be replaced. There are no timber curbs. Pier Bents 2 and 3 have new plank facings. Deck oiled surface generally good, except on a few deck plank where it has peeled off. Stringers appear to be intact. Load Limit: 10 Tons Gross.

Br. No. 370-41-0009

Branch of Bitterroot River 95' Untreated Timber Trestle

Paint Condition: Fair

General Condition: Fair

Remarks: Some deck planking loose. Deck surface has been sealed and is in fair condition. Due to thaw, could only see underside from downstream gravel bar. Stringers appeared to be intact, could not tell if stringer previously reported broken in Span 2, had been replaced. Load Limit: 10 Tons Gross.

Br. No. 370-41-0012

Bitterroot River Branch

187' Steel Thru Truss

Paint Condition: Poor

General Condition: Fair

Remarks: Paint good on all timber guard rail, except four rail sections which have been replaced. Deck has a seal coat which is wearing off in the traffic lane, otherwise, condition is fair. Underside of deck and stringers look good. Truss batter column, northeast, has been reinforced with a section of channel 3"x12"x10' fastened to underside with "u" bolts. Load Limit: 10 Tons Gross.

Br. No. 370-41-0018

Drainage

38' Treated Timber Trestle

Paint Condition: Fair

General Condition: Good

Remarks: No timber curbs. One Bent 3 pile split vertically. Deck has seal coat worn off in spots; general condition fair. Underside of deck and stringers are good. Load Limit: 10 Tons Gross.

Br. No. 370-41-0019 Irrigation Ditch 76' Untreated Timber Trestle
Paint Condition: None General Condition: Fair
Remarks: Underside of deck and stringers look good. Southwest end has one lower broken rail. Deck has an oiled seal coat in fair condition. Transverse cracking at plank joints. Due to thaw and volume of water only one pile was tested. Surface one inch above water line rotted, but interior tested firm. Both end bents, stringers, and decking are comparatively recent construction. Timber curb east span only. 10 Ton Gross Load Limit.

FEDERAL AID SECONDARY ROUTE 371

Field Maintenance Division No. 202 Sweet Grass County
Br. No. 371-49-0012 Sweet Grass Creek 120' Continuous Concrete T Beam
Paint Condition: Good General Condition: Good

Br. No. 371-49-0109 Sweet Grass Creek 45' Timber Queen Truss
Paint Condition: None General Condition: Poor
Remarks: Bridge Posted: Gross Limit 10 Tons. Checked the length of this bridge, 50'. Additional shoring under the truss divides the span into 16' 8" sections. Shores are 8"x8" timbers. Due to ice sills or footings, could not be inspected. Shores were tight. One piece of rail is gone.

FEDERAL AID SECONDARY ROUTE 372

No bridges.

FEDERAL AID SECONDARY ROUTE 373

Field Maintenance Division No. 101 Ravalli County
Br. No. 373-41-0004 Bitterroot River 324' Steel Girder
Paint Condition: Good General Condition: Good
Remarks: Bent 1, left curb, end post, and rail hit and top of curb concrete at post broken. Top rail post bolts exposed for 5". Flared rail end replaced. Concrete deck in good condition.

FEDERAL AID SECONDARY ROUTE 374

Field Maintenance Division No. 402 Sheridan County
Br. No. 374-46-0037 Plentywood Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Nameplate gone.

FEDERAL AID SECONDARY ROUTE 375

Field Maintenance Division No. 201 Silver Bow County
Br. No. 375-47-0083 N. P. Railway 214.5' Prestressed Concrete Beam
Remarks: Not inspected.

FEDERAL AID SECONDARY ROUTE 376

Field Maintenance Division No. 302 Blaine County
Br. No. 376-03-0166 Little Peoples Creek 25' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 376-03-0176	Little Peoples Creek	25' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 376-03-0220	Little Peoples Creek	38' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 376-03-0259	South Fork Peoples Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 376-03-0312	Peoples Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Remarks: Left curb line has a noticeable crook in it.		
Br. No. 376-03-0405	White Bear Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good
Br. No. 376-03-0470	Three Mile Creek	100' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

FEDERAL AID SECONDARY ROUTE 377

No Bridges.

FEDERAL AID SECONDARY ROUTE 378

Field Maintenance Division No. 301		Teton County
Br. No. 378-50-0058	Muddy Creek	93' Steel I Beam
Paint Condition: None		General Condition: Fair
Remarks: There is no load limit posted for this bridge. As of this date, 12-1-61, there are standard shoulder "Slow" signs approximately 200' each side of the structure. The deck is gravel surfaced and rough. The south end bent original piles have rotted and have been replaced with 12"x12" timbers. Piles of the other bents test sound for visible portions. Deck planking (4") appears to be in good condition from underside of deck. Timber stringer in the approach spans appear good; a few are checked. There is no solid bridging or crossbracing of the timber span stringers. One rail post is broken and one section of rail is split, otherwise, in fair condition.		

Br. No. 378-50-0063	Drainage	30' Untreated Timber Trestle
Paint Condition: None		General Condition: Fair
Remarks: This bridge is not posted for a load limit, nor are there any advance signs of any type. A good portion of the gravel surface deck is exposed. Exposed portions of piles tested are good. Center bent piles are set on a timber sill which is partially submerged and is solid where possible to test. Decking and stringers appear to be in fair condition, however, there is no solid bridging or x-bracing.		

FEDERAL AID SECONDARY ROUTE 379

No bridges.

FEDERAL AID SECONDARY ROUTE 380

No bridges.

FEDERAL AID SECONDARY ROUTE 381

Field Maintenance Division No. 501
Br. No. 381-33-0004 Musselshell River
Paint Condition: Good
Remarks: Two flared ends installed wrong.

Musselshell County
150' Steel Girder
General Condition: Good

Br. No. 381-33-0044 Harper Coulee
Paint Condition: Good

38' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 382

Field Maintenance Division No. 101
Br. No. 382-45-0002 Flathead River
Paint Condition: Fair to Poor

Sanders County
619.5' Steel Thru Truss
General Condition: Poor

Remarks: Concrete abutment looks good. Underside of deck and stringers for three spans ahead that can be seen from bank are intact. Three spans out from the north bank are intact. Deck snow covered, no open breaks in surface noted. North abutment bearing seat concrete has a light crack on the south face and the east bearing seat has a crack on the east face. At truss ends above bearing there is a bottom tie plate across the channels that do not have all the rivet holes filled.

Br. No. 382-45-0029 Camas Creek
Paint Condition: Good

50' Treated Timber Trestle
General Condition: Good

Remarks: Three pieces of solid bridging are gone and one piece hanging and is ready to drop out.

Br. No. 382-45-0034 Camas Creek
Paint Condition: Good

50' Treated Timber Trestle
General Condition: Good

Remarks: Three pieces of solid bridging are out and half of two pieces are gone.

Br. No. 382-45-0038 Camas Creek
Paint Condition: Good

50' Treated Timber Trestle
General Condition: Good

Remarks: The southwest and northeast flared end terminal posts and the two panel length rail are gone.

FEDERAL AID SECONDARY ROUTE 383

No bridges.

FEDERAL AID SECONDARY ROUTE 384

Field Maintenance Division No. 501
Br. No. 384-02-0005 Little Big Horn River
Paint Condition: Good
Remarks: New 1960.

Big Horn County
183' Prestressed Concrete Beams
General Condition: Good

FEDERAL AID SECONDARY ROUTE 385

No bridges.

FEDERAL AID SECONDARY ROUTE 386

Field Maintenance Division No. 301	Chouteau County
Br. No. 386-08-0005	G. N. Railway
Underpass	
Paint Condition: Good	General Condition: Good
Remarks: Steep grade and poor sight distance. Clearance height painted on girder faces; not very distinct and need to be repainted.	

FEDERAL AID SECONDARY ROUTE 387

No bridges.

FEDERAL AID SECONDARY ROUTE 388

Field Maintenance Division No. 101	Havalli County
Br. No. 388-41-0033	Skalkaho Creek
32' Steel I Beam	
Paint Condition: Good	General Condition: Good
Remarks: Deck sand covered. Good condition. New 2" angle iron rail. Paint good on structural steel, fair on rail.	

FEDERAL AID SECONDARY ROUTE 389

No bridges.

FEDERAL AID SECONDARY ROUTE 390

Field Maintenance Division No. 101	Missoula County
Br. No. 390-32-0043	Clark Fork
420' Steel Girder	
Paint Condition: Good	General Condition: Good

FEDERAL AID SECONDARY ROUTE 391

Field Maintenance Division No. 502	Powder River
Br. No. 391-38-0037	Sand Creek
45' Treated Timber Trestle	
Paint Condition: Poor	General Condition: Good
Br. No. 391-38-0078	
Rough Creek	60' Steel Pony Truss
Paint Condition: Poor	General Condition: Fair
Remarks: Has a fairly new deck. Some bolts missing from field splice. One broken stringer center span. Another repaired but does not look strong. Truss members out of adjustment. Looks like end bents are slowly pushing truss together.	
Br. No. 391-38-0104	
Cache Creek	45' Untreated Timber Trestle
Paint Condition: Poor	General Condition: Poor
Remarks: Three broken stringers. No rail. Hole through deck plank. All lumber old.	

FEDERAL AID SECONDARY ROUTE 392

No bridges.

FEDERAL AID SECONDARY ROUTE 393

No bridges.

FEDERAL AID SECONDARY ROUTE 394

Field Maintenance Division No. 403	Wheatland County
Br. No. 394-54-0005	Musselshell River
130' Steel Girder	
Paint Condition: Good	General Condition: Good
Remarks: Two flared end sections on wrong. Signs are gone.	

FEDERAL AID SECONDARY ROUTE 395

Field Maintenance Division No. 501	Yellowstone County
Br. No. 395-56-0018	B.B.W.A. Canal
37.5' Steel Girder	
Paint Condition: Poor	General Condition: Good
Remarks: Minor spalling showing up on curbs. No signs or reflectors.	

FEDERAL AID SECONDARY ROUTE 396

Field Maintenance Division No. 302	Blaine County
Br. No. 396-03-0004	Thirty Mile Creek
100' Steel I Beam	
Paint Condition: Good	General Condition: Good
Br. No. 396-03-0049	Drainage
33' Untreated Timber Trestle	
Paint Condition: Poor	General Condition: Poor
Remarks: All piling rotten. Backing plank have fallen away from piles. Caps look practically unsupported at end bents. Deck plank pretty well worn.	
Br. No. 396-03-0077	Wayne Creek
48' Steel I Beam	
Paint Condition: Poor	General Condition: Fair
Remarks: River bottom washed out around center pier footing exposing the piling. Rail bent.	
Br. No. 396-03-0111	Drainage
24' Untreated Timber Trestle	
Paint Condition: Poor	General Condition: Fair
Remarks: Wood is weathered looking.	
Br. No. 396-03-0131	Savoy Creek
74' Steel Pony Truss	
Paint Condition: Poor	General Condition: Good
Remarks: All lumber looks old. X-bridging loose.	

FEDERAL AID SECONDARY ROUTE 397

Field Maintenance Division No. 501	Carbon County
Br. No. 397-05-0050	Clark Fork Yellowstone River
193.6' Steel Girder	
Paint Condition: Poor	General Condition: Good
Remarks: One-way signs posted. Bent 1 and Bent 4 each have a small chip of concrete out. Bent 1 cap under slab and Bent 4 at curb joint left. Three rail posts are broken and bent over.	

FEDERAL AID SECONDARY ROUTE 399

Field Maintenance Division No. 201	Jefferson County
Br. No. 399-22-0003	Boulder River
120' Steel Girder	
Remarks: Not inspected.	

Br. No. 399-22-0235 Whitetail Creek 32' Steel I Beam
Paint Condition: Poor General Condition: Good
Remarks: Deck gravel covered except a strip at south end and the laminated
 deck is wearing.

FEDERAL AID SECONDARY ROUTE 400

No bridges.

FEDERAL AID SECONDARY ROUTE 401

Field Maintenance Division No. 201	Jefferson County
Br. No. 401-22-0014 Pipestone Creek	76' Treated Timber Trestle
Paint Condition: Fair	General Condition: Good
 Br. No. 401-22-0084 Fish Creek	 38' Treated Timber Trestle
Paint Condition: Good	General Condition: Good

FEDERAL AID SECONDARY ROUTE 402

Field Maintenance Division No. 502	Powder River County
Br. No. 402-38-0053 Little Powder River	251.1' Steel Truss
Paint Condition: Poor	General Condition: Good

FEDERAL AID SECONDARY ROUTE 403

Field Maintenance Division No. 201	Silver Bow County
Br. No. 403-47-0005 B.A. & P. Railway	20' Treated Timber Arch(Tunnel)
Paint Condition: Good	General Condition: Good
Remarks: Oil mat is good. Slight dip in surface at approximately the north side of tunnel.	
 Br. No. 403-47-0008 B.A. & P. Railway	 76' Treated Timber Trestle
Paint Condition: Good	General Condition: Good
 Br. No. 403-47-0011 Lexington Mine Crosswalk	 Underpass
Paint Condition: Good	General Condition: Good
Remarks: No clearance signs on structure.	

FEDERAL AID SECONDARY ROUTE 404

Field Maintenance Division No. 402	Roosevelt County
Br. No. 404-43-0207 Smoke Creek	110' Continuous Concrete T Beam
Paint Condition: Good	General Condition: Good

FEDERAL AID SECONDARY ROUTE 405

No bridges.

FEDERAL AID SECONDARY ROUTE 406

No bridges.

FEDERAL AID SECONDARY ROUTE 407

Field Maintenance Division No. 101	Powell County	
Br. No. 407-39-0002	Little Blackfoot River	54' Steel Howe Truss
Paint Condition: Poor		General Condition: Good
Remarks: Untreated 2"x4" laminated deck in good condition. No surface cover. Heavy vertical break in north abutment, midway between the west bottom chord and the adjacent floor beam. At the junction of the wall and footing there is an opening 1'x1' through the wall and surface concrete has spalled off around the opening. There is a similar but lighter vertical crack in the south abutment, east side, located between the east bottom chord and the adjacent floor beam.		

FEDERAL AID SECONDARY ROUTE 408

Field Maintenance Division No. 101	Teton County	
Br. No. 408-50-0013	U.S.R.S. Lateral Ditch	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good
Br. No. 408-50-0040	U.S.R.S. Main Canal	75' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

FEDERAL AID SECONDARY ROUTE 409

No bridges.

FEDERAL AID SECONDARY ROUTE 410

Field Maintenance Division 302	Toole County	
Br. No. 410-51-0110	West Fork Willow Creek	39' Steel I Beam
Paint Condition: Poor		General Condition: Fair
Remarks: Cracks in end bents from exterior channel bearing seats out to junction with wing walls. All guard rail is gone. Plank deck in good condition.		
Br. No. 410-51-0162	Willow Creek	35' Steel I Beam
Paint Condition: Poor		General Condition: Fair
Remarks: North rail gone and south rail bent out of alignment. Plank deck appears good. Advance narrow bridge warning signs.		
Br. No. 410-51-0166	East Fork Willow Creek	23' Steel I Beam
Paint Condition: Poor		General Condition: Fair
Remarks: Both wing walls of east abutment heavily cracked. North rail gone, south rail pushed out of alignment. Deck is in fair shape. Top layer longitudinal plank in traffic lane is good. Advance narrow bridge warning signs.		
Br. No. 410-51-0217	Trail Creek	31' Steel I Beam
Paint Condition: Poor		General Condition: Fair
Remarks: Both rails gone. Deck planking appears to be in good condition.		

FEDERAL AID SECONDARY ROUTE 411

Field Maintenance Division No. 202
Br. No. 411-16-0003 East Gallatin River
Paint Condition: Poor

Gallatin County
50' Steel Pony Truss
General Condition: Good

FEDERAL AID SECONDARY ROUTE 412

Field Maintenance Division No. 101
Br. No. 412-32-0247 Lolo Creek
Paint Condition: Fair to Good

Missoula County
84' Treated Timber Trestle
General Condition: Good

Remarks: Due to amount of snow on walks and above rail, could only check broken end plank at southwest corner from underside, whereas, side-walk plank was previously reported broken at three corners.

Br. No. 412-32-0250 Lolo Creek
Paint Condition: Good

63' Treated Timber Trestle
General Condition: Good

Remarks: Three sidewalk plank are gone from southwest end of walk.

Br. No. 412-32-0265 Lolo Creek
Paint Condition: Fair

28' Treated Timber Trestle
General Condition: Good

Remarks: Two lines of 3"x12" planking has been placed on the stream face of the piling to retain roadway fill.

Br. No. 412-32-0267 Lolo Creek
Paint Condition: Fair

28' Treated Timber Trestle
General Condition: Good

Remarks: Part of northeast end rail post split off. Deck base and stringers are good. Two lines of 3"x12" plank have been placed on the stream face of the piles to retain roadway fill.

FEDERAL AID SECONDARY ROUTE 413

Field Maintenance Division No. 401
Br. No. 413-55-0004 Beaver Creek
Paint Condition: Poor

Wibaux County
150' Treated Timber Trestle
General Condition: Good

Br. No. 413-55-0038 Drainage
Paint Condition: Good
Remarks: No signs and no reflectors.

25' Treated Timber Trestle
General Condition: Good

Br. No. 413-55-0246 Beaver Creek
Paint Condition: Good
Remarks: New 1960 - No signs and no reflectors.

100' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 414

No bridges.

FEDERAL AID SECONDARY ROUTE 415

Field Maintenance Division No. 501
Br. No. 415-52-0037 Sarpy Creek
Paint Condition: Poor
Remarks: Rail is flimsily built.

Treasure County
25' Treated Timber Trestle
General Condition: Fair

Br. No. 415-52-0093	Sarpy Creek	24.5' Treated Timber Trestle
Paint Condition: Poor		General Condition: Fair

Br. No. 415-52-0184	Sarpy Creek	36.2' Untreated Timber and Concrete
Paint Condition: Poor		
General Condition: Fair		

Remarks: Bridge has recently been reinforced with some Steel I beams.

FEDERAL AID SECONDARY ROUTE 416

Field Maintenance Division No. 501	Yellowstone County
Br. No. 416-56-0020	Yellowstone River
Paint Condition: Poor	766' Steel Truss
Remarks: Considerable drift collected at Pier 2 and 4. A few bends in the rail. A few chips out of corner posts. One good size chip knocked off corner Bent 1, column right.	General Condition: Good

Br. No. 416-56-0026	Blue Creek	38' Treated Timber Trestle
Paint Condition: Poor		General Condition: Good

FEDERAL AID SECONDARY ROUTE 417

Field Maintenance Division No. 302	Toole County
Br. No. 417-51-0071	Marias River
Paint Condition: Good	450' Steel Girder
Remarks: Shoulder fill at edge of roadway sloughing out at north bent back wall haunches.	General Condition: Good

FEDERAL AID SECONDARY ROUTE 418

Field Maintenance Division No. 501	Big Horn County
Br. No. 418-02-0005	Pass Creek
Paint Condition: Poor	64' Treated Timber Trestle
	General Condition: Good

Br. No. 418-02-0096	Little Big Horn River	90' Steel Truss
Paint Condition: Good		General Condition: Good

FEDERAL AID SECONDARY ROUTE 419

Field Maintenance Division No. 501	Stillwater County
Br. No. 419-48-0001	Overflow East Rosebud Creek
Paint Condition: Poor	26' Steel I Beam
Remarks: Noticeable erosion at low water line on bents. Rail bent.	General Condition: Good

Br. No. 419-48-0002	East Rosebud Creek	56' Steel Pony Truss
Paint Condition: Poor		General Condition: Fair
Remarks: Wing walls of end bents are cracked and moving out. Erosion has exposed piling under end bents.		

Br. No. 419-48-0036	West Rosebud Creek	60' Steel Pony Truss
Paint Condition: Fair		General Condition: Good
Remarks: Both vertical members in center of truss have been hit and bent. Fill washing away under Bent 1 between columns.		

Br. No. 419-48-0199 Stillwater River 175.7' Concrete Slab
Paint Condition: None needed General Condition: Good
Remarks: Concrete slightly eroded at low water line, center pier.

Br. No. 419-48-0213 Drainage 31' Untreated Timber Pony Truss
Paint Condition: Poor General Condition: Fair
Remarks: Rail broken. Noticeable erosion of concrete at low water line.

Br. No. 419-48-0214 West Fork Stillwater River 42' Steel I Beam
Paint Condition: Poor General Condition: Good
Remarks: Rail has been damaged slightly. Most stringers underneath have been repaired.

FEDERAL AID SECONDARY ROUTE 420

Field Maintenance Division No. 501 Stillwater County
Br. No. 420-48-0002 Drainage 24' Steel I Beam
Paint Condition: Fair General Condition: Good
Remarks: Rail bent slightly.

Br. No. 420-48-0003 Rosebud Creek 95' Steel I Beam
Paint Condition: Fair General Condition: Good
Remarks: Expansion end of truss has pushed past their anchor bolt.

FEDERAL AID SECONDARY ROUTE 421

No bridges.

FEDERAL AID SECONDARY ROUTE 422

Field Maintenance Division No. 201 Madison County
Br. No. 422-29-0001 Jefferson River 285' Steel Thru Truss
Paint Condition: Poor General Condition: Good
Remarks: No surfacing on deck. Deck has a top longitudinal one lane plank surface in good condition. One lower rail (steel) broken loose and hanging down towards river. Truss diagonal in same panel bent.

Br. No. 422-29-0015 Jefferson River Overflow 60' Untreated Timber Trestle
Paint Condition: None General Condition: Good
Remarks: Checked some piling within reach and all tested firm. Bent 1, from the south, concrete bearing wall at junction with wing and for five feet under bridge has been under cut by stream; remaining length of bent below ice and could not be inspected. Underside of deck good and has been replaced since last report. Gravel surfacing gone from deck.

Br. No. 422-29-0027 Parrot Canal 28' Timber Pony Truss
Paint Condition: None General Condition: Poor
Remarks: East side truss has been hit and outside lateral brace is gone. An 8"x8" timber shore with top blocking has been set in under center of truss. The shore has settled and there is a 3/4" space between bottom chord and blocking. Stringers made up of laminated 2"x12" lumber and some planks are broken. Gravel ballast gone from deck and surface is wearing.

Br. No. 422-29-0086 Jefferson River 244.5' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: Deck not oil surfaced. Concrete surface good.

FEDERAL AID SECONDARY ROUTE 423

Field Maintenance Division No. 201 Silver Bow County
Br. No. 423-47-0001 I 15 - Victor Interchange 209.5' Prestressed Concrete Beam
Paint Condition: Good General Condition: Good
Remarks: Oiled surface good. See FAP Route 3 Br. No. 147-0910-0281.

Br. No. 423-47-0003 U. P. Railroad 231' Steel Girder
Paint Condition: Good General Condition: Good
Remarks: Aluminum coat of paint worn off a few rail panels, exposing the under coat. Small triangular section broken out of south walk at expansion joint. Some light cracks in south side of east back wall at bearing seats.

FEDERAL AID SECONDARY ROUTE 424

Field Maintenance Division No. 102 Flathead County
Br. No. 424-15-0243 Stillwater River 198' Untreated Timber Howe Truss
Paint Condition: None General Condition: Good

FEDERAL AID SECONDARY ROUTE 425

No bridges.

FEDERAL AID SECONDARY ROUTE 426

No bridges.

FEDERAL AID SECONDARY ROUTE 427

Field Maintenance Division No. 301 Judith Basin County
Br. No. 427-23-0122 Otter Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Paint good except on two rail sections, which is poor. No bridge markers.

FEDERAL AID SECONDARY ROUTE 428

No bridges.

FEDERAL AID SECONDARY ROUTE 429

Field Maintenance Division No. 501 Yellowstone County
Br. No. 429-56-0002 I 90 Separation 457' Prestressed Concrete Beams
Paint Condition: Good General Condition: Good
Remarks: See FAP Route 2, Br. No. 156-0100-0141.

Br. No. 429-56-0012 Canyon Creek 133' Prestressed Concrete Beams
Paint Condition: Good General Condition: Good
Remarks: New 1959

Br. No. 429-56-0017 B.B.W.A. Canal 29' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: No signs or reflectors.

FEDERAL AID SECONDARY ROUTE 430

No bridges.

FEDERAL AID SECONDARY ROUTE 431

Field Maintenance Division No. 301

Br. No. 431-50-0001 Main Irrigation Canal

Paint Condition: Good

Teton County

57' Treated Timber Trestle

General Condition: Good

Br. No. 431-50-0048 Main Irrigation Canal

Paint Condition: Good

57' Treated Timber Trestle

General Condition: Good

Br. No. 431-50-0163 Big Muddy Creek

Paint Condition: None

54' Untreated Timber Trestle

General Condition: Poor

Remarks: There is a "slow" sign in advance of the bridge and a "10 Ton Load Limit" sign on one of the north side end rail posts. No signs on the south side. Stringers are intact. The second bent from the south end has had a new bent set in along side the old bent and consists of an 8"x8" cap, 4, 8"x8" shores set on a timber sill. The second bent from the north end has one rotted out pile with no bearing.

FEDERAL AID SECONDARY ROUTE 432

Field Maintenance Division No. 302

Br. No. 432-08-0291 Drainage

Paint Condition: Poor

Chouteau County

23' Untreated Timber Trestle

General Condition: Fair

Remarks: Substructure looks good. End bents have treated piles and untreated backing plank. Broken stringers in deck have been reinforced with an additional stringer set in along side. Rail is poor and one-half of the south rail has been broken off.

FEDERAL AID SECONDARY ROUTE 433

Field Maintenance Division No. 301

Br. No. 433-25-0005 Prickley Pear Creek

Paint Condition: Good

Lewis and Clark County

31.5' Concrete Slab

General Condition: Good

Br. No. 433-25-0018 Helena Valley Canal

Paint Condition: Good

42.3' Concrete and Timber

General Condition: Good

FEDERAL AID SECONDARY ROUTE 434

Field Maintenance Division No. 301

Br. No. 434-25-0187 Middle Fork Dearborn River

Paint Condition: Poor

Lewis and Clark County

87' Steel Howe Truss

General Condition: Fair

Remarks: Bridge Posted on north side only: "Load Limit 8 Tons". Plank deck is loose, but seems to be in fair shape. Truss members are rusty and approach timber spans have timber posts and rails without paint. A detour roadway with a double 60" C.M.P. Culvert has been constructed to the west of the bridge.

Br. No. 434-25-0267 North Fork Dearborn River 231' Steel Pratt Truss
Paint Condition: Good General Condition: Fair
Remarks: Bridge posted both sides: "Load Limit 6 Tons; 10 m.p.h.". There was approximately 1' of snow on deck and the traffic lane two wheel ruts. Could not examine the deck. General appearance of struture, pins, bolts, etc., seem satisfactory for the load and speed posted. The steep down hill approach from the south under present snow condition is dangerous to traffic and bridge. At the southwest corner, at end of deck, the fill has sloughed out. The depression was snow filled except for a wheel track and some vehicle had been stuck there. At the northeast end metal post, the pipe rails have been pulled from their sockets.

Br. No. 434-25-0407 South Fork Sun River 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: No bridge signs.

Br. No. 434-25-0424 Smith Creek 75' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: No bridge signs.

FEDERAL AID SECONDARY ROUTE 435

No Bridges.

FEDERAL AID SECONDARY ROUTE 436

Field Maintenance Division No. 302 Blaine County
Br. No. 436-03-0006 Irrigation Canal 25' Treated Timber Trestle
Paint Condition: Good General Condition: Good

Br. No. 436-03-0013 Fifteen Mile Creek 75' Treated Timber Trestle
Paint Condition: Good General Condition: Good

FEDERAL AID SECONDARY ROUTE 437

No bridges.

FEDERAL AID SECONDARY ROUTE 438

Field Maintenance Division No. 402 Valley County
Br. No. 438-53-0003 Porcupine Creek 288' Treated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: Upstream pile Bent 6 is gone. Cap is now unsupported there. Many piles show wear from drift and ice.

Br. No. 438-53-0252 East Fork Porcupine Creek 78' Steel I Beam
Paint Condition: Poor General Condition: Good

Br. No. 438-53-0355 Drainage 23' Untreated Timber Trestle
Paint Condition: Poor General Condition: Good

FEDERAL AID SECONDARY ROUTE 440

Field Maintenance Division No. 201
Br. No. 440-47-0008 Drainage Silver Bow County
Paint Condition: None 26' Untreated Timber Trestle
General Condition: Poor
Remarks: Rail poor condition. East rail has been pushed out. North bent timber piles are being pushed in at bottom. Bridge has a load limit of 7 tons. Deck sand covered.

Br. No. 440-47-0014 Drainage 40' Treated Timber Trestle
Paint Condition: None General Condition: Fair
Remarks: A cribbing of railroad ties has been set in between Bents 2 and 3 and back filled. A crib of railroad ties has also been constructed between Bent 4 and 5 and back filled. Span 1 is also back filled. The bridge clear length for water way is now 9' 3". Section of deck now visible on the unerside looks good. Deck is sand covered. Rail is poor.

FEDERAL AID SECONDARY ROUTE 441

Field Maintenance Division No. 201
Br. No. 441-47-0022 Clark Fork Silver Bow County
General Condition: Good 32' Concrete T Beam
Remarks: Concrete of both end bents eroded at water line. Tested firm using a prospectors pick. South side deck edge has two re-bars exposed where surface has deteriorated. These bars were set too near the surface of the concrete when poured.

FEDERAL AID SECONDARY ROUTE 444

Field Maintenance Division No. 302
Br. No. 444-18-0035 Willow Creek Glacier County
Paint Condition: Good 50' Treated Timber Trestle
General Condition: Good
Br. No. 444-18-0037 Cut Bank Creek 100' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Br. No. 444-18-0057 Cobelle Creek 38' Treated Timber Trestle
Paint Condition: Good General Condition: Good
Remarks: Deck ballast worn off in spots and deck shows wear.

FEDERAL AID SECONDARY ROUTE 445

Field Maintenance Division 302
Br. No. 445-18-0091 Cut Bank Creek Glacier County
Paint Condition: Good 100' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 446

Field Maintenance Division No. 502
Br. No. 446-44-0004 Yellowstone River. Rosebud County
Paint Condition: Poor 867.1' Steel Thru Truss
General Condition: Fair
Remarks: At Pier 3 left, first steel span, the anchor bolt for truss is bent and bearing plate is offset 3" on rollers. Pier 3 spalling at top and cavities at low water line. Top of piers covered with dirt. All piers show cavities and deterioration at low water line.

Br. No. 446-44-0027	Irrigation Canal	38' Untreated Timber Trestle
Paint Condition: Poor		General Condition: Poor
Remarks: All lumber is old. Piles are rotten. Rails are gone.		

Br. No. 446-44-0069	Sand Creek	23.2' Steel I Beam
Paint Condition: Poor		General Condition: Fair
Remarks: Rail is torn off. Deck planks becoming worn. Structurally satisfactory.		

FEDERAL AID SECONDARY ROUTE 447

Field Maintenance Division No. 502		Rosebud County
Br. No. 447-44-0051	Rosebud Creek	75' Steel Pratt Truss
Paint Condition: Poor		General Condition: Fair
Remarks: Drift collected underneath. One upstream bracket bent from drift. No signs or reflectors. Cracked concrete at beam seats.		

Br. No. 447-44-0094	Drainage	58' Untreated Timber Trestle
Paint Condition: Poor		General Condition: Fair
Remarks: Rail broken. No signs or reflectors.		

Br. No. 447-44-0172	Drainage	96' Steel I Beam
Paint Condition: Poor		General Condition: Fair
Remarks: Structurally satisfactory yet. All concrete is aged and spalled to different degrees. Bent 4 has re-bars showing at low water line. No signs or reflectors.		

Br. No. 447-44-0224	Drainage	31' Steel I Beam
Paint Condition: Poor		General Condition: Poor
Remarks: Structurally fair. Bent rail. Spalled concrete end bents. No signs or reflectors.		

Br. No. 447-44-0427	Lay Creek	31' Steel I Beam
Paint Condition: Poor		General Condition: Fair
Remarks: Structurally satisfactory. Old appearance. No signs or reflectors. Rail broken and boarded up.		

FEDERAL AID SECONDARY ROUTE 448

Field Maintenance Division No. 302		Hill County
Br. No. 448-21-0021	Big Sandy Creek	75' Treated Timber Trestle
Paint Condition: Good		General Condition: Good

FEDERAL AID SECONDARY ROUTE 449

Field Maintenance Division No. 302		Hill County
Br. No. 449-21-0002	Sage Creek	80' Steel Truss
Paint Condition: Fair		General Condition: Fair

FEDERAL AID SECONDARY ROUTE 450

No bridges.

FEDERAL AID SECONDARY ROUTE 452

Field Maintenance Division No. 302 Hill County
Br. No. 452-21-0012 Bull Hook Creek Overflow 95.5' Steel Pony Truss
Paint Condition: Fair General Condition: Good
Remarks: Fill is settling away behind wing walls. One dangerous hole on east end. Untreated timber underneath shows ageing.

FEDERAL AID SECONDARY ROUTE 453

No bridges.

FEDERAL AID SECONDARY ROUTE 454

No bridges.

FEDERAL AID SECONDARY ROUTE 456

Field Maintenance Division No. 102 Flathead County
Br. No. 456-15-0007 Stillwater River 127' Untreated Timber Howe Truss
Paint Condition: None General Condition: Good
Remarks: Pole stringers and underside of deck look good. Some of the nose planks of Bent 3 are gone. Posted load limit 10 tons.

FEDERAL AID SECONDARY ROUTE 457

Field Maintenance Division No. 302 Liberty County
Br. No. 457-26-0075 Tiber Dam (Spillway) 109.5' Concrete T Beam
Paint Condition: Good General Condition: Good
Remarks: Bridge posted as follows: Load Limit 18 Tons. "Equipment with lugs must place suitable material on bridge deck to protect concrete surface."

FEDERAL AID SECONDARY ROUTE 458

Field Maintenance Division No. 202 Gallatin County
Br. No. 458-16-0073 Middle Creek 21' Untreated Timber Trestle
Paint Condition: None General Condition: Good
Remarks: Deck and stringer are in good condition. One section of 4"x6" timber curb about 15' in length on the north side of deck; none on south side.

FEDERAL AID SECONDARY ROUTE 459

No bridges.

FEDERAL AID SECONDARY ROUTE 460

Field Maintenance Division No. 101 Powell County
Br. No. 460-39-0001 I 90 - Gold Creek Interchange Underpass
Remarks: See FAP Route 2, Br. No. 139-0100-0055P.

Br. No. 460-39-0002 I 90 - Gold Creek Interchange Underpass
Remarks: See FAP Route 2, Br. No. 139-0100-0055

Br. No. 460-39-0003 Clark Fork 120' Steel Howe Truss
Paint Condition: Poor General Condition: Good
Remarks: Bridge posted: Limit 8 Tons. A break and settlement of a section
 of the south end bent, west side, has been repaired.

FEDERAL AID SECONDARY ROUTE 461

Field Maintenance Division No. 101 Sanders County
Br. No. 461-45-0129 Clark Fork Toll Ferry
Remarks: Ferry out of service December 1 to April 1. Last half mile of road
 to ferry crossing closed by snow.

Br. No. 461-45-0138 N. P. Railway Underpass
Paint Condition: Good General Condition: Good
Remarks: Paint good except for a strip of rust along the girder web just above
 the flange. Some on both girders.

FEDERAL AID SECONDARY ROUTE 462

Field Maintenance Division No. 401 Garfield County
Br. No. 462-17-0103 Frozen Dog Coulee 23' Untreated Timber Trestle
Paint Condition: Poor General Condition: Fair
Remarks: Stringers okay. Backing plank rotten. No rail.

Br. No. 462-17-0125 Drainage 23' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: Bridge is sliding on a skew with the roadway. Lumber is old. Bents
 are patched up. Some piling have rotted off and been patched. No rail.

Br. No. 462-17-0200 Little Dry Creek 224.5' Prestressed Concrete Beams
Paint Condition: Good General Condition: Good
Remarks: New 1960

FEDERAL AID SECONDARY ROUTE 463

Field Maintenance Division No. 501 Big Horn County
Br. No. 463-02-0411 Big Horn Canal 57' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: Rail gone on right side. Car recently went through it 12-12-61. No
 signs or reflectors. Piling badly weathered and checked.

FEDERAL AID SECONDARY ROUTE 464

Field Maintenance Division No. 302 Glacier County
Br. No. 464-18-0044 Cut Bank Creek 75' Steel I Beam
Paint Condition: Good General Condition: Good
Remarks: At south end of deck a 2'x3' section of the corrugated metal deck base
 is exposed.

Br. No. 464-18-0068 South Fork Greasewood Creek 23.3' Untreated Timber Trestle
Paint Condition: None General Condition: Poor
Remarks: Very poor deck.

Br. No. 464-18-0169	South Fork Milk River	27' Untreated Timber Trestle
Paint Condition: None		General Condition: Fair
Remarks: Another deck and set of stringers has been set on top of gravel surface of old deck. Newer deck looks good but has no gravel surfacing and deck is wearing. There is no curb or guard rail. At north end two 2" Ø sticks are set to show outside edges of deck. There are a few spiral turns of tape at the top of the markers.		

Br. No. 464-18-0171	Livermore Creek	22' Untreated Timber Trestle
Paint Condition: None		General Condition: Fair
Remarks: No rail and one half of curb timber on each side is gone. Four 2" Ø poles are set to mark bridge corners. Underside of bridge almost filled with snow; what could be seen appeared to be in fair condition. On the east side of deck two 2" plank have been set longitudinally, evidently covering hole in decking.		

Br. No. 464-18-0239	Dry Fork Milk River	27' Untreated Timber Trestle
Paint Condition: None		General Condition: Fair
Remarks: This bridge has two central steel stringers, the remainder are timber. Southeast rail section broken and there is a large hole in the northwest portion of the deck which has been partially covered with a section of 2" plank; the uncovered part of the opening is 6"x2'6". Deck is wearing where the gravel surfacing is gone.		

FEDERAL AID SECONDARY ROUTE 465

Field Maintenance Division No. 401		Garfield County
Br. No. 465-17-0007	Big Dry Creek	410.5' Prestressed Concrete Beams
Paint Condition: Good		General Condition: Good
Remarks: New 1959.		

Br. No. 465-17-0056	Drainage	39' Untreated Timber Trestle
Paint Condition: Poor		General Condition: Poor
Remarks: No rail. Lumber is old. Pilings show drift wear.		

FEDERAL AID SECONDARY ROUTE 466

Field Maintenance Division No. 403		Fergus County
Br. No. 466-14-0014	Harrison Creek (Hanson)	32' Treated Timber Trestle
Paint Condition: Poor		General Condition: Fair
Remarks: Most of the timber looks untreated. Drift collected at center bent. No signs or reflectors.		

FEDERAL AID SECONDARY ROUTE 467

Field Maintenance Division No. 401		McCone County
Br. No. 467-28-0005	Redwater River	193' Prestressed Concrete Beams
Remarks: Under contract - Let 12-20-61		

Br. No. 467-28-0010	Hell Creek	38' Treated Timber Trestle
Remarks: Under contract - Let 12-20-61		

Br. No. 467-28-0034	McCone Creek	38' Treated Timber Trestle
Remarks: Under contract - Let 12-20-61		

Br. No. 467-28-0048 Drainage 22' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: All lumber partly rotten. No rail or signs. Deck planks nearly worn through.

Br. No. 467-28-0080 Dry Ash Creek 45' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: This bridge is old, dilapidated and rotten. It has been patched up and many deck planks are loose. No signs or reflectors.

Br. No. 467-28-0082 Drainage 38' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: All piles and lumber underneath is old and rotten. No rail, signs or reflectors.

Br. No. 467-28-0121 Drainage 44' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: No curb or rail, signs or reflectors. Deck planks are loose and worn out. All lumber is old and rotten.

Field Maintenance Division No. 401 Dawson County
Br. No. 467-11-0335 Upper Seven Mile Creek 31' Untreated Timber Trestle
Paint Condition: Poor General Condition: Fair
Remarks: No Rail. Patched up underneath. 10 ton load limit. Lumber is old. Looks structurally satisfactory.

FEDERAL AID SECONDARY ROUTE 469

Field Maintenance Division No. 402 Roosevelt County
Br. No. 469-43-0019 Missouri River Steel Truss
Paint Condition: Good General Condition: Good

FEDERAL AID SECONDARY ROUTE 470

Field Maintenance Division No. 401 Dawson County
Br. No. 470-11-0130 North Fork Deer Creek 60' Untreated Timber Trestle
Paint Condition: Fair General Condition: Fair
Remarks: New planks on Bent 2 wing wall. The rest of the lumber looks quite old and some of the piles are rotting.

Br. No. 470-11-0235 Drainage 25' Treated Timber Trestle
Paint Condition: Poor General Condition: Fair
Remarks: No signs or railing. Stringers are both treated and untreated. Two holes through plank deck. Structurally looks okay.

FEDERAL AID SECONDARY ROUTE 471

Field Maintenance Division No. 101 Sanders County
Br. No. 471-45-0112 Prospect Creek 72' Untreated Timber Howe Truss
Remarks: A new bridge is being constructed to the right of the old truss bridge. The bridge is partially completed. There was 3'6" of snow on the deck. No fill at west end. Bridge not accessible for any measurements due to snow and water and ice in creek bed.

FEDERAL AID SECONDARY ROUTE 472

No bridges.

FEDERAL AID SECONDARY ROUTE 473

Field Maintenance Division No. 101	Ravalli County
Br. No. 473-41-0063	Trappers Creek
General Condition: Good	56' Continuous Concrete Girder

Br. No. 473-41-0143 West Fork Bitterroot River 170' Steel Pony Truss
Paint Condition: Good on Truss
Remarks: One length of pipe rail from right side of truss is gone. Paint on approach spans, timber rail, is poor. Truss span pipe top rail has a few rust spots.

FEDERAL AID SECONDARY ROUTE 474

Field Maintenance Division No. 101	Missoula County
Br. No. 474-32-0011	N. P. Railway
Paint Condition: Good	180' Steel Girder
	General Condition: Good

FEDERAL AID SECONDARY ROUTE 475

No bridges.

FEDERAL AID SECONDARY ROUTE 476

Field Maintenance Division No. 202	Park County
Br. No. 476-34-0008	Yellowstone River
Paint Condition: Good	360' Riveted Plate Girder
	General Condition: Good
Br. No. 476-34-0039	Mill Creek
Paint Condition: Good	33' Treated Timber Trestle
	General Condition: Good
Br. No. 476-34-0065	Mill Creek
Paint Condition: Good	43' Treated Timber Trestle
	General Condition: Good
Br. No. 476-34-0098	East Fork Mill Creek
Paint Condition: Good	25' Treated Timber Trestle
	General Condition: Good

FEDERAL AID SECONDARY ROUTE 477

No bridges.

FEDERAL AID SECONDARY ROUTE 478

Field Maintenance Division No. 202	Sweet Grass County
Br. No. 478-49-0008	Yellowstone River
	336' Steel Truss
Remarks: Bridge not posted. Lower part of sign at south end is broken off and the load limit is gone. The sign at the north end is old and the top half is gone. The following can be made out by close inspection: "For loads over 20,000 lbs.". The first line of the sign is gone. No surfacing on deck. Deck is intact and where stringer can be seen from banks, they are intact or have had an additional stringer set in.	

Br. No. 478-49-0075 Fletcher Creek 24' Untreated Timber King Truss
Paint Condition: None General Condition: Fair
Remarks: Deck and stringers intact. End bents have been reinforced with 4"x12"
timbers set in along side the piles.

Br. No. 478-49-0080 Sweet Grass Creek 50' Timber Queen Truss
Paint Condition: Poor General Condition: Poor
Remarks: Posted: Gross Limit 10 Tons. A reinforcing bent of piles and a 6"x12"
cap has been set in at each end bent. Deck and stringers are intact.

Br. No. 478-49-0113 Sweet Grass Creek 100' Untreated Timber & Steel
Paint Condition: Poor General Condition: Poor
Remarks: Posted: Gross Limit 10 Tons. Deck and stringers are intact. End bents
have been reinforced with additional cap and piles. Timber is old and
weathered.

Br. No. 478-49-0122 East Fork Sweet Grass Creek 30' Untreated Timber King Truss
Paint Condition: None General Condition: Fair
Remarks: Bridge posted: Gross Limit 15 Tons. Deck and stringers intact.

FEDERAL AID SECONDARY ROUTE 479

Field Maintenance Division No. 202 Sweet Grass County
Br. No. 479-49-0063 Ten Mile Creek 30' Untreated Timber King Truss
Paint Condition: None General Condition: Poor
Remarks: Bridge posted with old signs that require close inspection to read.
Gross Limit 15 Tons. Deck and stringers are intact.

Br. No. 479-49-0105 Otter Creek 27' Untreated Timber King Truss
Paint Condition: None General Condition: Poor
Remarks: South side piling checked sound at ground line. Deck intact. Bridge
posted with old signs that require close inspection; "Gross Limit 10 Tons".

Br. No. 479-49-0159 Sweet Grass Creek 93' Steel Truss
Paint Condition: Metal paint good. General Condition: Fair
Remarks: Wood rail painted in a few scattered places, otherwise, poor.

FEDERAL AID SECONDARY ROUTE 480

Field Maintenance Division No. 402 Roosevelt County
Br. No. 480-43-0030 Missouri River
Remarks: No bridge, no crossing.

Field Maintenance Division No. 402 Richland County
Br. No. 480-42-0138 Long Grass Creek 29' Steel I Beam
Paint Condition: Poor General Condition: Fair
Remarks: Structurally fair. Lumber is old. No rail. Upstream pile Bent 1 is
broken off. Wing walls are warping with fill pressure.

FEDERAL AID SECONDARY ROUTE 481

No bridges.

FEDERAL AID SECONDARY ROUTE 482

Field Maintenance Division No. 102
Br. No. 482-27-0026 Libby Creek
Remarks: Under contract - Let 11-29-61

Lincoln County
121.5' Prestressed Concrete Beams

FEDERAL AID SECONDARY ROUTE 483

Field Maintenance Division No. 302
Br. No. 483-18-0030 Rocky Coulee
Paint Condition: Steel-Fair; Rail-Good
Remarks: Timber rail paint good except on one northwest rail section, which is poor.

Glacier County
52' Steel I Beam
General Condition: Good

Br. No. 483-18-0278 South Fork Milk River
Paint Condition: Fair to Poor
Remarks: Ice breaker gone from center pier, also two stream face plank broken on the next bent south. Bridge posted with signs on the bridge end posts as follows: Load Limit 20 Tons - Speed Limit 15 m.p.h.. One piece of solid bridging ready to fall and several pieces gone.

150' Treated Timber Trestle
General Condition: Good

FEDERAL AID SECONDARY ROUTE 484

Field Maintenance Division No. 502
Br. No. 484-38-0006 East Fork Otter Creek
Paint Condition: Poor
Remarks: Rail very crooked. One broken stringer. All lumber old. No signs or reflectors.

Powder River County
49' Untreated Timber Trestle
General Condition: Poor

Br. No. 484-38-0020 Home Creek
Paint Condition: Poor
Remarks: No signs or reflectors. Lumber in end bents and deck is old. Holes broken through the deck.

29' Steel I Beam
General Condition: Poor

Br. No. 484-38-0038 Otter Creek
Paint Condition: Poor
Remarks: Holes broken through deck. Bent rail. No signs or reflectors. End bent spalled and re-steel hanging loose.

45' Steel Pony Truss
General Condition: Poor

Br. No. 484-38-0060 Drainage
Paint Condition: Poor
Remarks: Two broken stringers under joining each other. All lumber is old. No signs or reflectors.

30' Untreated Timber Trestle
General Condition: Poor

Br. No. 484-38-0246 Otter Creek
Paint Condition: Poor
Remarks: Deck plank loose. About 50 percent of rail is gone. All lumber is old. No reflectors.

90' Steel Truss
General Condition: Poor

Br. No. 484-38-0264 Otter Creek
Paint Condition: Poor
Remarks: No signs or reflectors. Drainage area underneath cluttered up with an old bridge. Trusswork patched.

45' Steel Pony Truss
General Condition: Poor

Br. No. 484-38-0268 Bear Creek
Paint Condition: Poor
Remarks: No signs or reflectors. Bottom chord patched together.

35' Steel Truss
General Condition: Fair

FEDERAL AID SECONDARY ROUTE 485

No bridges.

FEDERAL AID SECONDARY ROUTE 486

Field Maintenance Division No. 102	Flathead County
Br. No. 486-15-0043 Crystal Creek	22' Untreated Pole Trestle
Paint Condition: None	General Condition: Good
 Br. No. 486-15-0068 Crystal Creek	 22' Untreated Pole Trestle
Paint Condition: None	General Condition: Good
 Br. No. 486-15-0208 Big Creek	 95' Steel Pony Truss
Paint Condition: Fair-Steel; Poor or none-Wood	General Condition: Good
Remarks: Four timber rail sections have been replaced with new unpainted rails. Inspected backwall at expansion end of truss. No indication of any damage due to expansion on account of previously reported lack of ample space for expansion.	
 Br. No. 486-15-0291 Coal Creek	 60' Steel Pony Truss
Paint Condition: Fair-Metal; Poor-Wood Rail	General Condition: Good
Remarks: Upstream bottom chord, outside angle twisted and one set of x-bracing underneath is bent. At the northwest fixed shoe(upstream), the concrete at the bearing plate has spalled off under the plate and a portion of the anchor bolt is exposed. Approximately 25% of the plate is unsupported.	
 Br. No. 486-15-0338 Moran Creek	 30' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good
 Br. No. 486-15-0354 Hay Creek	 45' Steel I Beam
Paint Condition: Poor	General Condition: Good
Remarks: Lack of adequate space for expansion. Bent 1 backwall has a heavy crack on the west side. At Bent 2, concrete has spalled off for a depth of 2" under one girder, and at the center of the bent face concrete has cracked and approximately two square feet is ready to spall off. Four rail posts have been replaced with new unpainted posts.	
 Br. No. 486-15-0410 Red Meadow Creek	 43' Steel Girder
Paint Condition: Poor	General Condition: Good
 Br. No. 486-15-0447 Drainage	 27' Untreated Pole Trestle
Paint Condition: None	General Condition: Good
 Br. No. 486-15-0448 Whale Creek	 75' Steel Pony Truss
Paint Condition: Metal-Good; Wood-Poor	General Condition: Good
Remarks: Left bottom chord slightly bent. One timber rail section broken out. On the west lower chord of the truss and on parts of the truss lattice, the aluminum paint is worn off, exposing the prime coat.	
 Br. No. 486-15-0506 Trail Creek	 39' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good
 Br. No. 486-15-0574 Colts Creek	 22' Treated Timber Trestle
Paint Condition: Poor	General Condition: Good

FEDERAL AID SECONDARY ROUTE 487

Field Maintenance Division No. 102	Flathead County
Br. No. 487-15-0002	G. N. Railway
Paint Condition: Good	632.6' Steel Warren Truss
Remarks: Advance warning signs: "No heavy traffic allowed". Rail and end posts are deteriorating, and there is some chipping of slab at joints. Two sidewalk side plates at expansion joints are gone. Light vertical cracks in two central piers. Underside of deck looks good.	General Condition: Good

FEDERAL AID SECONDARY ROUTE 488

No bridges.

FEDERAL AID SECONDARY ROUTE 489

Field Maintenance Division No. 502	Custer County
Br. No. 489-09-0037	Sunday Creek
Paint Condition: Good	198' Prestressed Concrete Beams
Remarks: New 1961.	General Condition: Good

Br. No. 489-09-0137	Sand Creek	40' Steel I Beam
Paint Condition: Poor		General Condition: Fair
Remarks: Structurally looks okay. Concrete and lumber looks fairly old.		

Br. No. 489-09-0177	Muster Creek	122' Steel I Beam
Paint Condition: Poor		General Condition: Poor
Remarks: Rail battered up, patched and crooked. One timber stringer broken. All lumber is old and some deteriorated piles. Didn't look good underneath. Banks are eroding away. 10 Ton limit posted.		

FEDERAL AID SECONDARY ROUTE 490

Field Maintenance Division No. 101	Ravalli County
Br. No. 490-41-0002	East Fork Bitterroot River
Remarks: Under contract - Let 4-19-61	198' Prestressed Concrete Beam

Br. No. 490-41-0007	West Fork Bitterroot River	173' Prestressed Concrete Beam
Remarks: Under contract - Let 4-19-61		

FEDERAL AID SECONDARY ROUTE 492

No bridges.

FEDERAL AID SECONDARY ROUTE 493

No bridges.

FEDERAL AID SECONDARY ROUTE 494

Field Maintenance Division No. 502	Fallon County
Br. No. 494-13-0005	North Fork Sandstone Creek
Paint Condition: Poor	95' Steel Pratt Truss
Remarks: Old patched up condition. Footings are exposed. Concrete scoured at drift line. Rail bent. No signs or reflectors.	General Condition: Poor

Br. No. 494-13-0010 South Fork Sandstone Creek 38' Steel Warren Truss
Paint Condition: Poor General Condition: Poor
Remarks: Bent rails. Old looking. Walls at ends have warped with fill pressure.
Structurally satisfactory.

FEDERAL AID SECONDARY ROUTE 495

Field Maintenance Division No. 301 Cascade County
Br. No. 495-07-0040 G. N. Railway Underpass
Paint Condition: Good General Condition: Good
Remarks: East span of rail road bridge (underpass) Clearance heights need to
be repainted.

Br. No. 495-07-0048 Auxiliary Spillway Rainbow Dam 45' Untreated Timber Trestle
Paint Condition: Rail only painted-Good General Condition: Fair
Remarks: One rail post on north side split. Rail has been reset and painted since
last report. Plank deck checked and nails are working loose. Some
planking loose under traffic, otherwise, deck in fair shape. No surfacing
cover on this deck.

Br. No. 495-07-0049 Drainage 108' Untreated Timber Trestle
Paint Condition: Good (Rail only painted) General Condition: Fair
Remarks: Deck planking checked, but in fair condition, except for two plank;
one with transverse open strip break in each traffic lane and one near
east end with break in north lane. Planking loose under traffic due to
nails working loose. Many nails protruding above deck. Most of them
within two to three feet of the rails. No surfacing cover on bridge
deck.

FEDERAL AID SECONDARY ROUTE 496

Field Maintenance Division No. 402 Roosevelt County
Br. No. 496-43-0103 West Fork Shotgun Creek 26.5' Steel I Beam
Paint Condition: Poor General Condition: Poor
Remarks: Very old and dilapidated looking. Wheel guards are knocked off. All
lumber is weathering and rotting. Looks structurally satisfactory yet.

Br. No. 496-43-0122 East Fork Shotgun Creek 21' Steel I Beam
Paint Condition: Poor General Condition: Poor
Remarks: Makeshift and patched up construction. Dirt fills are pushing piles
off the cap on one end. No wheel guards, signs, reflectors or rail.

Br. No. 496-43-0140 Drainage 36.5' Untreated Timber Trestle
Paint Condition: Poor General Condition: Fair
Remarks: Seems to be structurally all right. It is a patched up and make-shift
construction. Fairly old and dilapidated looking. No signs or reflectors. Wheel
guards crooked and broken.

Br. No. 496-43-0159 Irrigation Ditch 60' Untreated Timber Trestle
Paint Condition: Poor General Condition: Fair
Remarks: Part of a wheel guard rail is gone. Two cracked stringers. Upstream
piles are scored from drift. Fairly old looking. No signs or reflectors.

FEDERAL AID SECONDARY ROUTE 497

No bridges.

FEDERAL AID SECONDARY ROUTE 498

Field Maintenance Division No. 301	Cascade County
Br. No. 498-07-0001	G. W. Railway
Paint Condition: Poor	100' Steel Girder
	General Condition: Good
Remarks: Curb ends are broken and reinforcing steel is exposed. Tops of west bent wing walls cracked off. No number on the bridge.	

FEDERAL AID SECONDARY ROUTE 499

Field Maintenance Division No. 202	Gallatin County
Br. No. 499-16-0077	Beaver Creek
	98.8' Concrete Girder
Remarks: Not inspected - road closed due to snow.	

Br. No. 499-16-0091	Cabin Creek	82' Concrete T Beam
Remarks: Not inspected - road closed due to snow.		

Br. No. 499-16-0208	Grayling Creek	73.7' Concrete Girder
Remarks: Not inspected. Road closed due to snow.		

FEDERAL AID SECONDARY ROUTE 500

Field Maintenance Division No. 403	Petroleum County
Br. No. 500-35-0123	Drainage
Paint Condition: Poor	28' Untreated Timber Trestle
	General Condition: Poor
Remarks: One broken stringer. Lumber old. No rail.	

Br. No. 500-35-0188	North Fork Willow Creek	Concrete Ford
Paint Condition: None needed.		General Condition: Fair

Br. No. 500-35-0297	Flatwillow Creek	131.5' Prestressed Concrete Beams
Remarks: Under contract - Let 9-27-61		

FEDERAL AID SECONDARY ROUTE 501

Field Maintenance Division No. 101	Ravalli County
Br. No. 501-41-0025	Bitterroot Irrigation Canal
Paint Condition: Poor	30' Concrete Slab (Skewed)
	General Condition: Good

FEDERAL AID SECONDARY ROUTE 502

Field Maintenance Division No. 501	Yellowstone County
Br. No. 502-56-0001	Interstate 90
Underpass	
Remarks: See FAP Route 2, Br. No. 156-0100-0117	

Br. No. 502-56-0002	Interstate 90	Underpass
Remarks: See FAP Route 2, Br. No. 156-0100-0117P		

Br. No. 502-56-0004	B.B.W.A. Canal	24' Steel I Beam
Paint Condition: Poor		General Condition: Good
Remarks: No signs or reflectors. Dangerously narrow. Slight spalling of concrete curbs.		

Br. No. 502-56-0005	B.B.W.A. Canal	32' Steel I Beam
Paint Condition: Good		General Condition: Good
Remarks: Widened recently. Old wall footings are exposed. Rail has been hit and bent slightly.		

Br. No. 502-56-0023 Canyon Creek 39' Steel Pony Truss
Remarks: The county is in the process of removing this bridge. 1-5-62

FEDERAL AID SECONDARY ROUTE 503

No bridges.

FEDERAL AID SECONDARY ROUTE 504

Field Maintenance Division No. 401 Prairie County
Br. No. 504-40-0051 Drainage 24' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: One rail is gone. Truss is gone and stringers are supported with post uprights.

Br. No. 504-40-0130 Cabin Creek 68' Steel I Beam
Paint Condition: Poor General Condition: Poor
Remarks: Spalled concrete around piers. Part of left curb and rail gone.
All lumber is old and warped.

FEDERAL AID SECONDARY ROUTE 505

Field Maintenance Division No. 403 Fergus County
Br. No. 505-14-0012 Burnett Creek 27' Concrete Slab
Paint Condition: None needed General Condition: Good
Remarks: Extensive honeycomb concrete bottom of slab.

Br. No. 505-14-0021 Drainage 27' Untreated Timber Trestle
Paint Condition: Poor General Condition: Fair

Br. No. 505-14-0068 Big Spring Creek 90' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: One broken stringer in first span. Could not get under other spans.

Br. No. 505-14-0069 Cottonwood Creek 67' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: One broken stringer and two cracked ones in first span.

Br. No. 505-14-0123 Judith River 75' Steel Pony Truss
Remarks: Road snowed in. Not inspected 1-24-61.

FEDERAL AID SECONDARY ROUTE 506

Field Maintenance Division No. 101 Lincoln County
Br. No. 506-27-0034 Pipe Creek 64' Untreated Timber Trestle
Paint Condition: Fair General Condition: Fair
Remarks: Northeast end post and one panel length of rail gone. No curbs.

FEDERAL AID SECONDARY ROUTE 507

Field Maintenance Division No. 101 Mineral County
Br. No. 507-32-0088 Petty Creek 30' Treated Timber Trestle
Paint Condition: Good General Condition: Good

FEDERAL AID SECONDARY ROUTE 508

Field Maintenance Division No. 101
Br. No. 508-27-0022 Pine Creek
Paint Condition: Good

Lincoln County
42' Treated Timber Trestle Askew
General Condition: Excellent

Br. No. 508-27-0121 Fourth of July Creek
Paint Condition: Good

22' Treated Timber Trestle
General Condition: Excellent

Br. No. 508-27-0188 Meadow Creek
General Condition: Excellent

36' Treated Timber Trestle

Br. No. 508-27-0191 Hell Roaring Creek
General Condition: Excellent

35' Treated Timber Trestle Askew

Br. No. 508-27-0237 Spread Creek
Paint Condition: Good

111' Steel I Beam
General Condition: Excellent

Br. No. 508-27-0282 Pete Creek
General Condition: Excellent

34' Treated Timber Trestle

Br. No. 508-27-0383 Yaak River
Remarks: Not inspected. Road closed from north end of route. One lane road beyond 37 miles in from south end of route. Impassable due to snow and icy condition of road.

112' Warren Steel Truss

Br. No. 508-27-0426 East Fork Yaak River
Remarks: Not inspected. Road closed from north end of route. Road impassable beyond 37 miles in from south end of route, due to snow and ice on a one-lane road.

34' Steel I Beam

Br. No. 508-27-0484 Caribou Creek
Remarks: Not inspected. Could not reach this bridge from north end of route. Advised not to go beyond Dodge Creek. From south end of route 37 miles in was the limit due to snow and ice on a one-way road.

22' Treated Timber Trestle

Br. No. 508-27-0634 Dodge Creek
Paint Condition: None

22' Treated Timber Trestle
General Condition: Excellent

Br. No. 508-27-0689 Sullivan Creek
General Condition: Excellent

24' Treated Timber Trestle

FEDERAL AID SECONDARY ROUTE 509

Field Maintenance Division No. 201
Br. No. 509-01-0001 I 15 - Monida Interchange
Paint Condition: Good
Remarks: FAP Route 3, Br. No. 101-0910-0005

Beaverhead County
Underpass
General Condition: Good

FEDERAL AID SECONDARY ROUTE 510

Field Maintenance Division No. 401
Br. No. 510-28-0005 Ash Creek
Paint Condition: Poor
Remarks: All lumber is old and rotten. No rail, signs or reflectors.

McCone County
38' Untreated Timber Trestle
General Condition: Poor

Br. No. 510-28-0050 Tuster Creek 119' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: No rail; all lumber old and rotting. No signs or reflectors. Parts of
the curb are gone.

Br. No. 510-28-0078 Drainage 34' Untreated Timber Trestle
Paint Condition: Poor General Condition: Poor
Remarks: Lumber is old and rotting. One split in piling at Bent 3. No rail,
signs, or reflectors.

FEDERAL AID SECONDARY ROUTE 515

Field Maintenance Division No. 402 Sheridan County
Br. No. 515-46-0090 Lake Creek 29' Steel I Beam
Remarks: Not inspected, route approved 12-15-61.

FEDERAL AID SECONDARY ROUTE 516

No bridges.

FEDERAL AID SECONDARY ROUTE 517

Field Maintenance Division No. 402 Sheridan County
Br. No. 517-46-0044 Antelope Creek 30' Steel I Beam
Remarks: Not inspected, route approved 12-15-61.

FEDERAL AID SECONDARY ROUTE 518

Field Maintenance Division No. 301 Jefferson County
Br. No. 518-22-0015 Prickly Pear Creek
Remarks: No structure.

